

# CATÁLOGO BUJÍAS

2026

# GONHER®

AUTOPARTES



PLATINO | COBRE

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

### ACURA

<b>MDX</b>				
2020 -14	V6-3.5L		GPL-9407	0.044"
2006 -05	V6-3.5L	GCO-UXF79 <sup>(3)</sup> , GCO-RC12MC4		0.044"

<b>RL</b>				
2011 -09	V6-3.7L	GCO-UXF79 <sup>(3)</sup>		

<b>TLX</b>				
2020 -15	V6-3.5L		GPL-9407	0.044"

### ALFA ROMEO

<b>166</b>				
2003 -02	V6-3.0L		GPL-3071	0.045"

<b>GT</b>				
2008 -07	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		

<b>GTV</b>				
2003	V6-3.0L		GPL-3071	0.045"

<b>SPIDER</b>				
2003	V6-3.0L		GPL-3071	0.045"

### AUDI

<b>A1</b>				
2011	L4-1.4L Turbo		GPL-3071	0.035"

<b>A3</b>				
2008	L4-1.4L Turbo	GCO-RC9YC		0.028"
2004	L4-1.8L Turbo	GCO-REC10YC4		0.032"
2004	L4-2.0L	GCO-RC9YC		0.032"
2004	L4-2.0L	GCO-REC10YC4		0.032"
2003 -98	L4-1.8L Turbo	GCO-RC12MC4		0.04"

<b>A3 QUATTRO</b>				
2004	L4-2.0L Turbo	GCO-RC9YC		0.032"

<b>A4</b>				
2006 -02	L4-1.8L Turbo	GCO-RC12MC4		0.04"
2006	L4-2.0L Turbo	GCO-RC9YC		0.032"
2001 -98	L4-1.8L Turbo	GCO-RC8VTC4 <sup>(2)</sup>		0.04"
1997	V6-2.8L	GCO-RC8VTC4 <sup>(2)</sup>		0.04"

<b>A4 QUATTRO</b>				
2005	V6-3.2L	GCO-RC9YC		

<b>A5</b>				
2011	L4-2.0L Turbo	GCO-RC9YC		0.032"

<b>A5 QUATTRO</b>				
2011	L4-2.0L Turbo	GCO-RC9YC		0.032"

<b>A6</b>				
2001 -98	V6-2.8L	GCO-RC12MC4		0.04"

<b>A6 QUATTRO</b>				
2002	V6-3.0L	GCO-RC12YC		0.032"

<b>A7 QUATTRO</b>				
2012	V6-3.0L	GCO-RC12YC		0.032"

<b>A8</b>				
2000	V8-3.7L	GCO-UXF79 <sup>(3)</sup>		

<b>A8 QUATTRO</b>				
2013	V6-3.0L	GCO-RC12YC		0.032"
1997	V8-4.2L	GCO-RC12YC		0.032"




<b>ALLROAD QUATTRO</b>				
2004 -01	V6-2.7L Turbo	GCO-UXF79 <sup>(3)</sup>		

<b>CABRIOLET</b>				
1998 -97	V6-2.8L	GCO-RC8VTC4 <sup>(2)</sup>		

<b>Q3</b>				
2013	L4-2.0L Turbo	GCO-RC9YC		0.032"

<b>Q3 QUATTRO</b>				
2017	L4-2.0L Turbo	GCO-RC9YC		0.032"

<b>Q5</b>				
2010	L4-2.0L Turbo	GCO-RC9YC		0.032"

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

### AUDI (Continúa)

<b>Q7</b>				
2018 -17	V6-3.0L	GCO-UXF79 <sup>(3)</sup>		
2015 -12	V6-3.0L	GCO-UXF79 <sup>(3)</sup>		
2009 -07	V8-4.2L		GPL-3071	0.045"
2007	V6-3.6L	GCO-RC12MC4		0.04"

<b>S3</b>				
2004 -00	L4-1.8L Turbo		GPL-3071	0.045"

<b>S4</b>				
2016 -12	V6-3.0L	GCO-UXF79 <sup>(3)</sup>		
2010	V6-3.0L	GCO-RC12YC		
2008 -04	V8-4.2L		GPL-3071	0.065"
2000	V6-2.7L Turbo		GPL-3071	0.045"

<b>S5</b>				
2009 -08	V8-4.2L		GPL-3071	0.045"

<b>S6</b>				
2009 -07	V10 5.2L		GPL-3071	0.045"
2004 -01	V8-4.2L	GCO-UXF79 <sup>(3)</sup>		

<b>S8</b>				
2009 -07	V10 5.2L		GPL-3071	0.045"
2002 -01	V8-4.2L	GCO-UXF79 <sup>(3)</sup>		

<b>SQ5</b>				
2014	V6-3.0L	GCO-RC12YC		0.032"

<b>TT</b>				
2009 -07	L4-2.0L Turbo		GPL-3071	0.045"
2006 -99	L4-1.8L Turbo		GPL-3071	0.045"

### BAIC

<b>BJ40</b>				
2022	L4-2.3L Turbo	GCO-RC10YC4		0.032"
2018	L4-2.3L Turbo	GCO-RC10YC4		0.032"

<b>D20</b>				
2020	L4-1.5L	GCO-RN12YC		
2018 -17	L4-1.5L	GCO-RN12YC		

<b>X25</b>				
2020 -17	L4-1.5L	GCO-RN12YC		

<b>X65</b>				
2020 -18	L4-2.0L Turbo	GCO-RC10YC4		0.032"

### BENTLEY

<b>CONTINENTAL</b>				
2007	W12 6.0L Turbo	GCO-RC9YC		0.032"

### BMW

<b>125i</b>				
2012 -08	L6-3.0L	GCO-REC10YC4		0.044"

<b>760Li</b>				
2006	V12 6.0L		GPL-3071	

<b>X3</b>				
2012 -11	L6-3.0L Turbo	GCO-UXF79 <sup>(3)</sup>		
2012 -04	L6-3.0L	GCO-UXF79 <sup>(3)</sup>		
2007 -04	L6-2.5L	GCO-UXF79 <sup>(3)</sup>		




<b>X5</b>				
2011 -01	L6-3.0L	GCO-UXF79 <sup>(3)</sup>		
2011	L6-3.0L Turbo	GCO-UXF79 <sup>(3)</sup>		
2009 -05	V8-4.8L	GCO-RC12MC4		0.04"
2006 -02	V8-4.4L	GCO-UXF79 <sup>(3)</sup>		
2000	V8-4.4L	GCO-UXF79 <sup>(3)</sup>		




<b>X6</b>				
2010 -09	L6-3.0L	GCO-UXF79 <sup>(3)</sup>		
2010 -09	V8-4.4L Turbo	GCO-UXF79 <sup>(3)</sup>		
2009	L6-3.0L Turbo	GCO-UXF79 <sup>(3)</sup>		

<b>Z4</b>				
2011	L6-3.0L	GCO-REC10YC4		0.020"
2010 -07	L6-2.5L	GCO-REC10YC4		0.044"
2009 -07	L6-3.0L	GCO-REC10YC4		0.044"

(2) 3 Electrodo, (3) 4 Electrodo




Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER.</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>BMW (Continúa)</b>				
<b>Z4 (Continúa)</b>				
2005 -03	L6-2.5L	GCO-UXF79 <sup>(3)</sup>		
<b>Z8</b>				
2003 -01	V8-4.9L	GCO-UXF79 <sup>(3)</sup>		
<b>BUICK</b>				
<b>CENTURY</b>				
2005 -89	V6-3.1L	GCO-RES9YCC4		0.06"
1988 -84	V6-2.8L	GCO-BL15Y		0.044"
<b>ENCLAVE</b>				
2016 -10	V6-3.6L		GPL-7437	0.044"
<b>LACROSSE</b>				
2013 -10	V6-3.6L		GPL-7437	0.044"
<b>LESABRE</b>				
2000 -97	V6-3.8L		GPL-3013	0.060"
1995 -93	V6-3.8L		GPL-3013	0.060"
<b>PARK AVENUE</b>				
1996 -93	V6-3.8L		GPL-3013	0.060"
<b>REGAL</b>				
2004 -93	V6-3.8L	GCO-RES9YCC4		0.06"
<b>RENDEZVOUS</b>				
2007 -06	V6-3.5L		GPL-3013	0.060"
<b>ROADMASTER</b>				
1996 -94	V8-5.7L		GPL-3013	0.060"
<b>SKYLARK</b>				
1998 -96	V6-3.1L		GPL-3013	0.060"
1997 -96	L4-2.4L		GPL-3013	0.060"
1995	L4-2.3L		GPL-3013	0.060"
1993	V6-3.3L		GPL-3013	0.060"
<b>TERRAZA</b>				
2005	V6-3.5L		GPL-3013	0.060"
<b>CADILLAC</b>				
<b>ALLANTE</b>				
1993	V8-4.6L		GPL-3013	0.060"
<b>ATS</b>				
2013	L4-2.0L Turbo		GPL-7437	0.044"
<b>CATERA</b>				
2001 -99	V6-3.0L	GCO-UXF79 <sup>(3)</sup> , GCO-RC12YC	GPL-3071	0.040"
1998 -97	V6-3.0L	GCO-UXF79 <sup>(3)</sup>		
<b>CTS</b>				
2011 -10	V6-3.6L	GCO-UXF79 <sup>(3)</sup>		
2009 -08	V6-3.6L	GCO-RC9BMC		0.044"
2007 -04	V6-3.6L	GCO-UXF79 <sup>(3)</sup>		
2004 -03	V6-3.2L	GCO-RC9BMC		0.044"
<b>DEVILLE</b>				
2005	V8-4.6L	GCO-RES9YCC4		0.052"
2004 -02	V8-4.6L	GCO-RS9YCC		0.052"
2001 -97	V8-4.6L		GPL-3013	0.05"
1996	V8-4.6L	GCO-RS9YCC		
1995 -94	V8-4.6L	GCO-RES9YCC4		0.052"
1995 -92	V8-4.9L	GCO-RS9YCC		
1991	V8-4.9L		GPL-3013	0.06"
<b>ELDORADO</b>				
2002 -93	V8-4.6L	GCO-RES9YCC4		0.052"
<b>ESCALADE</b>				
2009 -07	V8-6.2L		GPL-7437	0.052"
2009	V8-6.0L Híbrido		GPL-7437	0.052"
2006 -02	V8-6.0L		GPL-7437	0.052"
<b>FLEETWOOD</b>				
1996 -93	V8-5.7L		GPL-3013	0.050"

<b>GONHER.</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>CADILLAC (Continúa)</b>				
<b>SEVILLE</b>				
2004 -03	V8-4.6L	GCO-RS9YCC		0.052"
2002 -01	V8-4.6L	GCO-RES9YCC4		0.052"
2000	V8-4.6L		GPL-3013	0.05"
1999 -93	V8-4.6L	GCO-RES9YCC4		0.052"
<b>SRX</b>				
2007 -04	V8-4.6L		GPL-3013	0.04"
2006 -04	V6-3.6L		GPL-7437	0.052"
<b>STS</b>				
2009 -07	V6-3.6L		GPL-7437	0.052"
2009 -07	V8-4.6L		GPL-7437	0.052"
2006 -05	V8-4.6L		GPL-3013	0.05"
<b>XLR</b>				
2009	V8-4.6L		GPL-3013	0.04"
2007 -04	V8-4.6L		GPL-3013	0.04"
<b>CHEVROLET</b>				
<b>ASTRA</b>				
2008 -06	L4-1.8L	GCO-RC9BMC		0.044"
2008	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.035"
2008	L4-2.0L Turbo	GCO-UXF79 <sup>(3)</sup>		0.035"
2007 -06	L4-2.0L Turbo	GCO-RN9YC		0.04"
2006 -04	L4-2.0L	GCO-RN9YC		0.04"
2006 -04	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.035"
2003 -00	L4-1.8L	GCO-RC9BMC, GCO-RC10DMC <sup>(1)</sup>		0.044", 0.036"
<b>AVALANCHE</b>				
2009 -07	V8-5.3L	GCO-RS9YCC		0.06"
<b>AVEO</b>				
2017 -13	L4-1.6L	GCO-RC8YC4 <sup>(1)</sup>		0.044"
2012	L4-1.6L	GCO-RC8YC4 <sup>(1)</sup> , GCO-UXF79 <sup>(3)</sup>		0.044", 0.035"
2011 -09	L4-1.6L	GCO-UXF79 <sup>(3)</sup> , GCO-RC9MC4		0.035"
2008	L4-1.6L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4, GCO-RC8YC4 <sup>(1)</sup>		0.035", 0.044"
2007 -04	L4-1.6L	GCO-RC8YC4 <sup>(1)</sup>		0.044"
2004	L4-1.6L	GCO-RC8YC4 <sup>(1)</sup>		0.0442"
<b>BEAT</b>				
2021 -18	L4-1.2L	GCO-RA7YC		0.040"
<b>BLAZER</b>				
2005 -02	V6-4.3L	GCO-BL15Y		0.045"
2001 -98	V6-4.3L	GCO-RES9YCC4		0.06"
1997 -96	V6-4.3L		GPL-3013	0.06"
1995	V6-4.3L	GCO-BL15Y		0.045"
<b>C10</b>				
1981 -80	L6-4.1L	GCO-N14Y		
1981 -80	L6-4.8L	GCO-N14Y		
1981 -80	V8-5.7L	GCO-N14Y		
<b>C20</b>				
1986	V8-5.7L	GCO-N14Y		
<b>C2500</b>				
2000 -96	V8-5.7L		GPL-3013	0.050"
<b>C2500 SUBURBAN</b>				
1999 -96	V8-5.7L		GPL-3013	0.060"
<b>C30</b>				
1982 -80	L6-4.1L	GCO-N14Y		
1982 -80	L6-4.8L	GCO-N14Y		
1982 -80	V8-5.7L	GCO-N14Y		
<b>CAMARO</b>				
2014 -10	V6-3.6L		GPL-7437	0.044"
2013	V8-6.2L	GCO-RS14LC		0.040"
2002 -96	V8-5.7L	GCO-RS9YCC		0.040"
2002 -95	V6-3.8L	GCO-RES9YCC4		0.06"
1995 -93	V8-5.7L		GPL-3013	0.060"

(1) Producto nuevo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

### CHEVROLET (Continúa)

#### CAPRICE

1996 -93	V8-5.7L	GCO-BL15Y		0.035"
1982 -79	V8-5.7L	GCO-BL15Y		0.035"

#### CAVALIER

2005	L4-2.2L	GCO-RES9YCC4		0.045"
2004 -03	L4-2.2L	GCO-RS9YCC		0.06"
2002 -99	L4-2.2L	GCO-RES9YCC4		0.045"
2002 -97	L4-2.4L	GCO-RES9YCC4		0.050"
2002	L4-2.2L	GCO-RS9YCC, GCO-RES9YCC4		0.06" 0.045"
1998	L4-2.2L	GCO-RS9YCC		0.050"
1997 -93	L4-2.2L	GCO-RES9YCC4		0.045"
1996	L4-2.4L	GCO-RS9YCC		0.050"
1995	L4-2.4L	GCO-RES9YCC4		0.050"
1994 -91	V6-3.1L	GCO-RES9YCC4		0.045"
1994 -90	V6-2.8L	GCO-RES9YCC4		0.045"

#### CELEBRITY

1989 -87	V6-2.8L	GCO-RES9YCC4		0.044"
1986 -82	V6-2.8L	GCO-BL15Y		0.045"

#### CHEVY

2012 -96	L4-1.6L	GCO-RN9YC		0.04"
2002 -94	L4-1.4L	GCO-RN9YC		0.04"

#### CHEVY MONZA

2003	L4-1.6L	GCO-RN9YC		0.04"
------	---------	-----------	--	-------

#### CHEVY PICKUP

2003 -99	L4-1.6L	GCO-UX79 <sup>(3)</sup>		0.035"
----------	---------	-------------------------	--	--------

#### CHEYENNE

2021 -16	V8-5.3L		GPL-7437	0.044"
2021 -14	V8-6.2L		GPL-7437	0.044"
2015 -07	V8-5.3L	GCO-RS14YC <sup>(1)</sup>	GPL-7437	0.044"

#### CITATION

1986 -82	V6-2.8L	GCO-BL15Y		0.045"
----------	---------	-----------	--	--------

#### COLORADO

2009 -07	L5-3.7L		GPL-7437	0.06"
2006 -04	L5-3.5L		GPL-7437	0.06"

#### CORSA

2008 -03	L4-1.8L	GCO-RN9YC		0.04"
2002	L4-1.4L	GCO-RN9YC		0.035"

#### CORVETTE

2004	V8-5.7L	GCO-RS9YCC		0.06"
1996 -92	V8-5.7L		GPL-3013	0.06"

#### CRUZE

2011 -10	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.028"
----------	---------	--------------------------	--	--------

#### EQUINOX

2009 -05	V6-3.4L	GCO-RS9YCC, GCO-RS14YC6 <sup>(1)</sup>		0.06"
----------	---------	---	--	-------

#### EXPRESS CARGO

2021 -18	V6-4.3L		GPL-7437	0.044"
----------	---------	--	----------	--------

#### IMPALA

2005 -00	V6-3.8L	GCO-RS9YCC		0.06"
1996 -95	V8-5.7L	GCO-BL15Y		0.035"
1975	V8-5.7L	GCO-BL15Y		0.035"

#### K2500 SUBURBAN

1999 -96	V8-5.7L		GPL-3013	0.060"
----------	---------	--	----------	--------

#### LUMINA




1999 -98	V6-3.8L		GPL-3013	0.060"
----------	---------	--	----------	--------

#### LUMINA APV

1995	V6-3.8L		GPL-3013	0.060"
------	---------	--	----------	--------

#### LUV

2005 -98	L4-2.2L	GCO-BL15Y		0.044"
1997	L4-2.3L	GCO-N7BYC		0.044"

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

### CHEVROLET (Continúa)

#### MALIBU

2009 -08	L4-2.4L	GCO-RES9YCC4		0.06"
2009 -08	L4-2.4L Híbrido	GCO-RES9YCC4		0.06"
2009 -04	V6-3.5L	GCO-RS9YCC		0.06"
2008 -04	L4-2.2L	GCO-RS9YCC		0.06"
2003 -97	V6-3.1L	GCO-RES9YCC4		0.06"
1999 -97	L4-2.4L	GCO-RES9YCC4		0.06"
1981 -79	V8-5.7L	GCO-BL15Y		0.035"

#### MATIZ

2014 -13	L4-1.0L	GCO-UXF79 <sup>(3)</sup>		0.044"
2012	L4-1.0L	GCO-RN9YC, GCO-UXF79 <sup>(3)</sup>		0.044"
2011	L4-1.0L	GCO-UX79 <sup>(3)</sup>		0.044"

#### MERIVA

2007 -04	L4-1.8L	GCO-RN9YC		0.04"
----------	---------	-----------	--	-------

#### MONTE CARLO

2000 -98	V6-3.8L		GPL-3013	0.060"
1984 -81	V8-5.7L	GCO-BL15Y		0.060"

#### NOVA

1978 -77	V8-5.7L	GCO-BL15Y		0.035"
1978 -75	L6-4.1L	GCO-BL15Y		0.035"

#### OPTRA

2010 -08	L4-2.0L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10DMC <sup>(1)</sup>		0.044", 0.032"
2007 -06	L4-2.0L	GCO-RC9YC, GCO-RC10DMC <sup>(1)</sup>		0.035", 0.032"

#### S10

2003 -00	L4-2.2L	GCO-UXF79 <sup>(3)</sup>		0.040"
2002 -01	L4-2.2L	GCO-RES9YCC4, GCO-UXF79 <sup>(3)</sup>		0.06"
2000	L4-2.2L	GCO-RC9BMC, GCO-UXF79 <sup>(3)</sup>		0.04"
1999 -98	L4-2.2L	GCO-RC9BMC		0.04"
1997 -94	L4-2.2L	GCO-UXF79 <sup>(3)</sup>		0.040"
1993 -91	V6-3.1L	GCO-BL15Y		0.045"

#### SILVERADO 1500

2015 -14	V6-4.3L		GPL-3013	0.060"
2013 -03	V6-4.3L	GCO-RS14YC6 <sup>(1)</sup>	GPL-3013	0.060"
2002 -99	V6-4.3L	GCO-RS14YC6 <sup>(1)</sup>		0.060"

#### SILVERADO 1500 CLASSIC

2007	V6-4.3L		GPL-3013	0.060"
------	---------	--	----------	--------

#### SILVERADO 2500

2002 -00	V8-5.7L		GPL-3013	0.060"
----------	---------	--	----------	--------

#### SONIC

2013 -12	L4-1.6L	GCO-RC12MC4		0.035"
----------	---------	-------------	--	--------

#### SONORA

2006 -03	V8-5.3L	GCO-RS9YCC, GCO-RS14YC <sup>(1)</sup>		0.06"
2002 -00	V8-5.7L	GCO-RS9YCC		0.06"

#### SPARK

2018 -16	L4-1.4L	GCO-RA7YC		0.035"
2015 -12	L4-1.2L	GCO-UXF79 <sup>(3)</sup> , GCO-RA7YC		0.040", 0.035"
2011	L4-1.2L	GCO-RN9YC, GCO-UXF79 <sup>(3)</sup> , GCO-RA7YC		0.040", 0.035"

#### SPARK CLASSIC

2016	L4-1.2L	GCO-UXF79 <sup>(3)</sup> , GCO-RA7YC		0.040", 0.035"
------	---------	---	--	-------------------

#### SUBURBAN 1500




2006 -00	V8-5.3L	GCO-RS14YC6 <sup>(1)</sup>		0.06"
----------	---------	----------------------------	--	-------

#### TAHOE




2014 -00	V8-5.3L	GCO-RS9YCC, GCO-RS12YC <sup>(1)</sup>		0.06", 0.04"
2009 -00	V8-4.8L	GCO-RS12YC <sup>(1)</sup>		1.0 mm

(1) Producto nuevo, (3) 4 Electrodo




Verifique la calibración de las bujías antes de instalarlas.




<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
AÑO	MOTOR			
<b>CHEVROLET (Continúa)</b>				
<b>TORNADO</b>				
2009 -04	L4-1.8L	GCO-RN9YC		0.04"
<b>TRACKER</b>				
2007 -05	L4-2.0L	GCO-UX79 <sup>(3)</sup>		0.044"
2004 -99	L4-2.0L	GCO-RN9YC		0.044"
2000 -98	L4-1.6L	GCO-RN9YC		0.045"
<b>TRAILBLAZER</b>				
2009 -02	L6-4.2L	GCO-RS9YCC		0.044"
<b>TRAVERSE</b>				
2015 -09	V6-3.6L		GPL-7437	0.044"
<b>TRAX</b>				
2013	L4-1.8L	GCO-RC12MC4		0.035"
<b>UPLANDER</b>				
2009	V6-3.9L	GCO-RS14YC <sup>(1)</sup>		0.044"
2008 -07	V6-3.9L	GCO-RS14YC <sup>(1)</sup>	GPL-7437	0.044", 0.06"
2006 -05	V6-3.5L	GCO-RS14YC6 <sup>(1)</sup>	GPL-7437	0.06"
2006	V6-3.9L		GPL-7437	0.06"
<b>VECTRA</b>				
2005 -03	V6-3.2L	GCO-UXF79 <sup>(3)</sup>		0.035"
<b>VENTURE</b>				
2005 -97	V6-3.4L	GCO-RES9YCC4		0.06"
<b>ZAFIRA</b>				
2005	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.035"
2004 -02	L4-1.8L	GCO-RC9BMC		0.04"
<b>CHRYSLER</b>				
<b>200</b>				
2015	L4-2.4L	GCO-RC12MC4		0.044"
2014 -12	L4-2.4L	GCO-RC12MC4, GCO-RC12MCC4 <sup>(1)</sup>		0.044"
2013	V6-3.6L	GCO-RC12MC4, GCO-RC12MCC4 <sup>(1)</sup>		0.044"
2011	L4-2.4L	GCO-RC12MCC4 <sup>(1)</sup>		0.044"
<b>300</b>				
2021 -12	V6-3.6L		GPL-9407	0.044"
2009 -05	V8-5.7L	GCO-RE14MCC4		0.045"
<b>ASPEN</b>				
2009	V8-5.7L	GCO-RE14MCC4		0.05"
2008 -07	V8-5.7L	GCO-RE14MCC4		0.045"
<b>CIRRUS</b>				
2009	L4-2.4L		GPL-3071	0.05"
2007	L4-2.4L	GCO-RE14MCC4		0.05"
2006 -97	L4-2.4L Turbo	GCO-RE14MCC4		0.05"
2000 -96	V6-2.5L	GCO-RC10YC4		0.044"
2000	L4-2.4L	GCO-RE14MCC4		0.05"
1997	L4-2.4L	GCO-RE14MCC4		0.05"
1996 -95	L4-2.4L		GPL-3071	0.05"
<b>CONCORDE</b>				
2001	V6-3.2L	GCO-UXF79 <sup>(3)</sup>		
<b>CORDOBA</b>				
1982 -80	V8-5.9L	GCO-N12YC		0.035"
<b>CROSSFIRE</b>				
2005 -04	V6-3.2L	GCO-UXF79 <sup>(3)</sup>		
<b>GRAND VOYAGER</b>				
2002 -96	V6-3.8L	GCO-UXF79 <sup>(3)</sup>		0.050"
<b>IMPERIAL</b>				
1991	V6-3.3L	GCO-UX79 <sup>(3)</sup>		
<b>LEBARON</b>				
1995 -92	L4-2.5L Turbo	GCO-N12YC		0.035"
1993	L4-2.5L	GCO-N12YC		0.035"
1991	L4-2.5L Turbo	GCO-UX79 <sup>(3)</sup>		0.035"

(1) Producto nuevo, (3) 4 Electrodo

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
AÑO	MOTOR			
<b>CHRYSLER (Continúa)</b>				
<b>LEBARON (Continúa)</b>				
1987 -84	L4-2.2L Turbo	GCO-N12YC		0.035"
1987 -83	L4-2.2L	GCO-N12YC		0.035"
1982 -79	V8-5.9L	GCO-N12YC		0.035"
<b>NEW YORKER</b>				
1994 -92	V6-3.0L	GCO-N7BYC		0.044"
1993 -92	L4-2.5L Turbo	GCO-N12YC		0.035"
1989 -85	L4-2.2L Turbo	GCO-UX79 <sup>(3)</sup>		0.035"
1986 -85	L4-2.2L	GCO-UX79 <sup>(3)</sup>		0.035"
<b>PACIFICA</b>				
2020 -17	V6-3.6L		GPL-9407	0.044"
2020 -17	V6-3.6L Híbrido		GPL-9407	0.044"
2008	V6-4.0L	GCO-UXF79 <sup>(3)</sup>		0.050"
2007	V6-3.8L	GCO-RE14MCC4		0.05"
2006 -04	V6-3.5L	GCO-RC12MC4		0.05"
2005	V6-3.8L	GCO-RE14MCC4		0.05"
<b>PHANTOM</b>				
1993 -92	L4-2.2L Turbo	GCO-N12YC		0.035"
1990	L4-2.5L Turbo	GCO-UX79 <sup>(3)</sup>		0.035"
1989 -87	L4-2.2L Turbo	GCO-N12YC		0.035"
<b>PT CRUISER</b>				
2009 -01	L4-2.4L	GCO-RE14MCC4		0.05"
2008 -03	L4-2.4L Turbo	GCO-RE14MCC4		0.05"
<b>SEBRING</b>				
2000 -95	V6-2.5L	GCO-RC10YC4		0.044"
<b>TOWN &amp; COUNTRY</b>				
2014 -11	V6-3.6L		GPL-9407	0.044"
2007 -00	V6-3.8L	GCO-RE14MCC4		0.05"
1999 -96	V6-3.8L	GCO-UX79 <sup>(3)</sup>		0.050"
<b>VOYAGER</b>				
2008 -00	V6-3.3L	GCO-RE14MCC4		0.05"
<b>DODGE</b>				
<b>ATOS</b>				
2012 -10	L4-1.1L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4	GPL-3346 <sup>(1)</sup>	0.044"
2009 -05	L4-1.1L	GCO-RC12YC, GCO-RC10YC4	GPL-3346 <sup>(1)</sup>	0.04", 0.044"
2004 -01	L4-1.0L	GCO-RC12YC	GPL-3346 <sup>(1)</sup>	0.04", 0.044"
<b>ATTITUDE</b>				
2011	L4-1.4L	GCO-UXF79 <sup>(3)</sup>	GPL-3346 <sup>(1)</sup>	0.044"
2011	L4-1.6L	GCO-UXF79 <sup>(3)</sup>	GPL-3346 <sup>(1)</sup>	0.044"
2010	L4-1.4L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4	GPL-3346 <sup>(1)</sup>	0.044"
2010	L4-1.6L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4	GPL-3346 <sup>(1)</sup>	0.044"
2009 -06	L4-1.4L	GCO-RC12YC, GCO-RC10YC4	GPL-3346 <sup>(1)</sup>	0.045", 0.044"
2009 -06	L4-1.6L	GCO-RC12YC, GCO-RC10YC4	GPL-3346 <sup>(1)</sup>	0.045", 0.044"
<b>AVENGER</b>				
2014 -10	L4-2.4L	GCO-RC12MCC4 <sup>(1)</sup>	GPL-3318 <sup>(1)</sup>	0.044"
2010 -08	L4-2.0L		GPL-3318 <sup>(1)</sup>	0.044"
2009 -08	L4-2.4L	GCO-RE14MCC4, GCO-RC12MCC4 <sup>(1)</sup>	GPL-3318 <sup>(1)</sup>	0.05", 0.044"
<b>CALIBER</b>				
2009 -08	L4-2.4L Turbo	GCO-RE14MCC4		0.05"
2009 -07	L4-2.4L	GCO-RE14MCC4		0.05"
<b>CARAVAN</b>				
1997 -96	L4-2.4L		GPL-3071	0.050"
1993	L4-2.5L	GCO-RN12YC		0.035"




Verifique la calibración de las bujías antes de instalarlas.




<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>DODGE (Continúa)</b>				
<b>CHALLENGER</b>				
2021 -11	V6-3.6L		GPL-9407	0.044"
2009 -08	V8-6.1L	GCO-RE14MCC4		0.045"
2009	V8-5.7L	GCO-RE14MCC4		0.05"
<b>CHARGER</b>				
2020 -11	V6-3.6L		GPL-9407	0.044"
2009 -06	V8-6.1L	GCO-RE14MCC4		0.045"
2009	V8-5.7L	GCO-RE14MCC4		0.05"
2008 -06	V8-5.7L	GCO-RE14MCC4		0.045"
2008	V8-5.7L	GCO-REC10YC4		0.045"
<b>D150</b>				
1993 -91	V6-3.9L	GCO-RN12YC		0.035"
<b>D250</b>				
1993	V6-3.9L	GCO-RC12YC		0.035"
1992 -88	V8-5.9L	GCO-RN12YC		0.035"
<b>D300</b>				
1980 -76	V8-5.9L	GCO-RN12YC		0.035"
<b>D350</b>				
1992 -81	V8-5.9L	GCO-RN12YC		0.035"
<b>DAKOTA</b>				
2012 -04	V6-3.7L	GCO-RC9MC4		0.035"
2003 -97	V6-3.9L	GCO-RC12LC4 <sup>(1)</sup>		0.04"
2002 -93	L4-2.5L	GCO-RC12YC		0.035"
<b>DART</b>				
1989 -82	L4-2.2L	GCO-UXF79 <sup>(3)</sup>		0.044"
1982 -79	L6-3.7L	GCO-BL15Y		0.035"
1980	V8-5.2L	GCO-N12YC		0.035"
1978	L6-3.7L	GCO-UXF79 <sup>(3)</sup>		0.044"
1977 -76	L6-3.7L	GCO-N14Y		0.035"
1976	V8-5.9L	GCO-N12YC		0.035"
<b>DURANGO</b>				
2021 -11	V8-5.7L	GCO-REC12MCC4 <sup>(1)</sup>		0.044"
2015 -12	V6-3.6L		GPL-9407	0.044"
2009	V8-5.7L	GCO-RE14MCC4		0.05"
2009	V8-5.7L Híbrido	GCO-RE14MCC4		0.045"
2008 -04	V8-5.7L	GCO-RE14MCC4		0.045"
2003 -98	V8-5.9L	GCO-RC12MC4		0.04"
2000 -98	V8-5.2L	GCO-RC12MC4, GCO-RC12LC4 <sup>(1)</sup>		0.04"
<b>GRAND CARAVAN</b>				
2020 -11	V6-3.6L		GPL-9407	0.044"
<b>H100</b>				
2005 -03	L4-2.4L	GCO-RN9YC		0.04"
<b>I10</b>				
2014 -12	L4-1.1L		GPL-3071	0.044"
<b>JOURNEY</b>				
2020 -12	L4-2.4L	GCO-RC12MCC4 <sup>(1)</sup>		0.044"
2019 -11	V6-3.6L		GPL-9407	0.044"
2011	L4-2.4L	GCO-UXF79 <sup>(3)</sup> , GCO-RC12MCC4 <sup>(1)</sup>		0.035", 0.044"
2010	L4-2.4L	GCO-UXF79 <sup>(3)</sup> , GCO-RC12MCC4 <sup>(1)</sup> , GCO-RC12MC4		0.035", 0.044"
2009	L4-2.4L	GCO-RC9MC4, GCO-RC12MCC4 <sup>(1)</sup>		0.045", 0.044"
<b>MONACO</b>				
1977 -75	V8-5.2L	GCO-N12YC		0.035"
1970 -69	V8-5.2L	GCO-N12YC		0.035"

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>DODGE (Continúa)</b>				
<b>NEON</b>				
2005 -03	L4-2.4L Turbo	GCO-RE14MCC4		0.05"
2005 -95	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.035"
<b>NITRO</b>				
2012 -11	V6-3.7L	GCO-RC9MC4		0.035"
2010	V6-3.7L	GCO-UXF79 <sup>(3)</sup> , GCO-RC9MC4		0.044", 0.035"
2009 -07	V6-3.7L	GCO-RC9MC4		0.035"
<b>RAM 1500</b>				
2009 -03	V6-3.7L	GCO-RC9MC4		0.035"
2008 -07	V8-4.7L	GCO-UXF79 <sup>(3)</sup>		0.040"
2002 -97	V6-3.9L	GCO-UXF79 <sup>(3)</sup> , GCO-RC12LC4 <sup>(1)</sup>		0.035", 0.04"
2001 -97	V8-5.2L	GCO-UXF79 <sup>(3)</sup>		0.040"
1996 -94	V6-3.9L	GCO-RC12YC	GPL-3071	0.035"
1996 -94	V8-5.2L	GCO-RC12YC	GPL-3071	0.035"
1996 -94	V8-5.9L	GCO-RC12YC	GPL-3071	0.035"
<b>RAM 2500</b>				
2010 -09	V8-5.7L	GCO-REC12MCC4 <sup>(1)</sup>		0.044"
2009 -02	V8-4.7L	GCO-UXF79 <sup>(3)</sup>		0.040"
1997	V8-5.9L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>		0.035"
1996 -95	V8-5.9L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>	GPL-3071	0.035"
1996 -94	V10 8.0L	GCO-RC12YC		0.045"
1996 -94	V8-5.2L	GCO-RC12YC	GPL-3071	0.035"
1996 -94	V8-5.9L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>	GPL-3071	0.035"
<b>RAM 2500 VAN</b>				
1997 -96	V8-5.2L	GCO-RC12YC	GPL-3071	0.035"
<b>RAM 3500</b>				
2009	V8-5.7L	GCO-RE14MCC4		0.045"
2006 -03	V8-5.7L	GCO-RE14MCC4		0.045"
1997 -94	V8-5.9L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>	GPL-3071	0.035"
1997 -94	V8-5.9L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>	GPL-3071	0.035"
<b>RAM 3500 VAN</b>				
1997	V8-5.9L	GCO-RC12YC	GPL-3071	0.035"
<b>RAMCHARGER</b>				
1996 -94	V8-5.9L	GCO-RC12YC		0.040"
<b>ROYAL MONACO</b>				
1977	V8-5.9L	GCO-N12YC		0.040"
<b>SHADOW</b>				
1994 -93	L4-2.2L	GCO-RN12YC, GCO-UXF79 <sup>(3)</sup>		0.035"
1994 -93	L4-2.5L	GCO-RN12YC, GCO-UXF79 <sup>(3)</sup>		0.035"
<b>STRATUS</b>				
2006 -98	L4-2.4L Turbo	GCO-RC12YC		0.045"
2006 -95	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.035"
2006 -95	L4-2.4L	GCO-RC12YC		0.045"
<b>VAN 1000</b>				
2009 -08	L4-2.4L	GCO-RE14MCC4		0.05"
<b>VERNA</b>				
2006 -04	L4-1.5L	GCO-RC12YC, GCO-RC10YC4		0.045", 0.044"
2006 -04	L4-1.6L	GCO-RC12YC, GCO-RC10YC4		0.045", 0.044"
<b>VIPER</b>				
2006 -04	V10 8.3L	GCO-RC9MC4		0.045"
2000	V10 8.0L	GCO-RC12MC4		0.045"
<b>W250</b>				
1993	V8-5.9L	GCO-RN12YC		0.035"

(1) Producto nuevo, (3) 4 Electrodos




Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER.</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
AÑO	MOTOR			
<b>FAW</b>				
<b>F1</b>				
2008	L3-1.0L	GCO-UXF79 <sup>(3)</sup>		
<b>F4</b>				
2008	L4-1.4L	GCO-UXF79 <sup>(3)</sup>		
<b>FIAT</b>				
<b>500L</b>				
2019 -15	L4-1.4L Turbo	GCO-RA7YC		0.028"
<b>ALBEA</b>				
2009	L4-1.8L	GCO-RN9YC		0.04"
<b>IDEA</b>				
2009 -08	L4-1.8L	GCO-RN9YC		0.035"
<b>PALIO</b>				
2008 -06	L4-1.8L	GCO-RN9YC		0.035"
2005 -04	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.035"
<b>STILO</b>				
2007	L5-2.4L	GCO-RC9YC		0.035"
<b>STRADA</b>				
2008	L4-1.8L	GCO-RN9YC		0.032"
2007	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.032"
<b>FORD</b>				
<b>AEROSTAR</b>				
1997 -95	V6-3.0L		GPL-3013	0.054"
1997 -93	V6-4.0L		GPL-3013	0.044"
1995 -94	V6-4.0L		GPL-3013	0.054"
1993 -91	V6-3.0L		GPL-3013	0.054"
<b>CLUB WAGON</b>				
1998 -97	V8-5.4L	GCO-RS9YCC		0.054"
1996 -95	V8-5.8L	GCO-BL15Y		0.044"
<b>CONTOUR</b>				
2000 -95	L4-2.0L		GPL-7437	0.054"
2000 -95	V6-2.5L	GCO-RS9YCC		0.054"
<b>COURIER</b>				
2007 -01	L4-1.6L	GCO-RES9YCC4		0.05"
<b>CROWN VICTORIA</b>				
1995 -93	V8-4.6L		GPL-3013	0.054"
<b>E-150</b>				
2004	V8-4.6L	GCO-RS9YCC		0.054"
2003 -02	V6-4.2L	GCO-RS14LC		0.054"
<b>ECONOLINE</b>				
2004	V8-4.6L	GCO-RS9YCC		0.054"
<b>ECOSPORT</b>				
2011 -04	L4-2.0L	GCO-RS9YCC		0.05"
<b>EDGE</b>				
2009 -07	V6-3.5L	GCO-RS9YCC		0.054"
<b>ESCAPE</b>				
2019 -09	L4-2.5L		GPL-7437	0.052"
2009 -01	V6-3.0L	GCO-RS9YCC		0.054"
<b>ESCORT</b>				
2003 -97	L4-2.0L		GPL-7437	
1996 -93	L4-1.8L	GCO-RC12YC		0.05"
1996 -93	L4-1.9L	GCO-RS9YCC		0.054"
<b>EXCURSION</b>				
2005 -00	V10 6.8L	GCO-RS9YCC		0.054"
<b>EXPEDITION</b>				
2009 -97	V8-5.4L	GCO-RS9YCC		0.054"
2004	V8-4.6L	GCO-RS9YCC		0.054"
2003 -97	V8-4.6L		GPL-3013	0.054"
<b>EXPLORER</b>				
2009 -02	V8-4.6L	GCO-RS9YCC		0.054"
2009 -97	V6-4.0L	GCO-RS9YCC		0.054"
2009 -91	V6-4.0L		GPL-3013	0.054"
2001 -96	V8-5.0L	GCO-RS9YCC		0.054"

<b>GONHER.</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
AÑO	MOTOR			
<b>FORD (Continúa)</b>				
<b>F-100 RANGER</b>				
2001 -96	V6-3.0L	GCO-RS9YCC, GCO-RS12YC <sup>(1)</sup>		0.054", 0.044"
<b>F-150</b>				
2021 -18	V6-3.3L		GPL-7437	0.052"
2009 -98	V6-4.2L	GCO-RS14LC		0.054"
1997	V8-4.6L	GCO-RS9YCC		0.054"
<b>F-350</b>				
1993	V8-5.8L	GCO-F11Y		0.044"
1990 -89	V8-5.8L	GCO-F11Y		0.044"
<b>FIESTA</b>				
2001 -98	L4-1.3L	GCO-RS9YCC		0.04"
<b>FIVE HUNDRED</b>				
2007 -05	V6-3.0L	GCO-RS9YCC		0.054"
<b>FOCUS</b>				
2010	L4-2.0L	GCO-RS14LC		0.054"
2009 -06	L4-2.0L	GCO-RS9YCC		0.054"
2009 -00	L4-2.0L		GPL-7437	0.05"
2000	L4-2.0L	GCO-RS9YCC		0.05"
<b>FOCUS ST</b>				
2011 -07	L5-2.5L Turbo		GPL-REC8PYB <sup>(1)</sup>	0.032"
<b>FREESTAR</b>				
2007 -04	V6-4.2L	GCO-RS9YCC		0.054"
<b>FUSION</b>				
2020 -17	L4-2.0L Híbrido		GPL-7437	0.052"
2009 -07	L4-2.3L	GCO-RS9YCC		0.054"
2009 -06	V6-3.0L	GCO-RS9YCC		0.054"
<b>GHIA</b>				
1991	L4-2.3L		GPL-3013	0.054"
<b>GRAND MARQUIS</b>				
2004 -95	V8-4.6L		GPL-3013	0.054"
<b>IKON</b>				
2007 -03	L4-1.6L	GCO-RES9YCC4		0.054"
<b>KA</b>				
2008 -03	L4-1.6L	GCO-RES9YCC4		0.05"
<b>LOBO</b>				
2009 -04	V8-4.6L	GCO-RS9YCC		0.054"
2006 -04	V8-5.4L	GCO-RS9YCC		0.054"
1997	V8-4.6L	GCO-RS9YCC		0.054"
<b>MONDEO</b>				
2007 -02	V6-2.5L	GCO-RS9YCC		0.04"
2007	L4-2.0L		GPL-7437	0.054"
2006 -01	L4-2.0L	GCO-RS9YCC		0.04"
2001	V6-2.5L	GCO-RS9YCC		0.054"
<b>MUSTANG</b>				
2009 -05	V8-4.6L		GPL-3013	0.054"
2004 -03	V8-4.6L	GCO-RES9YCC4		0.054"
2004 -03	V8-4.6L	GCO-RES9YCC4	GPL-3013	0.054"
2002 -01	V8-4.6L		GPL-3013	0.054"
2000 -96	V8-4.6L	GCO-RES9YCC4		0.054"
1995 -94	V8-5.0L	GCO-BL15Y		0.054"
1984 -80	V8-5.0L		GPL-3013	0.044"
<b>P-350</b>				
1997 -92	V8-5.8L	GCO-BL15Y		0.044"
<b>RANGER</b>				
2012	L4-2.3L	GCO-RS12YC <sup>(1)</sup>		0.052"
2011 -10	L4-2.3L	GCO-RS9YCC, GCO-RS12YC <sup>(1)</sup>		0.054", 0.052"
2009	L4-2.3L	GCO-RES9YCC4, GCO-RS12YC <sup>(1)</sup> , GCO-RS9YCC		0.054", 0.052"
2008 -07	V6-3.0L	GCO-RS9YCC		0.054"

(1) Producto nuevo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

### FORD (Continúa)

#### RANGER (Continúa)

2008 -01	L4-2.3L	GCO-RES9YCC4, GCO-RS12YC <sup>(1)</sup>		0.054", 0.052"
2006 -93	V6-3.0L	GCO-RS9YCC, GCO-RS12YC <sup>(1)</sup>		0.054", 0.044"
1997	L4-2.3L		GPL-3013	0.054"
1996 -93	L4-2.3L	GCO-RES9YCC4		0.054"
1992 -91	V6-3.0L	GCO-RS12YC <sup>(1)</sup>		0.044"

#### TAURUS

1995 -93	V6-3.8L	GCO-RS9YCC		0.054"
1991	V6-3.8L	GCO-RS14LC		0.054"
1990	V6-3.8L	GCO-RS9YCC		0.054"
1988	V6-3.8L	GCO-RS9YCC		0.054"

#### THUNDERBIRD

2005 -02	V8-3.9L		GPL-3013	0.045"
1997 -95	V6-3.8L	GCO-RS9YCC		0.054"
1995	V8-4.6L	GCO-RS9YCC		0.054"
1994 -89	V6-3.8L	GCO-RS14LC		0.054"
1988 -85	V6-3.8L	GCO-RS9YCC		0.054"

#### TOPAZ

1994 -89	L4-2.3L	GCO-RS9YCC		0.054"
----------	---------	------------	--	--------

#### WINDSTAR

2003 -97	V6-3.8L		GPL-3013	0.054"
1996 -95	V6-3.8L	GCO-RS14LC		0.054"

### GEO

#### TRACKER

1995 -94	L4-1.6L		GPL-3071	0.032"
----------	---------	--	----------	--------

### GMC

#### ACADIA

2009 -07	V6-3.6L	GCO-RS9YCC		0.06"
----------	---------	------------	--	-------

#### CANYON

2009 -07	L5-3.7L		GPL-7437	0.06"
----------	---------	--	----------	-------

#### K1500

1999 -96	V8-5.7L		GPL-3013	0.060"
1997 -96	V8-5.0L		GPL-3013	0.060"

#### K2500

1999 -96	V8-5.7L		GPL-3013	0.060"
----------	---------	--	----------	--------

#### K3500

2000 -96	V8-5.7L		GPL-3013	0.060"
----------	---------	--	----------	--------

#### SAVANA 1500

2002	V8-5.0L		GPL-3013	0.060"
------	---------	--	----------	--------

#### SAVANA 2500

2002	V8-5.0L		GPL-3013	0.060"
------	---------	--	----------	--------

#### SIERRA

2009 -08	V8-6.2L	GCO-RS9YCC		0.06"
2009 -07	V8-5.3L	GCO-RS9YCC		0.06"

#### SIERRA 1500

2007 -99	V6-4.3L		GPL-3013	0.060"
----------	---------	--	----------	--------

#### TERRAIN

2013	V6-3.6L		GPL-7437	0.044"
------	---------	--	----------	--------


#### YUKON

2009 -07	V8-6.2L	GCO-RS9YCC		0.06"
2009 -00	V8-5.3L	GCO-RS9YCC		0.06"

### HONDA

#### ACCORD

2016 -10	L4-2.4L		GPL-9407	0.044"
2009 -08	L4-2.4L	GCO-RC12MC4	GPL-9407	0.045", 0.044"
2009 -08	V6-3.5L	GCO-RC12MC4		0.045"
2007 -03	L4-2.4L	GCO-RC12MC4		0.045"
2007 -99	V6-3.0L	GCO-RC12MC4		0.045"
2002 -98	L4-2.3L	GCO-UXF79 <sup>(3)</sup>		0.044"

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

### HONDA (Continúa)

#### CITY

2020 -15	L4-1.5L	GCO-RC8YC4 <sup>(1)</sup>		0.052"
2010	L4-1.5L	GCO-RC12MC4		0.052"
2010	L4-1.5L	GCO-RC9YC		0.052"

#### CIVIC

2015 -07	L4-1.8L		GPL-9407	0.044"
2009 -07	L4-1.3L Híbrido	GCO-RC12MC4		0.040"
2009 -06	L4-1.8L	GCO-RC9MC4	GPL-9407	0.035", 0.044"
2005 -01	L4-1.7L	GCO-RC9MC4	GPL-3318 <sup>(1)</sup>	0.035", 0.044"
2000 -93	L4-1.6L	GCO-RC12YC		0.045"

#### CR-V

2017	L4-2.4L	GCO-REA8MCX		0.044"
2016 -10	L4-2.4L		GPL-9407	0.044"
2009	L4-2.4L	GCO-UXF79 <sup>(3)</sup> , GCO-RC9MC4		0.044", 0.035"
2008 -07	L4-2.4L	GCO-RC9MC4		0.035"
2006 -02	L4-2.4L	GCO-UXF79 <sup>(3)</sup> , GCO-RC9MC4		0.044", 0.035"

#### CR-Z

2013	L4-1.5L Híbrido	GCO-RC9YC		0.044"
------	--------------------	-----------	--	--------

#### FIT

2009 -06	L4-1.5L	GCO-UXF79 <sup>(3)</sup>		0.044"
----------	---------	--------------------------	--	--------

#### HR-V

2017 -16	L4-1.8L		GPL-9407	0.044"
----------	---------	--	----------	--------

#### ODYSSEY

2017 -11	V6-3.5L		GPL-9407	0.044"
2009 -05	V6-3.5L	GCO-RC12MC4		0.045"
2004 -02	V6-3.5L	GCO-UXF79 <sup>(3)</sup>		0.044"
2001 -99	V6-3.5L	GCO-RC12MC4		0.045"

#### PASSPORT

1995 -94	V6-3.2L	GCO-RC12YC	GPL-3071	0.044"
----------	---------	------------	----------	--------

#### PILOT

2017 -09	V6-3.5L		GPL-9407	0.044"
2008 -03	V6-3.5L	GCO-UXF79 <sup>(3)</sup>		0.044"

#### RIDGELINE

2014 -09	V6-3.5L		GPL-9407	0.044"
----------	---------	--	----------	--------

### HUMMER

#### H2

2007 -05	V8-6.0L	GCO-RS9YCC		0.06"
----------	---------	------------	--	-------

#### H3

2009 -08	V8-5.3L	GCO-RS9YCC		0.06"
2009 -07	L5-3.7L		GPL-7437	0.06"

### HYUNDAI

#### ELANTRA

2017	L4-2.0L		GPL-9407	0.044"
2015	L4-1.8L		GPL-9407	0.044"

#### TUCSON

2017	L4-2.0L		GPL-9407	0.044"
------	---------	--	----------	--------

### INFINITI

#### I30

2001 -98	V6-3.0L		GPL-3071	0.044"
----------	---------	--	----------	--------

#### I35




2003 -02	V6-3.5L	GCO-REC10YC4		0.044"
----------	---------	--------------	--	--------

#### Q45




2002	V8-4.5L		GPL-3071	0.044"
1997	V8-4.1L	GCO-RC12YC		0.045"
1995 -94	V8-4.5L		GPL-3071	0.044"

(1) Producto nuevo, (3) 4 Electrodo




Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>JAGUAR</b>				
<b>S-TYPE</b>				
2006 -05	V8-4.2L	GCO-RC10YC4		0.044"
2002 -99	V8-4.0L	GCO-UXF79 <sup>(3)</sup>		
<b>XF</b>				
2009	V8-4.2L	GCO-RC10YC4	GPL-3071	0.050"
<b>XJ8</b>				
2009	V8-4.2L	GCO-RC10YC4	GPL-3071	0.050"
2005	V8-4.2L	GCO-RC10YC4		0.044"
2002 -00	V8-4.0L	GCO-RC10YC4		0.044"
1999	V8-4.0L	GCO-RC10YC4	GPL-3071	0.050"
1998	V8-4.0L	GCO-RC10YC4		0.044"
<b>XJR</b>				
2002 -99	V8-4.0L	GCO-RC10YC4		0.044"
<b>XKR</b>				
2006	V8-4.2L	GCO-RC10YC4		0.044"
<b>JEEP</b>				
<b>CHEROKEE</b>				
2020 -14	V6-3.2L		GPL-9407	0.044"
2014	L4-2.4L	GCO-REC10YC4		0.045"
<b>COMMANDER</b>				
2009	V8-5.7L	GCO-RE14MCC4		0.05"
2008 -06	V8-4.7L	GCO-RC12MC4		0.045"
2008 -06	V8-5.7L	GCO-RE14MCC4		0.045"
<b>COMPASS</b>				
2009 -07	L4-2.4L	GCO-RE14MCC4		0.05"
2009	L4-2.4L	GCO-RC12MC4		0.043"
2007	L4-2.0L	GCO-RC12MC4		0.043"
<b>GLADIATOR</b>				
2021 -20	V6-3.6L		GPL-9407	0.044"
<b>GRAND CHEROKEE</b>				
2021 -20	V6-3.6L		GPL-9407	0.044"
2017 -11	V6-3.6L		GPL-9407	0.044"
2010	V8-6.1L	GCO-RE14MCC4		0.045"
2009 -08	V8-4.7L	GCO-UXF79 <sup>(3)</sup>		0.040"
2009 -05	V6-3.7L	GCO-RC9MC4		0.035"
2009 -05	V8-5.7L	GCO-RE14MCC4		0.045"
2009	V8-6.1L	GCO-RE14MCC4		0.05"
2008 -06	V8-6.1L	GCO-RE14MCC4		0.045"
2008	V8-5.7L	GCO-REC10YC4		0.045"
2007	V8-4.7L	GCO-UXF79 <sup>(3)</sup> ,		0.040"
		GCO-RC12MCC4 <sup>(1)</sup> ,		0.045"
		GCO-RC12MC4		0.045"
2006 -05	V8-4.7L	GCO-RC12MC4,		0.045"
		GCO-RC12MCC4 <sup>(1)</sup>		0.04"
2004 -99	V8-4.7L	GCO-UXF79 <sup>(3)</sup> ,		0.040"
		GCO-RC12MCC4 <sup>(1)</sup>		0.04"
1999	L6-4.0L	GCO-UXF79 <sup>(3)</sup>		0.035"
1998	V8-5.2L	GCO-RC12LC4 <sup>(1)</sup> ,		0.044"
		GCO-UXF79 <sup>(3)</sup>		0.040"
1998	V8-5.9L		GPL-3071	0.035"
1997	V8-5.2L	GCO-RC12LC4 <sup>(1)</sup>	GPL-3071	0.044"
				0.035"
1996 -93	V8-5.2L		GPL-3071	0.035"
<b>LIBERTY</b>				
2012	V6-3.7L	GCO-RC9MC4		0.035"
2011 -10	V6-3.7L	GCO-UXF79 <sup>(3)</sup> ,		0.044"
		GCO-RC9MC4		0.035"
2009 -02	V6-3.7L	GCO-RC9MC4		0.035"
<b>PATRIOT</b>				
2017 -12	L4-2.4L		GPL-3318 <sup>(1)</sup>	0.044"
2011 -07	L4-2.4L	GCO-RC9MC4	GPL-3318 <sup>(1)</sup>	0.044"

(1) Producto nuevo, (3) 4 Electrodo

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>JEEP (Continúa)</b>				
<b>WRANGLER</b>				
2021 -20	V6-3.6L		GPL-9407	0.044"
2017 -12	V6-3.6L		GPL-9407	0.044"
2009 -07	V6-3.8L		GPL-7437	0.054"
2006 -05	L6-4.0L	GCO-RC12MC4,		0.045"
		GCO-RC12YC		0.04"
2006 -97	L6-4.0L	GCO-RC12YC		0.04"
2002 -97	L4-2.5L	GCO-RC12MC4		0.04"
1995 -93	L4-2.5L	GCO-RC12YC		0.035"
1995 -93	L6-4.0L	GCO-RC12YC		0.04"
<b>KIA</b>				
<b>FORTE</b>				
2017	L4-2.0L		GPL-9407	0.044"
<b>RIO</b>				
2016	L4-1.6L		GPL-9407	0.044"
<b>SORENTO</b>				
2017 -16	L4-2.4L		GPL-9407	0.044"
<b>SOUL</b>				
2017 -16	L4-2.0L		GPL-9407	0.044"
<b>SPORTAGE</b>				
2017	L4-2.4L	GCO-REC10YC4		0.044"
<b>LAND ROVER</b>				
<b>LR2</b>				
2012 -08	L6-3.2L	GCO-REC10YC4		
<b>LR3</b>				
2008 -06	V8-4.4L	GCO-UXF79 <sup>(3)</sup>		
<b>LR4</b>				
2013 -10	V8-5.0L	GCO-REC10YC4		
<b>RANGE ROVER</b>				
2009 -06	V8-4.4L	GCO-UXF79 <sup>(3)</sup>		
2001 -99	V8-4.6L		GPL-3071	0.04"
<b>LINCOLN</b>				
<b>AVIATOR</b>				
2005 -03	V8-4.6L	GCO-RS9YCC		0.054"
<b>BLACKWOOD</b>				
2003 -02	V8-5.4L	GCO-RS9YCC		0.054"
<b>CONTINENTAL</b>				
2002 -95	V8-4.6L		GPL-3013	0.054"
<b>LS</b>				
2006 -00	V8-3.9L		GPL-3071	0.044"
<b>MARK LT</b>				
2007 -06	V8-5.4L	GCO-RS9YCC		0.054"
<b>MARK VIII</b>				
1998 -97	V8-4.6L		GPL-3013	0.054"
1996	V8-4.6L		GPL-3013	0.05"
1995 -93	V8-4.6L		GPL-3013	0.054"
<b>MKX</b>				
2009 -07	V6-3.5L	GCO-RS9YCC		0.054"
<b>NAVIGATOR</b>				
2009	V8-5.4L		GPL-3013	0.054"
2009	V8-5.4L	GCO-RS9YCC	GPL-3013	0.054"
2008 -05	V8-5.4L	GCO-RS9YCC		0.054"
2005 -98	V8-5.4L		GPL-3013	0.054"
<b>TOWN CAR</b>				
2009	V8-4.6L		GPL-3013	0.054"
2007 -92	V8-4.6L		GPL-3013	0.054"
1991	V8-4.6L	GCO-RS9YCC		0.054"
<b>ZEPHYR</b>				
2006	V6-3.0L	GCO-RS9YCC		0.054"

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

<b>MAZDA</b>				
<b>2</b>				
2017 -15	L4-1.5L	GCO-RC10YC4		0.044"
2014 -12	L4-1.5L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044"
2012	L4-1.5L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044"

<b>3</b>				
2017 -14	L4-2.0L	GCO-REA8MCX		0.044"
2010 -06	L4-2.0L		GPL-7437	
2009 -08	L4-2.3L Turbo		GPL-7437	
2009 -06	L4-2.3L		GPL-7437	

<b>5</b>				
2009 -06	L4-2.3L		GPL-7437	

<b>6</b>				
2008 -03	L4-2.3L		GPL-7437	
2008 -03	V6-3.0L		GPL-7437	

<b>CX-5</b>				
2015 -13	L4-2.0L	GCO-REA8MCX		0.044"

<b>CX-7</b>				
2009 -07	L4-2.3L Turbo		GPL-7437	0.05"

<b>CX-9</b>				
2007	V6-3.5L		GPL-7437	0.05"

<b>MX-5</b>				
2008 -06	L4-2.0L		GPL-7437	0.055"

**MERCEDES-BENZ**

<b>A160</b>				
2005 -04	L4-1.6L		GPL-3071	
2001 -00	L4-1.6L		GPL-3071	

<b>A190</b>				
2005 -04	L4-1.9L		GPL-3071	
2001	L4-1.9L		GPL-3071	

<b>C220</b>				
1997 -95	L4-2.2L		GPL-3071	

<b>C230</b>				
2000 -96	L4-2.3L		GPL-3071	

<b>C240</b>				
2002 -01	V6-2.6L		GPL-3071	

<b>C280</b>				
2000 -99	V6-2.8L	GCO-RC12YC		
1998 -95	L6-2.8L	GCO-UXF79 <sup>(3)</sup>		

<b>C32 AMG</b>				
2004 -02	V6-3.2L		GPL-3071	

<b>C320</b>				
2005 -01	V6-3.2L		GPL-3071	

<b>C36 AMG</b>				
1997 -96	L6-3.6L	GCO-UXF79 <sup>(3)</sup>		

<b>C43 AMG</b>				
2000 -98	V8-4.3L	GCO-RC12YC		

<b>CLK320</b>				
2003 -98	V6-3.2L	GCO-RC12YC		

<b>E280</b>				
1999	V6-2.8L	GCO-RC12YC		

<b>E420</b>				
1997	V8-4.2L	GCO-RC12YC		
1995	V8-4.2L	GCO-RC12YC		

<b>E430</b>				
2001	V8-4.3L		GPL-3071	


<b>G65 AMG</b>				
2018 -14	V12 6.0L Turbo	GCO-RC10YC4		0.044"

<b>ML320</b>				
2002 -98	V6-3.2L	GCO-RC12YC		

<b>ML320</b>				
2002 -98	V6-3.2L	GCO-RC12YC		

<b>ML320</b>				
2002 -98	V6-3.2L	GCO-RC12YC		

<b>ML320</b>				
2002 -98	V6-3.2L	GCO-RC12YC		

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

**MERCEDES-BENZ (Continúa)**

<b>S430</b>				
2003 -01	V8-4.3L	GCO-RC12YC		

<b>S500</b>				
2002 -96	V8-5.0L	GCO-RC12YC		

<b>S600</b>				
1998 -96	V12 6.0L	GCO-RC12YC		

<b>S600L</b>				
1995	V12 6.0L	GCO-RC12YC		

<b>SL320</b>				
1997 -96	L6-3.2L	GCO-RC12YC		

<b>SL500</b>				
2003 -96	V8-5.0L	GCO-RC12YC		

<b>SL55 AMG</b>				
2002	V8-5.0L	GCO-RC12YC		

<b>SL600</b>				
2002 -96	V12 6.0L	GCO-RC12YC		

<b>SL65 AMG</b>				
2019 -13	V12 6.0L Turbo	GCO-RC10YC4		0.044"

<b>SLK230</b>				
2004 -01	L4-2.3L		GPL-3071	
1998 -97	L4-2.3L		GPL-3071	

**MERCURY**

<b>MARINER</b>				
2009 -05	V6-3.0L	GCO-RS9YCC		0.054"

<b>MILAN</b>				
2009 -06	V6-3.0L	GCO-RS9YCC		0.054"

<b>MONTEGO</b>				
2007 -05	V6-3.0L	GCO-RS9YCC		0.054"

<b>SABLE</b>				
2004 -03	V6-3.0L		GPL-3013	0.054"

<b>TOPAZ</b>				
1994 -93	L4-2.3L		GPL-3013	0.045"

**MINI**

<b>COOPER</b>				
2003 -02	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		

**MITSUBISHI**

<b>ASX</b>				
2013	L4-2.0L	GCO-RC9YC		0.044"

<b>ECLIPSE</b>				
2012 -11	V6-3.8L	GCO-RC10YC4		0.044"
2009 -08	V6-3.8L	GCO-RC10YC4	GPL-3071	0.044", 0.045"
2007 -06	V6-3.8L		GPL-3071	0.045"
2005 -03	V6-3.0L	GCO-RC10YC4	GPL-3071	0.044", 0.045"
2002 -00	V6-3.0L		GPL-3071	0.045"

<b>ENDEAVOR</b>				
2011 -10	V6-3.8L	GCO-RC10YC4		0.044"
2009 -04	V6-3.8L	GCO-RC10YC4	GPL-3071	0.044", 0.045"

<b>GALANT</b>				
2009 -05	L4-2.4L		GPL-3071	0.045"
2009	V6-3.8L		GPL-3071	0.045"
2007 -04	V6-3.8L		GPL-3071	0.045"
2004	L4-2.4L		GPL-3071	0.044"
2003 -94	L4-2.4L		GPL-3071	0.045"
2003	V6-3.0L	GCO-RC10YC4		0.044"
2003	V6-3.0L	GCO-RC10YC4	GPL-3071	0.044", 0.045"
2002 -99	V6-3.0L		GPL-3071	0.045"

<b>GRANDIS</b>				
2009 -07	L4-2.4L		GPL-3071	0.045"

(3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER.</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

**MITSUBISHI (Continúa)**

<b>LANCER</b>				
2010	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		
2010	L4-2.4L	GCO-RC12YC		0.045"
2009 -08	L4-2.0L	GCO-RC12YC		0.045"
2009	L4-2.4L		GPL-3071	0.045"
2007 -04	L4-2.0L	GCO-RC12YC, GCO-RC10YC4		0.045", 0.044"
2007	L4-2.0L	GCO-RC10YC4		0.044"
2006 -05	L4-2.4L		GPL-3071	0.045"
2006 -04	L4-2.0L Turbo	GCO-RC12YC, GCO-RC10YC4		0.045", 0.044"
2004	L4-2.0L	GCO-RC10YC4		0.044"
2004	L4-2.0L	GCO-RC9YC, GCO-RC10YC4		0.045", 0.044"

<b>MONTERO</b>				
2019 -08	V6-3.8L	GCO-RC10YC4		0.044"
2006 -05	V6-3.8L	GCO-RC10YC4		0.044"
2006 -05	V6-3.8L	GCO-RC10YC4	GPL-3071	0.044", 0.045"
2004	V6-3.8L	GCO-RC10YC4 <sup>(3)</sup>		0.044"
2004	V6-3.8L	GCO-RC10YC4		0.044"
2003	V6-3.8L	GCO-RC10YC4 <sup>(3)</sup>		0.044"
2003	V6-3.8L	GCO-RC10YC4		0.044"

<b>MONTERO SPORT</b>				
2006 -03	V6-3.5L	GCO-RC10YC4		0.044"

<b>OUTLANDER</b>				
2016 -14	L4-2.4L		GPL-9407	0.044"
2013 -10	L4-2.4L	GCO-RC10YC4		0.044"
2009 -08	L4-2.4L	GCO-RC10YC4	GPL-3071	0.044", 0.045"
2009 -07	V6-3.0L		GPL-3071	0.045"

<b>SPACE STAR</b>				
2004	L4-1.8L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044"
2003	L4-1.8L	GCO-RC10YC4		0.044"

**NISSAN**

<b>200SX</b>				
1997 -95	L4-2.0L	GCO-RC12YC	GPL-3071	0.044"

<b>240SX</b>				
1998	L4-2.4L		GPL-3071	0.044"
1993	L4-2.4L		GPL-3071	0.044"

<b>300ZX</b>				
1996	V6-3.0L		GPL-3071	0.044"
1996	V6-3.0L Turbo		GPL-3071	0.044"
1995 -91	V6-3.0L	GCO-UXF79 <sup>(3)</sup>		
1995	V6-3.0L Turbo	GCO-UXF79 <sup>(3)</sup>		

<b>350Z</b>				
2008 -04	V6-3.5L		GPL-7437	0.05"

<b>ALMERA</b>				
2005 -01	L4-1.8L	GCO-REC10YC4		0.05"

<b>ALTIMA</b>				
2016 -07	V6-3.5L	GCO-REA8MCX		0.044"
2009 -07	L4-2.5L Híbrido	GCO-REC10YC4		0.05"
2009 -02	L4-2.5L	GCO-REC10YC4		0.05"
2001	L4-2.4L	GCO-REC10YC4		0.05"
2000	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.044"
1999 -93	L4-2.4L		GPL-3071	0.044"

<b>APRIO</b>				
2010 -08	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040"

<b>ARMADA</b>				
2009 -05	V8-5.6L		GPL-7437	0.05"

<b>GONHER.</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

**NISSAN (Continúa)**

<b>FRONTIER</b>				
2008 -06	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.044"
2004 -99	V6-3.3L		GPL-3071	0.044"
2004 -98	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.044"

<b>HIKARI</b>				
1992 -88	L4-1.6L	GCO-N12YC		0.045"
1992 -88	L4-1.6L Turbo	GCO-N12YC		0.045"

<b>ICHI VAN</b>				
1994 -91	L4-2.4L	GCO-N12YC		0.044"

<b>KICKS</b>				
2017	L4-1.6L	GCO-REA8MCX		0.044"

<b>LUCINO</b>				
2000 -96	L4-1.6L		GPL-3071	0.044"
2000	L4-2.0L		GPL-3071	0.044"
1999 -96	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.044"

<b>MARCH</b>				
2017 -13	L4-1.6L	GCO-REA8MCX		0.044"
2012	L4-1.6L	GCO-UXF79 <sup>(3)</sup> , GCO-REA8MCX		0.044"

<b>MAXIMA</b>				
2007 -04	V6-3.5L		GPL-7437	0.05"
2001 -96	V6-3.0L		GPL-3071	0.044"
1995	V6-3.0L	GCO-RC12YC		0.045"
1993 -91	V6-3.0L	GCO-RC12YC		0.045"

<b>MICRA</b>				
2007 -05	L4-1.4L	GCO-REC10YC4		0.044"

<b>MURANO</b>				
2007 -04	V6-3.5L		GPL-7437	0.05"

<b>NP300</b>				
2015 -10	L4-2.4L	GCO-RC12YC	GPL-3071	0.044"

<b>NV350 URVAN</b>				
2017 -14	L4-2.5L	GCO-REA8MCX		0.044"

<b>PATHFINDER</b>				
2017 -13	V6-3.5L	GCO-REA8MCX		0.044"
2004 -01	V6-3.5L	GCO-RC10YC4		0.044"
2000 -97	V6-3.3L	GCO-RC12YC		0.045"

<b>PICKUP</b>				
2010 -94	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.044"
1993 -91	L4-2.4L	GCO-N12YC		0.044"

<b>PLATINA</b>				
2010	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.044"
2009 -02	L4-1.6L	GCO-RC12YC		0.045"

<b>QUEST</b>				
2002	V6-3.3L	GCO-RC12YC		0.039"
2001 -99	V6-3.3L		GPL-3071	0.039"
1998 -93	V6-3.0L	GCO-RC12YC		0.045"

<b>ROGUE</b>				
2012 -08	L4-2.5L	GCO-REA8MCX		0.044"




<b>SAMURAI</b>				
1986	L4-1.6L	GCO-N12YC		0.035"




<b>SENTRA</b>				
2017 -13	L4-1.8L	GCO-REA8MCX		0.044"
2012 -10	L4-2.0L	GCO-UXF79 <sup>(3)</sup> , GCO-REA8MCX		0.044"
2009 -07	L4-2.0L	GCO-REA8MCX	GPL-3071	0.044"
2009 -07	L4-2.0L	GCO-UXF79 <sup>(3)</sup> , GCO-REA8MCX	GPL-3071	0.044"
2009 -02	L4-2.5L	GCO-REC10YC4		0.05"
2006 -00	L4-1.8L	GCO-REC10YC4		0.05"
2001 -96	L4-2.0L		GPL-3071	0.044"
2000 -93	L4-1.6L		GPL-3071	0.044"
1994 -93	L4-2.0L		GPL-3071	0.044"

<b>TIIDA</b>				
2017 -07	L4-1.8L	GCO-REA8MCX		0.044"

(3) 4 Electrodo




Verifique la calibración de las bujías antes de instalarlas.




<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>NISSAN (Continúa)</b>				
<b>TITAN</b>				
2009 -04	V8-5.6L		GPL-7437	0.05"
<b>TSUBAME</b>				
2004 -93	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
<b>TSURU</b>				
2015 -97	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.044"
1997	L4-1.6L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>		0.044"
1996 -95	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.044"
1996	L4-1.6L		GPL-3071	0.044"
1995	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.044"
1994 -93	L4-2.0L		GPL-3071	0.044"
1992 -86	L4-1.6L	GCO-N12YC		0.035"
1985 -84	L4-1.5L	GCO-N12YC		0.044"
<b>URVAN</b>				
2012 -08	L4-2.5L	GCO-REA8MCX		0.044"
2007 -00	L4-2.4L		GPL-3071	0.044"
<b>VERSA</b>				
2017 -16	L4-1.6L	GCO-REA8MCX		0.044"
2015 -12	L4-1.6L	GCO-UXF79 <sup>(3)</sup> , GCO-REA8MCX		0.044"
<b>XTERRA</b>				
2004 -00	V6-3.3L		GPL-3071	
<b>X-TRAIL</b>				
2017 -08	L4-2.5L	GCO-REA8MCX		0.044"
<b>OLDSMOBILE</b>				
<b>88</b>				
1999 -92	V6-3.8L	GCO-RES9YCC4		
<b>CUTLASS</b>				
1996	V6-3.1L		GPL-3013	
<b>SILHOUETTE</b>				
1995	V6-3.8L	GCO-RES9YCC4		0.06"
1994 -93	V6-3.8L		GPL-3013	0.06"
<b>PEUGEOT</b>				
<b>206</b>				
2009 -02	L4-1.4L	GCO-RC12YC		0.032"
2009 -02	L4-1.6L		GPL-7437	0.06"
2001	L4-1.4L	GCO-UXF79 <sup>(3)</sup>		
<b>207</b>				
2011 -10	L4-1.4L	GCO-UXF79 <sup>(3)</sup>		
2009 -08	L4-1.6L Turbo		GPL-7437	0.06"
2009	L4-1.4L	GCO-RC12YC		0.032"
<b>306</b>				
2000 -98	L4-1.8L		GPL-7437	0.06"
1997	L4-1.6L		GPL-7437	0.06"
<b>405</b>				
1999 -98	L4-2.0L	GCO-RC12YC		0.032"
<b>406</b>				
2003 -01	L4-2.0L		GPL-7437	0.06"
2002 -01	V6-3.0L		GPL-7437	0.06"
<b>407</b>				
2009 -07	L4-2.2L		GPL-7437	0.06"
<b>607</b>				
2003 -02	V6-2.9L	GCO-REC10YC4		0.040"
<b>GRAND RAID</b>				
2009 -07	L4-1.6L		GPL-7437	0.06"
<b>PARTNER</b>				
2009 -04	L4-1.6L		GPL-7437	0.06"
<b>PLYMOUTH</b>				
<b>BARRACUDA</b>				
1969	V8-5.2L	GCO-N12YC		0.035"

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>PLYMOUTH (Continúa)</b>				
<b>BREEZE</b>				
1996	L4-2.0L	GCO-RC9YC, GCO-UXF79 <sup>(3)</sup>		0.035"
<b>LASER</b>				
1994 -93	L4-1.8L	GCO-RN9YC		0.044"
1994 -93	L4-2.0L	GCO-RN9YC		0.044"
1993	L4-2.0L Turbo	GCO-RN9YC		0.044"
<b>VOYAGER</b>				
1995 -93	L4-2.5L	GCO-RN12YC		0.035"
<b>PONTIAC</b>				
<b>AZTEK</b>				
2005 -01	V6-3.4L		GPL-3013	0.060"
<b>BONNEVILLE</b>				
2005 -93	V6-3.8L	GCO-RES9YCC4		0.06"
<b>FIREBIRD</b>				
2002 -93	V8-5.7L	GCO-RES9YCC4		0.05"
<b>G3</b>				
2009 -07	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040"
<b>G4</b>				
2006 -05	L4-2.2L		GPL-7437	
2006	L4-2.4L		GPL-7437	
<b>G5</b>				
2009 -07	L4-2.2L		GPL-7437	
2008 -07	L4-2.4L		GPL-7437	
<b>G6</b>				
2009 -07	V6-3.6L	GCO-RS9YCC		0.040"
2009 -05	V6-3.5L	GCO-RS9YCC		0.060"
<b>GRAND AM</b>				
2005	V6-3.4L		GPL-3013	0.06"
2004 -02	V6-3.4L	GCO-RS9YCC		0.06"
2001 -99	V6-3.4L		GPL-3013	0.06"
<b>GRAND PRIX</b>				
2008 -97	V6-3.8L	GCO-RS9YCC		0.06"
2003 -93	V6-3.1L		GPL-3013	0.06"
<b>MATIZ</b>				
2010	L4-1.0L	GCO-UX79 <sup>(3)</sup>		
2009 -04	L4-1.0L	GCO-RN9YC		0.035"
<b>MONTANA</b>				
2009 -06	V6-3.9L	GCO-RS9YCC		0.06"
2006 -05	V6-3.5L	GCO-RS9YCC		0.06"
<b>SOLSTICE</b>				
2009 -06	L4-2.4L		GPL-7437	0.04"
<b>SUNFIRE</b>				
2005 -95	L4-2.2L		GPL-7437	0.06"
2002	L4-2.4L		GPL-7437	0.06"
2001 -99	L4-2.4L		GPL-3013	0.06"
1998 -96	L4-2.4L		GPL-7437	0.06"
<b>TORRENT</b>				
2009 -06	V6-3.4L	GCO-RS9YCC		0.06"
<b>TRANS SPORT</b>				
1995 -93	V6-3.8L		GPL-3013	0.060"
<b>PORSCHE</b>				
<b>911</b>				
2007 -05	H6-3.6L	GCO-UXF79 <sup>(3)</sup>		
2007	H6-3.6L Turbo	GCO-UXF79 <sup>(3)</sup>		
2005	H6-3.6L Turbo	GCO-UXF79 <sup>(3)</sup>		
<b>BOXSTER</b>				
2007 -05	H6-2.7L	GCO-UXF79 <sup>(3)</sup>		
<b>CAYMAN</b>				
2007	H6-2.7L	GCO-UXF79 <sup>(3)</sup>		
2007	H6-3.4L	GCO-UXF79 <sup>(3)</sup>		

(3) 4 Electrodo




Verifique la calibración de las bujías antes de instalarlas.




<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>PORSCHE (Continúa)</b>				
<b>PANAMERA</b>				
2015 -14	V6-3.0L Híbrido	GCO-UXF79 <sup>(3)</sup>		0.032"
2015 -14	V6-3.0L Turbo	GCO-UXF79 <sup>(3)</sup>		0.032"
<b>RAM</b>				
<b>1500</b>				
2013 -11	V6-3.7L		GPL-3318 <sup>(1)</sup>	0.044"
<b>700</b>				
2018 -15	L4-1.6L	GCO-RC9YC		0.036"
<b>RENAULT</b>				
<b>ALLIANCE</b>				
1986 -85	L4-1.7L	GCO-UX79 <sup>(3)</sup>		
1984	L4-1.7L	GCO-N12YC		0.025"
<b>CLIO</b>				
2009 -02	L4-1.6L	GCO-RC12YC		0.045"
2006 -02	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		
<b>ENCORE</b>				
1986 -85	L4-1.7L	GCO-UX79 <sup>(3)</sup>		
<b>EURO CLIO</b>				
2008 -07	L4-1.6L	GCO-RC12YC		0.045"
<b>KANGOO</b>				
2009 -07	L4-1.6L	GCO-RC12YC		0.045"
<b>KANGOO EXPRESS</b>				
2009 -04	L4-1.6L	GCO-RC12YC		
<b>LAGUNA</b>				
2006	L4-2.0L Turbo	GCO-UXF79 <sup>(3)</sup>		
2004 -03	V6-2.9L	GCO-UXF79 <sup>(3)</sup>		
<b>MEGANE</b>				
2010	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
2009 -07	L4-2.0L Turbo	GCO-UXF79 <sup>(3)</sup>		
2009 -01	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		
2009	L4-1.6L	GCO-RC12YC		0.045"
2008	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
2005	L4-2.0L Turbo	GCO-UXF79 <sup>(3)</sup>		
<b>R12</b>				
1978 -75	L4-1.6L	GCO-N12YC		
<b>R18</b>				
1986 -85	L4-2.0L	GCO-RES9YCC4		
1984 -80	L4-1.6L	GCO-N12YC		
<b>SANDERO</b>				
2011 -10	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
<b>SCALA</b>				
2012 -11	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
<b>SCENIC</b>				
2004 -01	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		
<b>SCENIC II</b>				
2008 -05	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		
<b>STEPWAY</b>				
2011	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
<b>SEAT</b>				
<b>ALHAMBRA</b>				
2007 -04	L4-1.8L Turbo	GCO-RC8VTC4 <sup>(2)</sup>		0.035"
<b>CORDOBA</b>				
2009 -04	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.035"
2009 -04	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040"
2003	L4-2.0L	GCO-RC8VTC4 <sup>(2)</sup>		0.040"
2002 -01	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.035"

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>SEAT (Continúa)</b>				
<b>IBIZA</b>				
2013 -09	L4-2.0L	GCO-RC8VTC4 <sup>(2)</sup>		0.040"
2012 -04	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040"
2008 -03	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040"
2008	L4-1.8L Turbo	GCO-UXF79 <sup>(3)</sup>		0.040"
2002 -01	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040"
<b>LEON</b>				
2009 -08	L4-2.0L Turbo	GCO-RC12MC4		0.04"
2009	L4-1.8L Turbo	GCO-RC8VTC4 <sup>(2)</sup>		0.035"
2008	L4-2.0L	GCO-RC12MC4		0.04"
2006 -01	L4-1.8L Turbo	GCO-UXF79 <sup>(3)</sup>		0.035"
2005 -01	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.035"
<b>NUEVO IBIZA</b>				
2010	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
2010	L4-2.0L	GCO-RC8VTC4 <sup>(2)</sup>		
<b>TOLEDO</b>				
2005 -01	L4-1.8L	GCO-RC8VTC4 <sup>(2)</sup>		0.040"
2004 -01	L4-1.8L Turbo	GCO-RC8VTC4 <sup>(2)</sup>		0.040"
<b>SUBARU</b>				
<b>LEGACY</b>				
2007 -06	H4-2.5L	GCO-RC10YC4		0.044"
2007 -06	H4-2.5L Turbo	GCO-RC10YC4		0.044"
<b>OUTBACK</b>				
2009	H4-2.5L	GCO-RC10YC4		0.044"
2008 -06	H4-2.5L Turbo	GCO-RC10YC4		0.044"
<b>SUZUKI</b>				
<b>AERIO</b>				
2007 -06	L4-2.3L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044"
<b>GRAND VITARA</b>				
2008	V6-2.7L	GCO-RC10YC4		0.044"
2007 -06	V6-2.7L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044"
<b>SWIFT</b>				
2011 -08	L4-1.5L	GCO-RC8YC4 <sup>(1)</sup>		0.044"
2007	L4-1.5L	GCO-RC8YC4 <sup>(1)</sup> , GCO-UXF79 <sup>(3)</sup>		0.044"
<b>SX4</b>				
2011 -08	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		
<b>TOYOTA</b>				
<b>4RUNNER</b>				
2008	V8-4.7L	GCO-RC10YC4		0.044"
2007 -04	V8-4.7L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044"
2007	V6-4.0L		GPL-3071	0.045"
2003	V8-4.7L	GCO-RC10YC4		0.044"
<b>AVANZA</b>				
2015 -07	L4-1.5L	GCO-RA6HC <sup>(1)</sup>		0.036"
<b>CAMRY</b>				
2009 -07	V6-3.5L	GCO-UXF79 <sup>(3)</sup>		0.044"
2009 -03	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.044"
2006 -05	V6-3.0L	GCO-UXF79 <sup>(3)</sup>		0.044"
<b>COROLLA</b>				
2017 -10	L4-1.8L	GCO-REA8MCX		0.044"
2009	L4-1.8L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4, GCO-REA8MCX		0.044"
2009	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.044"

(1) Producto nuevo, (2) 3 Electrodo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>TOYOTA (Continúa)</b>				
<b>COROLLA (Continúa)</b>				
2008 -07	L4-1.8L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044"
2006 -93	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.044"
<b>HIACE</b>				
2007 -06	L4-2.7L	GCO-UXF79 <sup>(3)</sup>		0.044"
<b>HILUX</b>				
2007 -04	L4-2.7L	GCO-UXF79 <sup>(3)</sup>		0.044"
<b>LAND CRUISER</b>				
2009 -08	V8-5.7L	GCO-UXF79 <sup>(3)</sup>		0.044"
2007	V8-4.7L	GCO-UXF79 <sup>(3)</sup>		0.044"
2006 -04	V8-4.7L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044"
<b>MATRIX</b>				
2009 -08	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.044"
2007 -04	L4-1.8L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044"
2003	L4-1.8L	GCO-RC10YC4		0.044"
<b>MR2 SPYDER</b>				
2006 -05	L4-1.8L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044"
<b>PRIUS C</b>				
2018	L4-1.5L Híbrido	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>		0.043"
<b>RAV4</b>				
2008 -04	L4-2.4L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4	GPL-3346 <sup>(1)</sup>	0.044"
<b>SEQUOIA</b>				
2008	V8-4.7L	GCO-RC10YC4		0.044"
<b>SIENNA</b>				
2006 -04	V6-3.3L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4, GCO-RC8YC4 <sup>(1)</sup>		0.044"
<b>SOLARA</b>				
2006	V6-3.3L	GCO-RC10YC4		0.044"
<b>TACOMA</b>				
2011 -10	V6-4.0L	GCO-UXF79 <sup>(3)</sup>		0.044"
2009 -07	V6-4.0L		GPL-3071	0.045"
<b>TUNDRA</b>				
2009 -08	V8-4.7L		GPL-3071	0.045"
2009 -05	V6-4.0L		GPL-3071	0.045"
2007	V8-4.7L	GCO-RC10YC4	GPL-3071	0.044", 0.045"
2006 -00	V8-4.7L		GPL-3071	0.045"
<b>YARIS</b>				
2011	L4-1.5L	GCO-RC12YC		0.044"
2010 -06	L4-1.5L	GCO-UXF79 <sup>(3)</sup>		0.044"
2005	L4-1.3L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044"
2004	L4-1.3L	GCO-RC10YC4		0.044"
<b>VAM</b>				
<b>GREMLIN</b>				
1981 -76	L6-4.2L	GCO-N12YC		0.035"
1975 -74	L6-4.2L	GCO-UX79 <sup>(3)</sup>		
<b>JAVELIN</b>				
1973 -72	L6-4.6L	GCO-N12YC		0.035"
<b>PACER</b>				
1979	L6-4.6L	GCO-N12YC		0.035"
1978 -76	L6-4.6L	GCO-UX79 <sup>(3)</sup>		
<b>VOLKSWAGEN</b>				
<b>ATLANTIC</b>				
1987 -85	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.028"
1987	L4-1.7L	GCO-N12YC		0.028"
1986 -83	L4-1.7L	GCO-UX79 <sup>(3)</sup>		0.028"
1984	L4-1.8L	GCO-N12YC		0.028"

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>VOLKSWAGEN (Continúa)</b>				
<b>ATLANTIC (Continúa)</b>				
1982	L4-1.7L	GCO-N12YC		0.027"
1981	L4-1.6L	GCO-UX79 <sup>(3)</sup>		0.028"
<b>BEETLE</b>				
2011 -10	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040"
2008	L4-2.0L	GCO- RC8V7YC4 <sup>(2)</sup>		0.040"
2007	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040"
2005 -98	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040"
<b>CABRIO</b>				
1999 -98	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040"
<b>CARIBE</b>				
1987 -86	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.028"
1987	L4-1.7L	GCO-N12YC		0.028"
1986 -81	L4-1.7L	GCO-UX79 <sup>(3)</sup>		0.028"
1985 -84	L4-1.8L	GCO-N12YC		0.028"
1980 -77	L4-1.6L	GCO-UX79 <sup>(3)</sup>		0.028"
<b>CLASICO</b>				
2014 -11	L4-2.0L	GCO- RC8V7YC4 <sup>(2)</sup>		0.040"
<b>COMBI</b>				
2001 -88	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.028"
<b>CORSAR</b>				
1988 -84	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.028"
<b>CROSSFOX</b>				
2012 -11	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040"
2009 -07	L4-1.6L	GCO- RC8V7YC4 <sup>(2)</sup>		0.04"
<b>DERBY</b>				
2009 -08	L4-1.8L	GCO-N7BYC		0.032"
2007	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.032"
2006 -95	L4-1.8L	GCO-N7BYC		0.032"
2003 -02	L4-2.0L	GCO- RC8V7YC4 <sup>(2)</sup>		0.032"
<b>EUROVAN</b>				
2004 -01	L5-2.5L	GCO-UXF79 <sup>(3)</sup>		0.032"
2000	V6-2.8L	GCO- RC8V7YC4 <sup>(2)</sup> , GCO-RC10YC4		0.044"
<b>GOL</b>				
2020 -16	L4-1.6L	GCO- KC8ZMCC <sup>(1)</sup>		0.044"
2011 -09	L4-1.6L	GCO- RC8V7YC4 <sup>(2)</sup>		0.04"
<b>GOL SEDAN</b>				
2011 -10	L4-1.6L	GCO- RC8V7YC4 <sup>(2)</sup>		0.044"
<b>GOLF</b>				
2007 -06	L4-2.0L	GCO- RC8V7YC4 <sup>(2)</sup>		0.04"
2005 -02	L4-1.8L Turbo		GPL-3071	0.032"
2005 -95	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.032"
2001	L4-1.8L Turbo	GCO-RC10YC4	GPL-3071	0.044", 0.032"
1999 -96	L4-1.8L	GCO-N7BYC, GCO-RC10YC4		0.032", 0.044"
1999 -96	V6-2.8L	GCO-RC9BMC		0.04"
1995 -92	L4-1.8L	GCO-N7BYC		0.032"
1991 -88	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.032"
1987	L4-1.8L	GCO-N12YC		0.028"
<b>GTI</b>				
2009 -07	L4-2.0L Turbo	GCO-RC12MC4		0.04"

(1) Producto nuevo, (2) 3 Electrodo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

**VOLKSWAGEN (Continúa)****JETTA**

2018 -11	L4-2.0L	GCO-KC8ZMCC <sup>(1)</sup>		0.044"
2018 -08	L5-2.5L	GCO-KC8ZMCC <sup>(1)</sup>		0.044"
2012	L4-2.0L Turbo	GCO-RC8VTYC4 <sup>(2)</sup>		0.040"
2010	L4-2.0L	GCO-KC8ZMCC <sup>(1)</sup> , GCO-RC8VTYC4 <sup>(2)</sup>		0.044", 0.040"
2009 -08	L4-2.0L	GCO-UXF79 <sup>(3)</sup> , GCO-RC9BMC		0.040", 0.04"
2009 -08	L4-2.0L Turbo	GCO-RC9BMC		0.04"
2008	L4-2.0L Turbo	GCO-UXF79 <sup>(3)</sup> , GCO-RC9BMC		0.040", 0.04"
2007 -00	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040"
2007	L4-2.0L Turbo	GCO-UXF79 <sup>(3)</sup>		0.040"
2005 -04	L4-1.8L Turbo	GCO-RC8VTYC4 <sup>(2)</sup>		0.032"
2003	L4-1.8L Turbo	GCO-RC12YC		0.032"
2002 -01	V6-2.8L	GCO-RC12YC		0.04"
2002 -00	L4-1.8L Turbo	GCO-RC8VTYC4 <sup>(2)</sup>		0.032"
2000 -95	V6-2.8L	GCO-RC9BMC		0.04"
1999 -98	L4-2.0L	GCO-RC8VTYC4 <sup>(2)</sup>		0.04"
1999 -93	L4-1.8L	GCO-N7BYC		0.032"
1999	L4-1.8L Turbo	GCO-N7BYC		0.032"
1997 -93	L4-2.0L	GCO-RC9BMC		0.04"
1992 -87	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.032"

**JETTA CITY**

2009 -08	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040"
----------	---------	--------------------------	--	--------

**LUPO**

2009 -07	L4-1.6L	GCO-RC8VTYC4 <sup>(2)</sup>		0.040"
2006 -05	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040"

**PASSAT**

2018 -12	L5-2.5L	GCO-KC8ZMCC <sup>(1)</sup>		0.032"
2017 -12	V6-3.6L		GPL-9407	0.044"
2005 -99	V6-2.8L	GCO-RC8VTYC4 <sup>(2)</sup>		0.04"
2005	L4-1.8L Turbo	GCO-RC12MC4		0.04"
2004 -00	L4-1.8L Turbo	GCO-RC8VTYC4 <sup>(2)</sup> , GCO-RC10YC4		0.028", 0.044"
1999	L4-1.8L Turbo	GCO-RC12MC4		0.04"
1997 -96	V6-2.8L	GCO-RC9BMC		0.04"
1993	L4-2.0L	GCO-RC8VTYC4 <sup>(2)</sup>		0.028"
1992 -91	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.028"

**POINTER**

2009 -08	L4-1.8L	GCO-RC8VTYC4 <sup>(2)</sup>		0.040"
2007 -06	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.040"
2005 -98	L4-1.8L	GCO-N7BYC		0.040"
2002 -00	L4-2.0L	GCO-N7BYC		0.040"

**POINTER TRUCK**

2007 -06	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.040"
2005 -98	L4-1.8L	GCO-N7BYC		0.040"

**POLO**

2007 -03	L4-1.6L	GCO-RC8VTYC4 <sup>(2)</sup>		0.04"
2007	L4-2.0L	GCO-RC8VTYC4 <sup>(2)</sup>		0.04"
2006 -03	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.033"

**ROUTAN**

2009	V6-3.8L	GCO-RE14MCC4		0.05"
------	---------	--------------	--	-------

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

**VOLKSWAGEN (Continúa)****SAVEIRO**

2011	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.044"
------	---------	--------------------------	--	--------

**SEDAN**

2004 -91	H4-1.6L	GCO-N12YC		0.025"
----------	---------	-----------	--	--------

**SHARAN**

2008 -02	L4-1.8L Turbo	GCO-RC8VTYC4 <sup>(2)</sup>		0.032"
----------	---------------	-----------------------------	--	--------

**SPORTVAN**

2010	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040"
2009 -07	L4-1.6L	GCO-RC8VTYC4 <sup>(2)</sup>		0.040"

**TIGUAN**

2009	L4-2.0L Turbo	GCO-RC12MC4		0.04"
------	---------------	-------------	--	-------

**TOUAREG**

2014 -13	V6-3.0L Híbrido	GCO-UXF79 <sup>(3)</sup>		0.028"
2009 -08	V6-3.6L	GCO-RC12MC4		0.04"
2008 -04	V8-4.2L		GPL-3071	0.045"

**VAN**

2008	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.032"
2007 -03	L4-1.8L	GCO-RC8VTYC4 <sup>(2)</sup>		0.04"

**VENTO**

2020 -14	L4-1.6L	GCO-KC8ZMCC <sup>(1)</sup>		0.044"
----------	---------	----------------------------	--	--------

**VOLVO****C30**

2009 -08	L5-2.5L Turbo		GPL-3071	
2009	L5-2.4L		GPL-3071	

**C70**

2005 -02	L5-2.4L Turbo		GPL-3071	0.04"
----------	---------------	--	----------	-------

**S40**

2009 -04	L5-2.5L Turbo		GPL-3071	
----------	---------------	--	----------	--

**S60**

2008 -06	L5-2.4L Turbo		GPL-3071	0.04"
2005	L5-2.3L Turbo		GPL-3071	
2003 -01	L5-2.4L Turbo		GPL-3071	0.04"

**S80**

2006 -04	L6-2.9L Turbo		GPL-3071	
2003 -00	L6-2.9L		GPL-3071	

**V50**

2007 -06	L5-2.5L Turbo		GPL-3071	
----------	---------------	--	----------	--

**XC70**

2007 -04	L5-2.5L Turbo		GPL-3071	0.04"
----------	---------------	--	----------	-------

**XC90**

2007 -04	L5-2.5L Turbo		GPL-3071	0.04"
2006 -03	L6-2.9L Turbo		GPL-3071	0.04"

(1) Producto nuevo, (2) 3 Electrodo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>				
Marca Modelo	Cilindrada (cc)	Año	GONHER	Calibración



### AHM

AH110	110	2004 >	GCO-Z9Y	0.028 in
ATTILA	125	2004-2006	GCO-Z9Y	0.028 in
CITY	125	2006-2008	GCO-Z9Y	0.028 in
COMET 125	125	2005-2006	GCO-Z9Y	0.028 in
COMET 150	150	2006-2009	GCO-Z9Y	0.028 in
FORTUNE	110	2004-2009	GCO-Z9Y	0.028 in
MAGIC	50	2005 >	GCO-Z9Y	0.028 in
MAGIC	90	2010-2012	GCO-Z9Y	0.028 in
PLAY BIKE	110	2006 >	GCO-Z9Y	0.028 in
R110	110	2008-2011	GCO-Z9Y	0.028 in
RIDER 250	250	2004-2010	GCO-Z9Y	0.028 in
SHARK	125	2005 >	GCO-Z9Y	0.028 in
SPIDER	50	2006 >	GCO-Z9Y	0.028 in
SPIDER	90	2006 >	GCO-Z9Y	0.028 in
SPIDER	110	2006 >	GCO-Z9Y	0.028 in
SPIDER	200	2007-2011	GCO-Z9Y	0.028 in
SPIDER 200FA	200	2009-2012	GCO-Z9Y	0.028 in

### HONDA

AERO, GYRO, SPREE	50		GCO-Z9Y	0.024 in
AT	70		GCO-Z9Y	0.024 in
C	80		GCO-Z9Y	0.024 in
C (12MM)	90		GCO-Z9Y	0.024 in
CA	70		GCO-Z9Y	0.024 in
CA	250		GCO-Z9Y	0.024 in
CA 105 T	55		GCO-Z9Y	0.024 in
CD (10MM)	90		GCO-Z9Y	0.024 in
CD M	65		GCO-Z9Y	0.024 in
CE	75		GCO-Z9Y	0.024 in
CF	70		GCO-Z9Y	0.024 in
CF CHALY	50		GCO-Z9Y	0.024 in
CF II	70		GCO-Z9Y	0.024 in
CF III	50		GCO-Z9Y	0.024 in
CH	80		GCO-Z9Y	0.024 in
CJ	125		GCO-Z9Y	0.024 in
CL	50		GCO-Z9Y	0.024 in
CL	70		GCO-Z9Y	0.024 in
CM	125		GCO-Z9Y	0.024 in
CMX250C	250	1996-2005	GCO-Z9Y	0.028 in
REBEL				
CR III	70		GCO-Z9Y	0.024 in
CR L, LA	50		GCO-Z9Y	0.024 in
CS	50		GCO-Z9Y	0.024 in
CS	70		GCO-Z9Y	0.024 in
CT	50		GCO-Z9Y	0.024 in
CY	50	1980-1985	GCO-Z9Y	0.024 in
LS	70		GCO-Z9Y	0.024 in
MD	70		GCO-Z9Y	0.024 in
MD	90		GCO-Z9Y	0.024 in
MINI	70		GCO-Z9Y	0.024 in
P L	50		GCO-Z9Y	0.024 in
PF	50		GCO-Z9Y	0.024 in
PS	50		GCO-Z9Y	0.024 in
QA	50		GCO-Z9Y	0.024 in
S ROLLER	50		GCO-Z9Y	0.024 in
SL	70		GCO-Z9Y	0.024 in
SS M	50		GCO-Z9Y	0.024 in
ROLLER				

<b>GONHER</b>				
Marca Modelo	Cilindrada (cc)	Año	GONHER	Calibración



### HONDA (Continuación)


SS V, ZK2 ROLLER	50		GCO-Z9Y	0.024 in
T	250		GCO-Z9Y	0.024 in
TL	50		GCO-Z9Y	0.024 in
TRAIL	70		GCO-Z9Y	0.024 in
TRAIL	70		GCO-Z9Y	0.024 in
XE	50		GCO-Z9Y	0.024 in
XE	75		GCO-Z9Y	0.024 in
XE II	50		GCO-Z9Y	0.024 in
XL	70		GCO-Z9Y	0.024 in
XL	75		GCO-Z9Y	0.024 in
XL (S M 10 MM)	100		GCO-Z9Y	0.024 in
XL K	75		GCO-Z9Y	0.024 in
XL S	80		GCO-Z9Y	0.024 in
XR K	75		GCO-Z9Y	0.024 in
YR	75		GCO-Z9Y	0.024 in

### ISLO

ATC70	70	1973-1981	GCO-Z9Y	0.024 in
HERO 100	100	2002-2003	GCO-Z9Y	0.028 in
TRX90EX	90	2008 >	GCO-Z9Y	0.028 in

### ITALIKA

ARGENTA (AT-110)	110	2005-2014	GCO-Z9Y	0.028 in
AT110	110	2011-2014	GCO-Z9Y	0.028 in
AT110	110	2011-2012	GCO-Z9Y	0.028 in
SPORT				
ATV150	150	2006-2011	GCO-Z9Y	0.028 in
ATV150	150	2013-2014	GCO-Z9Y	0.028 in
CON REVERSA				
ATV150	150	2011-2012	GCO-Z9Y	0.028 in
SPORT				
CITY	125	2007-2009	GCO-Z9Y	0.028 in
CS-125				
CS125	125	2010-2014	GCO-Z9Y	0.028 in
DIABOLO-125	125	2007-2009	GCO-Z9Y	0.028 in
DIABOLO-150	150	2007-2009	GCO-Z9Y	0.028 in
DS125	125	2005-2009	GCO-Z9Y	0.028 in
DS150	150	2013-2014	GCO-Z9Y	0.028 in
FT110	110	2010-2014	GCO-Z9Y	0.028 in
GS150	150	2013-2014	GCO-Z9Y	0.028 in
LEDS				
GTS175	175	2010-2014	GCO-Z9Y	0.028 in
JUMBO	110	2007 >	GCO-Z9Y	0.024 in
PS90	90	2010-2014	GCO-Z9Y	0.028 in
ST170	170	2005-2008	GCO-Z9Y	0.028 in
STRADA (ST-70)	70	2007-2009	GCO-Z9Y	0.028 in
STRADA (ST-90)	90	2009-2014	GCO-Z9Y	0.028 in
TS-170	170	2009 >	GCO-Z9Y	0.028 in
VENDETTA VS-90	90	2007-2009	GCO-Z9Y	0.028 in
VS90	90	2006-2008	GCO-Z9Y	0.028 in
WS-150	150	2008-2009	GCO-Z9Y	0.028 in
WS175	175	2012-2014	GCO-Z9Y	0.028 in
XS125	125	2010-2014	GCO-Z9Y	0.028 in
XS150	150	2010-2012	GCO-Z9Y	0.028 in

<b>GONHER</b>				
Marca Modelo	Cilindrada (cc)	Año	GONHER	Calibración

**KAWASAKI**

4S-100	100	1993-1995	GCO-Z9Y	0.028 in
AN	80		GCO-Z9Y	0.028 in
AN090 (NEOMAX)	100	1995 >	GCO-Z9Y	0.028 in
AN110 (KAZE-R)	110	2000-2002	GCO-Z9Y	0.028 in
AN90 (NEOMAX, MAX II)	90	1998-1999	GCO-Z9Y	0.028 in
AX1	90		GCO-Z9Y	0.024 in
KAZE	110	1995 >	GCO-Z9Y	0.024 in
KLT	110		GCO-Z9Y	0.024 in
KLT	160		GCO-Z9Y	0.024 in
KLX110	110	2008-2009	GCO-Z9Y	0.028 in
KZE	110	1995 >	GCO-Z9Y	0.024 in
MOJAVE	110		GCO-Z9Y	0.024 in
NINJA 250R	250	2008-2010	GCO-Z9Y	0.020 in

**KYMCO**

CALYPSO 125	125	1997 >	GCO-Z9Y	0.020 in
PEOPLE	125	1999 >	GCO-Z9Y	0.024 in

**MOTO GUZZI**

V35 IMOLA II	350	1979-1986	GCO-Z9Y	0.020 in
V50 MONZA II	500	1984-1987	GCO-Z9Y	0.024 in
V65 LARIO	650		GCO-Z9Y	0.024 in
V75 DUNA	750		GCO-Z9Y	0.024 in

**SUZUKI**


FD110	110	2005 >	GCO-Z9Y	0.032 in
FD110CK4	110	2004 >	GCO-Z9Y	0.032 in
FK110SD (SMASH)	110	2008 >	GCO-Z9Y	0.032 in

**SYM**

F1-125	125	2010 >	GCO-Z9Y	0.028 in
JET 125	125	2010 >	GCO-Z9Y	0.028 in
MOVING 125	125	2010 >	GCO-Z9Y	0.028 in
RS-21 125	125	2005 >	GCO-Z9Y	0.028 in

**VENTO**

COLT 250	250	2009 >	GCO-Z9Y	0.028 in
FIRENZE	125	2005 >	GCO-Z9Y	0.028 in
PHANTON	150	2005-2006	GCO-Z9Y	0.028 in
REBELLIAN 250	250	2008 >	GCO-Z9Y	0.028 in
V-THUNDER 300	300	2009 >	GCO-Z9Y	0.028 in

<b>GONHER</b>				
Marca Modelo	Cilindrada (cc)	Año	GONHER	Calibración

**YAMAHA**

BELUGA XC125	125	1997 >	GCO-Z9Y	0.020 in
JOG 100	100	2009 >	GCO-Z9Y	0.028 in
T 105 (CRYPTON)	105	1999-2008	GCO-Z9Y	0.028 in
T 50	50		GCO-Z9Y	0.028 in
XC 125D	125	1986-1993	GCO-Z9Y	0.028 in
XV 250 V-STAR	250	2009 >	GCO-Z9Y	0.028 in
XV VIRAGO V TWIN	125	1997 >	GCO-Z9Y	0.024 in
YFM 100	100		GCO-Z9Y	0.024 in
YFM 80	80	1985-2004	GCO-Z9Y	0.028 in
YFM 80R	80	2002 >	GCO-Z9Y	0.028 in
YFM E, F	80	1993 >	GCO-Z9Y	0.024 in

<b>AC DELCO</b>	<b>GONHER</b>
44XLS	GCO-N12YC
FR1LS	GCO-RC9YC
FR2LS	GCO-RC12YC
R42LTS	GCO-BN12Y
R43TS	GCO-BL15Y
R43XLS	GCO-RN12YC
S102F	GCO-Z9Y
<b>AUTOLITE</b>	<b>GONHER</b>
106	GCO-BN14Y
2544	GCO-RS14LC
2545	GCO-RS14LC
2546	GCO-RS14LC
26	GCO-BL15Y
275	GCO-L92Y
3923	GCO-RC10YC4
3923	GCO-RC9YC
3924	GCO-RC12YC
3924	GCO-RC9YC
4194	GCO-Z9Y
4253	GCO-RN9YC
4263	GCO-RN9YC
5224	GCO-RC12MC4
5224	GCO-RC9MC4
5263	GCO-RE14MCC4
55	GCO-N12YC
64	GCO-N7BYC
65	GCO-RN12YC
66	GCO-RN12YC
747	GCO-F11Y
765	GCO-BN12Y
APP5344	GCO-RES9YCC4
<b>BERU</b>	<b>GONHER</b>
12VR-8 SE	GCO-REA8MCX
14F-8LUR	GCO-RC10YC4
14FR-6 DPUX02	GCO-RC10YC4
14FR-7LUX	GCO-RC9MC4
UX 79	GCO-UXF79
UXF 79	GCO-UXF79
UXK-79	GCO-RS9YCC
Z 1	GCO-N12YC
Z 117	GCO-RS14LC
Z 118	GCO-L92Y
Z 15	GCO-RC9YC
Z 174	GCO-BL15Y
Z 199	GCO-Z9Y
Z 2	GCO-N7BYC
Z 20	GCO-RN9YC
Z 209	GCO-RS9YCC
Z 216	GCO-RE14MCC4
Z 73	GCO-RC12YC
Z 76	GCO-N14Y
Z 90	GCO-RC8VTYC4
Z175 18K-9BU	GCO-F11Y
Z177 14KR-8MUV	GCO-RES9YCC4
Z183 14FR-8MU2	GCO-REC10YC4
Z299 14FR-7LUX0	GCO-RC12MC4
Z358	GCO-RA7YC

<b>BERU</b>	<b>GONHER</b>
Z6 14K-8DU	GCO-BN12Y
Z74 14FR-8LDU0X4	GCO-RC9BMC
Z8 14R-8DU	GCO-RN12YC
Z80 14K-9DU	GCO-BN14Y
<b>BOSCH</b>	<b>GONHER</b>
F7LTCR	GCO-RC8VTYC4
FR7DC	GCO-RC9YC
FR7LCX	GCO-RC9MC4
FR8DCX	GCO-RC10YC4
FR8DCX	GCO-RC12YC
FR8LDC	GCO-RC10YC4
FR8MC9	GCO-REC10YC4
FR9HC	GCO-RC12MC4
HR7DCX	GCO-RS9YCC
HR8MEV	GCO-RES9YCC4
UR3AS	GCO-Z9Y
VR8SE	GCO-REA8MCX
WR8DP	GCO-N12YC
WR9DC	GCO-RN12YC
YR7DC	GCO-RA7YC
YR7DE	GCO-RA7YC
<b>CHAMPION</b>	<b>GONHER</b>
BL15Y	GCO-BL15Y
BN12Y	GCO-BN12Y
BN14Y	GCO-BN14Y
F11Y	GCO-F11Y
L92Y	GCO-L92Y
N12YC	GCO-N12YC
N12YC	GCO-UX79
N14Y	GCO-N14Y
N7BYC	GCO-N7BYC
RA7YC	GCO-RA7YC
RC10YC4	GCO-RC10YC4
RC12MC4	GCO-RC12MC4
RC12YC	GCO-RC12YC
RC12YC	GCO-UXF79
RC87YCL	GCO-UXF79
RC8VTYC4	GCO-RC8VTYC4
RC8VTYC4	GCO-UXF79
RC9BMC	GCO-RC9BMC
RC9MC4	GCO-RC9MC4
RC9YC	GCO-RC9YC
RE14MCC4	GCO-RE14MCC4
REA8MCX	GCO-REA8MCX
REC10YC4	GCO-REC10YC4
RES9YCC4	GCO-RES9YCC4
RN12YC	GCO-RN12YC
RN9YC	GCO-RN9YC
RN9YC	GCO-UX79
RS14LC	GCO-RS14LC
RS9YCC	GCO-RS9YCC
Z9Y	GCO-Z9Y
<b>DENSO</b>	<b>GONHER</b>
K16PR- U11	GCO-RC10YC4
K20PBR-S10	GCO-RC8VTYC4
KJ16CR-L11	GCO-RC12MC4

<b>DENSO</b>	<b>GONHER</b>
KJ20CR-L11	GCO-RC9MC4
MA16P-U	GCO-F11Y
PT16VR-13	GCO-RES9YCC4
Q16PR-U11	GCO-RC12YC
Q20PR-U	GCO-RC9YC
Q20PR-U11	GCO-RC10YC4
T16EPR-U	GCO-BN12Y
T16NR-U11	GCO-RS14LC
T16P-U	GCO-BL15Y
T20EPR-U	GCO-RS9YCC
U22FSU	GCO-Z9Y
W16EPR-U	GCO-RN12YC
W16EP-U	GCO-N12YC
W16EP-U	GCO-N14Y
W20EPR-U	GCO-RN9YC
XE20HR-U9	GCO-REA8MCX
XU22EPR-U	GCO-RA7YC
<b>MOTOCRAFT</b>	<b>GONHER</b>
AF52C	GCO-BL15Y
AGRF22PP1	GCO-RES9YCC4
AGSP52C	GCO-RC12YC
ASF22C	GCO-BL15Y
ASF32C	GCO-BL15Y
ASF52C	GCO-BL15Y
BSF82C	GCO-F11Y
MAE42C	GCO-L92Y
MAG42C	GCO-N14Y
MAG52C	GCO-N14Y
MAGS32C	GCO-N12YC
MAGS52C	GCO-BN14Y
MAGS52C	GCO-RN12YC
MAGS54C	GCO-BN14Y
MAGSF52C	GCO-BN12Y
MAGSP32C	GCO-RC9YC
MBF82C	GCO-F11Y
<b>NGK</b>	<b>GONHER</b>
AP4FS	GCO-F11Y
APR4FS	GCO-F11Y
BKR5E-11	GCO-RC12YC
BKR5E-11	GCO-UXF79
BKR5EK	GCO-RC9BMC
BKR5EKU	GCO-RC9BMC
BKR6E	GCO-RC9YC
BKR6ES	GCO-RC9YC
BKUR6ET-10	GCO-RC8VTYC4
BKUR6ET-10	GCO-UXF79
BKUR6ET-11	GCO-RC8VTYC4
BP4EFS	GCO-BN14Y
BP4ES	GCO-N14Y
BP-4FS	GCO-BL15Y
BP5EFS	GCO-BN12Y
BP5ES	GCO-N12YC
BP5ES-A	GCO-N12YC
BP5ES-A	GCO-UX79
BP5HS	GCO-L92Y
BP6ET	GCO-N7BYC
BPR4EFS	GCO-BN14Y

<b>NGK</b>	<b>GONHER</b>
BPR5EFS	GCO-BN12Y
BPR5ES-A	GCO-RN12YC
BPR6E-11	GCO-RC10YC4
BPR6EFS	GCO-RS9YCC
BPR6ES	GCO-RN9YC
BPR6EY	GCO-RN9YC
BPR6EY	GCO-UX79
C7HSA	GCO-Z9Y
DCPR7E	GCO-RA7YC
LFR5A-11	GCO-REC10YC4
LZKAR7A	GCO-REA8MCX
LZTR4A-11	GCO-RE14MCC4
TR4	GCO-BN12Y
TR5-1	GCO-RS14LC
TR55	GCO-RS14LC
TR5B-13	GCO-RES9YCC4
WR4-1	GCO-F11Y
ZFR5F	GCO-RC10YC4
ZFR5F11	GCO-RC9MC4
ZFR5F-11	GCO-RC12MC4
ZFR6K-11	GCO-RC12MC4

**PLATINO**

<b>AUTOLITE</b>	<b>GONHER</b>
AP3923	GPL-3071
AP3924	GPL-3071
AP605	GPL-3013
APP5344	GPL-7437
<b>BERU</b>	<b>GONHER</b>
Z 400	GPL-3071
Z 402	GPL-3013
Z97 14KR-6MPX	GPL-7437
<b>BOSCH</b>	<b>GONHER</b>
FR8DPX	GPL-3071
HR8DPX	GPL-3013
<b>CHAMPION</b>	<b>GONHER</b>
3013	GPL-3013
3071	GPL-3071
7437	GPL-7437
9407	GPL-9407
<b>DENSO</b>	<b>GONHER</b>
IT16	GPL-3013
<b>MOTOCRAFT</b>	<b>GONHER</b>
AZFS32FE	GPL-7437
MAWSF32P	GPL-3013
MAZFS22FE	GPL-7437
<b>NGK</b>	<b>GONHER</b>
BKR6EVX-11	GPL-3071
ILZKR7B11	GPL-9407
PTR5A-13	GPL-7437
PTR5A-15	GPL-7437

**GONHER**

# ESPECIFICACIONES DE BUJÍAS

GONHER	ROSCA	ASIENTO	RESISTENCIA	ALCANCE DE ROSCA	HEXÁGONO	TIPO	CANTIDAD DE ELECTRODOS	GAP
GCO-BL15Y	M14X1.25	CONICO	SI	11.2 mm	16 mm	COBRE	1	1.1 mm
GCO-BN12Y	M14X1.25	CONICO	NO	17.25 mm	16 mm	COBRE	1	1.1 mm
GCO-BN14Y	M14X1.25	CONICO	NO	17.25 mm	16 mm	COBRE	1	1.1 mm
GCO-F11Y	M18X1.5	CONICO	NO	13.6 mm	20.8 mm	COBRE	1	1.1 mm
GCO-L92Y	M14X1.25	PLANO	NO	12.7 mm	20.8 mm	COBRE	1	0.7 mm
GCO-N12YC	M14X1.25	PLANO	NO	19 mm	20.8 mm	COBRE	1	0.7 mm
GCO-N14Y	M14X1.25	PLANO	NO	19 mm	20.8 mm	COBRE	1	0.8 mm
GCO-N7BYC	M14X1.25	PLANO	NO	19 mm	20.8 mm	COBRE	3	1.0 mm
GCO-RC12MC4	M14X1.25	PLANO	NO	19 mm	16 mm	COBRE	1	1.0 mm
GCO-RC12YC	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	1	1.1 mm
GCO-RC8VTYC4	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	3	1.0 mm
GCO-RC9BMC	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	2	1.0 mm
GCO-RC9YC	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	1	0.9 mm
GCO-RE14MCC4	M14X1.25	CONICO	SI	25 mm	16 mm	COBRE	1	1.0 mm
GCO-REC10YC4	M14X1.25	PLANO	SI	26.5 mm	16 mm	COBRE	1	1.1 mm
GCO-RES9YCC4	M14X1.25	CONICO	SI	25 mm	16 mm	COBRE	1	1.1 mm
GCO-RN12YC	M14X1.25	PLANO	SI	19 mm	20.8 mm	COBRE	1	0.7 mm
GCO-RN9YC	M14X1.25	PLANO	SI	19 mm	20.8 mm	COBRE	1	0.8 mm
GCO-RS14LC	M14X1.25	CONICO	SI	17 mm	16 mm	COBRE	1	1.1 mm
GCO-RS9YCC	M14X1.25	CONICO	SI	17.5 mm	16 mm	COBRE	1	1.1 mm
GCO-UX79	M14X1.25	PLANO	SI	19 mm	20.8 mm	COBRE	4	1.1 mm
GCO-UXF79	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	4	1.1 mm
GCO-Z9Y	M10X1.0	PLANO	NO	12.7 mm	16 mm	COBRE	1	0.7 mm
GPL-3013	M14X1.25	CONICO	SI	17.25 mm	16 mm	PLATINO	1	1.1 mm
GPL-3071	M14X1.25	PLANO	SI	19 mm	16 mm	PLATINO	1	0.7 mm
GPL-7437	M14X1.25	CONICO	SI	25 mm	16 mm	PLATINO	1	1.3 mm

# GARANTÍA

Para nosotros la satisfacción del cliente es el objetivo principal. Por ello, en todos nuestros productos ofrecemos garantías de fabricación. Cuando se utilicen las **Bujías GONHER, Gonhermex, S.A. de C.V.**, garantiza sus productos contra cualquier defecto de fabricación durante un período de 1 año para bujías de cobre y 2 años para bujías de platino a partir de su compra.

En el caso de daño al motor atribuible en forma directa a falla de una bujía **GONHER** que ha sido instalada en forma correcta, **Gonhermex, S.A. de C.V.**, pagará la reparación a una condición equivalente a la que exista antes de la falla. El daño deberá ser comprobado por un técnico autorizado por **Gonhermex, S.A. de C.V.**, antes de cualquier reparación.

**Gonhermex, S.A. de C.V.**, no es responsable por cualquier otro daño o perjuicio ni cuando las bujías hayan sido utilizadas en condiciones distintas a las normales y no cubre pérdidas causadas por una instalación incorrecta, errores en la aplicación o modificaciones del producto.

Esta garantía podrá hacerse válida en **Gonhermex, S.A. de C.V.**, o cualquiera de los distribuidores autorizados.

GONHERMEX, S.A. DE C.V.  
Av. Manuel Ordoñez No. 600 C.P. 66350  
Santa Catarina, N.L., México  
Tel: (81) 8153-31-00



# GONHER®

AUTOPARTES



DESCARGA NUESTRA APP



gonher.com.mx