

# GONHER<sup>®</sup>

AUTOPARTES

CATÁLOGO 2023

BUJÍAS



<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## ACURA

### MDX

2020-14	V6-3.5L		GPL-9407	0.044 IN
2006-05	V6-3.5L	GCO-UXF79 <sup>(3)</sup> GCO-RC12MC4		0.044 IN

### RL

2011 -09	V6-3.7L	GCO-UXF79 <sup>(3)</sup>		
----------	---------	--------------------------	--	--

### TLX

2020-15	V6-3.5L		GPL-9407	0.044 IN
---------	---------	--	----------	----------

## ALFA ROMEO

### 166

2003-02	V6-3.0L		GPL-3071	0.045 IN
---------	---------	--	----------	----------

### GT

2008-07	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		
---------	---------	--------------------------	--	--

### GTV

2003	V6-3.0L		GPL-3071	0.045 IN
------	---------	--	----------	----------

### SPIDER

2003	V6-3.0L		GPL-3071	0.045 IN
------	---------	--	----------	----------

## AUDI

### A1

2011	L4-1.4L Turbo		GPL-3071	0.035 IN
------	---------------	--	----------	----------

### A3

2008	L4-1.4L Turbo	GCO-RC9YC		0.028 IN
2004	L4-1.8L Turbo	GCO-REC10YC4		0.032 IN
2004	L4-2.0L	GCO-RC9YC		0.032 IN
2004	L4-2.0L	GCO-REC10YC4		0.032 IN
2003-98	L4-1.8L Turbo	GCO-RC12MC4		0.04 IN

### A3 QUATTRO

2004	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
------	---------------	-----------	--	----------

### A4

2006-02	L4-1.8L Turbo	GCO-RC12MC4		0.04 IN
2006	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
2001-98	L4-1.8L Turbo	GCO-RC8VTYC4 <sup>(2)</sup>		0.04 IN
1997	V6-2.8L	GCO-RC8VTYC4 <sup>(2)</sup>		0.04 IN

### A4 QUATTRO

2005	V6-3.2L	GCO-RC9YC		
------	---------	-----------	--	--

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## AUDI (Continúa)

### A5

2011	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
------	---------------	-----------	--	----------

### A5 QUATTRO

2011	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
------	---------------	-----------	--	----------

### A6

2001-98	V6-2.8L	GCO-RC12MC4		0.04 IN
---------	---------	-------------	--	---------

### A6 QUATTRO

2002	V6-3.0L	GCO-RC12YC		0.032 IN
------	---------	------------	--	----------

### A7 QUATTRO

2012	V6-3.0L	GCO-RC12YC		0.032 IN
------	---------	------------	--	----------

### A8

2000	V8-3.7L	GCO-UXF79 <sup>(3)</sup>		
------	---------	--------------------------	--	--

### A8 QUATTRO

2013	V6-3.0L	GCO-RC12YC		0.032 IN
1997	V8-4.2L	GCO-RC12YC		0.032 IN

### ALLROAD QUATTRO

2004-01	V6-2.7L Turbo	GCO-UXF79 <sup>(3)</sup>		
---------	---------------	--------------------------	--	--

### CABRIOLET

1998 -97	V6-2.8L	GCO-RC8VTYC4 <sup>(2)</sup>		
----------	---------	-----------------------------	--	--

### Q3

2013	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
------	---------------	-----------	--	----------

### Q3 QUATTRO

2017	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
------	---------------	-----------	--	----------

### Q5

2010	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
------	---------------	-----------	--	----------

### Q7

2018 -17	V6-3.0L	GCO-UXF79 <sup>(3)</sup>		
2015 -12	V6-3.0L	GCO-UXF79 <sup>(3)</sup>		
2009-07	V8-4.2L		GPL-3071	0.045 IN
2007	V6-3.6L	GCO-RC12MC4		0.04 IN

### S3

2004-00	L4-1.8L Turbo		GPL-3071	0.045 IN
---------	---------------	--	----------	----------

### S4

2016 -12	V6-3.0L	GCO-UXF79 <sup>(3)</sup>		
2010	V6-3.0L	GCO-RC12YC		
2008-04	V8-4.2L		GPL-3071	0.065 IN

BUJÍAS

ACURA

(2) 3 Electrodo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		COBRE	PLATINO	CLBR
AÑO	MOTOR			

**AUDI (Continúa)****S4 (Continúa)**

2000	V6-2.7L Turbo		GPL-3071	0.045 IN
------	---------------	--	----------	----------

**S5**

2009-08	V8-4.2L		GPL-3071	0.045 IN
---------	---------	--	----------	----------

**S6**

2009-07	V10 5.2L		GPL-3071	0.045 IN
2004-01	V8-4.2L	GCO-UXF79 <sup>(3)</sup>		

**S8**

2009-07	V10 5.2L		GPL-3071	0.045 IN
2002-01	V8-4.2L	GCO-UXF79 <sup>(3)</sup>		

**SQ5**

2014	V6-3.0L	GCO-RC12YC		0.032 IN
------	---------	------------	--	----------

**TT**

2009-07	L4-2.0L Turbo		GPL-3071	0.045 IN
2006-99	L4-1.8L Turbo		GPL-3071	0.045 IN

**BAIC****BJ40**

2022	L4-2.3L Turbo	GCO-RC10YC4		0.032 IN
2018	L4-2.3L Turbo	GCO-RC10YC4		0.032 IN

**D20**

2020	L4-1.5L	GCO-RN12YC		
2018-17	L4-1.5L	GCO-RN12YC		

**X25**

2020-17	L4-1.5L	GCO-RN12YC		
---------	---------	------------	--	--

**X65**

2020-18	L4-2.0L Turbo	GCO-RC10YC4		0.032 IN
---------	---------------	-------------	--	----------

**BENTLEY****CONTINENTAL**

2007	W12 6.0L Turbo	GCO-RC9YC		0.032 IN
------	----------------	-----------	--	----------

**BMW****125I**

2012-08	L6-3.0L	GCO-REC10YC4		0.044 In
---------	---------	--------------	--	----------

**760LI**

2006	V12 6.0L		GPL-3071	
------	----------	--	----------	--

(3) 4 Electrodos

<b>GONHER</b>		COBRE	PLATINO	CLBR
AÑO	MOTOR			

**BMW (Continúa)****X3**

2012-11	L6-3.0L Turbo	GCO-UXF79 <sup>(3)</sup>		
2012-04	L6-3.0L	GCO-UXF79 <sup>(3)</sup>		
2007-04	L6-2.5L	GCO-UXF79 <sup>(3)</sup>		

**X5**

2011-01	L6-3.0L	GCO-UXF79 <sup>(3)</sup>		
2011	L6-3.0L Turbo	GCO-UXF79 <sup>(3)</sup>		
2009-05	V8-4.8L	GCO-RC12MC4		0.04 IN
2006-02	V8-4.4L	GCO-UXF79 <sup>(3)</sup>		
2000	V8-4.4L	GCO-UXF79 <sup>(3)</sup>		

**X6**

2010-09	L6-3.0L	GCO-UXF79 <sup>(3)</sup>		
2010-09	V8-4.4L Turbo	GCO-UXF79 <sup>(3)</sup>		
2009	L6-3.0L Turbo	GCO-UXF79 <sup>(3)</sup>		

**Z4**

2011	L6-3.0L	GCO-REC10YC4		0.020 In
2010-07	L6-2.5L	GCO-REC10YC4		0.044 In
2009-07	L6-3.0L	GCO-REC10YC4		0.044 In
2005-03	L6-2.5L	GCO-UXF79 <sup>(3)</sup>		

**Z8**

2003-01	V8-4.9L	GCO-UXF79 <sup>(3)</sup>		
---------	---------	--------------------------	--	--

**BUICK****CENTURY**

2005-89	V6-3.1L	GCO-RES9YCC4		0.06 IN
1988-84	V6-2.8L	GCO-BL15Y		0.044 IN

**ENCLAVE**

2016-10	V6-3.6L		GPL-7437	0.044 In
---------	---------	--	----------	----------

**LACROSSE**

2013-10	V6-3.6L		GPL-7437	0.044 In
---------	---------	--	----------	----------

**LESABRE**

2000-97	V6-3.8L		GPL-3013	0.060 In
1995-93	V6-3.8L		GPL-3013	0.060 In

**PARK AVENUE**

1996-93	V6-3.8L		GPL-3013	0.060 In
---------	---------	--	----------	----------

**REGAL**

2004-93	V6-3.8L	GCO-RES9YCC4		0.06 IN
---------	---------	--------------	--	---------

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## BUICK (Continúa)

### RENDEZVOUS

2007-06	V6-3.5L		GPL-3013	0.060 In
---------	---------	--	----------	-------------

### ROADMASTER

1996-94	V8-5.7L		GPL-3013	0.060 In
---------	---------	--	----------	-------------

### SKYLARK

1998-96	V6-3.1L		GPL-3013	0.060 In
1997-96	L4-2.4L		GPL-3013	0.060 In
1995	L4-2.3L		GPL-3013	0.060 In
1993	V6-3.3L		GPL-3013	0.060 In

### TERRAZA

2005	V6-3.5L		GPL-3013	0.060 In
------	---------	--	----------	-------------

## CADILLAC

### ALLANTE

1993	V8-4.6L		GPL-3013	0.060 In
------	---------	--	----------	-------------

### ATS

2013	L4-2.0L Turbo		GPL-7437	0.044 In
------	------------------	--	----------	-------------

### CATERA

2001-99	V6-3.0L	GCO-UXF79 <sup>(3)</sup> , GCO-RC12YC	GPL-3071	0.040 In
1998-97	V6-3.0L	GCO-UXF79 <sup>(3)</sup>		

### CTS

2011-10	V6-3.6L	GCO-UXF79 <sup>(3)</sup>		
2009-08	V6-3.6L	GCO-RC9BMC		0.044 IN
2007-04	V6-3.6L	GCO-UXF79 <sup>(3)</sup>		
2004-03	V6-3.2L	GCO-RC9BMC		0.044 IN

### DEVILLE

2005	V8-4.6L	GCO-RES9YCC4		0.052 IN
2004-02	V8-4.6L	GCO-RS9YCC		0.052 IN
2001-97	V8-4.6L		GPL-3013	0.05 IN
1996	V8-4.6L	GCO-RS9YCC		
1995-94	V8-4.6L	GCO-RES9YCC4		0.052 IN
1995-92	V8-4.9L	GCO-RS9YCC		
1991	V8-4.9L		GPL-3013	0.06 IN

### ELDORADO

2002-93	V8-4.6L	GCO-RES9YCC4		0.052 IN
---------	---------	--------------	--	-------------

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## CADILLAC (Continúa)

### ESCALADE

2009-07	V8-6.2L		GPL-7437	0.052 IN
2009	V8-6.0L Híbrido		GPL-7437	0.052 IN
2006-02	V8-6.0L		GPL-7437	0.052 IN

### FLEETWOOD

1996-93	V8-5.7L		GPL-3013	0.050 In
---------	---------	--	----------	-------------

### SEVILLE

2004-03	V8-4.6L	GCO-RS9YCC		0.052 IN
2002-01	V8-4.6L	GCO-RES9YCC4		0.052 IN
2000	V8-4.6L		GPL-3013	0.05 IN
1999-93	V8-4.6L	GCO-RES9YCC4		0.052 IN

### SRX

2007-04	V8-4.6L		GPL-3013	0.04 IN
2006-04	V6-3.6L		GPL-7437	0.052 IN

### STS

2009-07	V6-3.6L		GPL-7437	0.052 IN
2009-07	V8-4.6L		GPL-7437	0.052 IN
2006-05	V8-4.6L		GPL-3013	0.05 IN

### XLR

2009	V8-4.6L		GPL-3013	0.04 IN
2007-04	V8-4.6L		GPL-3013	0.04 IN

## CHEVROLET

### ASTRA

2008-06	L4-1.8L	GCO-RC9BMC		0.044 IN
2008	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.035 IN
2008	L4-2.0L Turbo	GCO-UXF79 <sup>(3)</sup>		0.035 IN
2007-06	L4-2.0L Turbo	GCO-RN9YC		0.04 IN
2006-04	L4-2.0L	GCO-RN9YC		0.04 IN
2006-04	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.035 IN
2003-00	L4-1.8L	GCO-RC9BMC		0.044 IN

### AVALANCHE

2009-07	V8-5.3L	GCO-RS9YCC		0.06 IN
---------	---------	------------	--	---------

### AVEO

2012	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.035 IN
2011-09	L4-1.6L	GCO-UXF79 <sup>(3)</sup> , GCO-RC9MC4		0.035 IN

BUJÍAS

BUICK

(3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

**CHEVROLET (Continúa)****AVEO (Continúa)**

2008	L4-1.6L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.035 IN, 0.044 IN
------	---------	---	--	-----------------------------

**BEAT**

2021	L4-1.2L	GCO-RA7YC		0.040 In
2020-18	L4-1.2L	GCO-RA7YC		0.040 In

**BLAZER**

2005-02	V6-4.3L	GCO-BL15Y		0.045 IN
2001-98	V6-4.3L	GCO-RES9YCC4		0.06 IN
1997-96	V6-4.3L		GPL-3013	0.06 IN
1995	V6-4.3L	GCO-BL15Y		0.045 IN

**C10**

1981-80	L6-4.1L	GCO-N14Y		
1981-80	L6-4.8L	GCO-N14Y		
1981-80	V8-5.7L	GCO-N14Y		

**C20**

1986	V8-5.7L	GCO-N14Y		
------	---------	----------	--	--

**C2500**

2000-96	V8-5.7L		GPL-3013	0.050 In
---------	---------	--	----------	-------------

**C2500 SUBURBAN**

1999-96	V8-5.7L		GPL-3013	0.060 In
---------	---------	--	----------	-------------

**C30**

1982-80	L6-4.1L	GCO-N14Y		
1982-80	L6-4.8L	GCO-N14Y		
1982-80	V8-5.7L	GCO-N14Y		

**CAMARO**

2014-10	V6-3.6L		GPL-7437	0.044 In
2013	V8-6.2L	GCO-RS14LC		0.040 In
2002-96	V8-5.7L	GCO-RS9YCC		0.040 IN
2002-95	V6-3.8L	GCO-RES9YCC4		0.06 IN
1995-93	V8-5.7L		GPL-3013	0.060 In

**CAPRICE**

1996-93	V8-5.7L	GCO-BL15Y		0.035 IN
1982-79	V8-5.7L	GCO-BL15Y		0.035 IN

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

**CHEVROLET (Continúa)****CAVALIER**

2005	L4-2.2L	GCO-RES9YCC4		0.045 IN
2004-03	L4-2.2L	GCO-RS9YCC		0.06 IN
2002-99	L4-2.2L	GCO-RES9YCC4		0.045 IN
2002-97	L4-2.4L	GCO-RES9YCC4		0.050 IN
2002	L4-2.2L	GCO-RS9YCC, GCO-RES9YCC4		0.06 IN, 0.045 IN
1998	L4-2.2L	GCO-RS9YCC		0.050 IN
1997-93	L4-2.2L	GCO-RES9YCC4		0.045 IN
1996	L4-2.4L	GCO-RS9YCC		0.050 IN
1995	L4-2.4L	GCO-RES9YCC4		0.050 IN
1994-91	V6-3.1L	GCO-RES9YCC4		0.045 IN
1994-90	V6-2.8L	GCO-RES9YCC4		0.045 IN

**CELEBRITY**

1989-87	V6-2.8L	GCO-RES9YCC4		0.044 IN
1986-82	V6-2.8L	GCO-BL15Y		0.045 IN

**CHEVY**

2012-96	L4-1.6L	GCO-RN9YC		0.04 IN
2002-94	L4-1.4L	GCO-RN9YC		0.04 IN

**CHEVY MONZA**

2003	L4-1.6L	GCO-RN9YC		0.04 IN
------	---------	-----------	--	---------

**CHEVY PICKUP**

2003-99	L4-1.6L	GCO-UX79 <sup>(3)</sup>		0.035 IN
---------	---------	-------------------------	--	-------------

**CHEYENNE**

2021	V8-5.3L		GPL-7437	0.044 IN
2021	V8-6.2L		GPL-7437	0.044 IN
2020-15	V8-5.3L		GPL-7437	0.044 IN
2020-14	V8-6.2L		GPL-7437	0.044 IN
2015	V8-5.3L		GPL-7437	0.044 IN
2014	V8-5.3L		GPL-7437	0.044 IN
2014	V8-5.3L		GPL-7437	0.044 IN
2013	V8-5.3L		GPL-7437	0.044 IN
2013	V8-5.3L		GPL-7437	0.044 IN
2012	V8-5.3L		GPL-7437	0.044 IN

(3) 4 Electrodo

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## CHEVROLET

### CHEYENNE

2012	V8-5.3L		GPL-7437	0.044 IN
2011	V8-5.3L		GPL-7437	0.044 IN
2011	V8-5.3L		GPL-7437	0.044 IN
2010-07	V8-5.3L		GPL-7437	0.044 IN

### CITATION

1986-82	V6-2.8L	GCO-BL15Y		0.045 IN
---------	---------	-----------	--	----------

### COLORADO

2009-07	L5-3.7L		GPL-7437	0.06 IN
2006-04	L5-3.5L		GPL-7437	0.06 IN

### CORSA

2008-03	L4-1.8L	GCO-RN9YC		0.04 IN
2002	L4-1.4L	GCO-RN9YC		0.035 IN

### CORVETTE

2004	V8-5.7L	GCO-RS9YCC		0.06 IN
1996-92	V8-5.7L		GPL-3013	0.06 IN

### CRUZE

2011-10	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.028 IN
---------	---------	--------------------------	--	----------

### EQUINOX

2009-05	V6-3.4L	GCO-RS9YCC		0.06 IN
---------	---------	------------	--	---------

### EXPRESS CARGO

2021	V6-4.3L		GPL-7437	0.044 IN
2020-19	V6-4.3L		GPL-7437	0.044 IN
2019	V6-4.3L		GPL-7437	0.044 IN
2018	V6-4.3L		GPL-7437	0.044 IN

### IMPALA

2005-00	V6-3.8L	GCO-RS9YCC		0.06 IN
1996-95	V8-5.7L	GCO-BL15Y		0.035 IN
1975	V8-5.7L	GCO-BL15Y		0.035 IN

### K2500 SUBURBAN

1999-96	V8-5.7L		GPL-3013	0.060 In
---------	---------	--	----------	----------

### LUMINA

1999-98	V6-3.8L		GPL-3013	0.060 In
---------	---------	--	----------	----------

### LUMINA APV

1995	V6-3.8L		GPL-3013	0.060 In
------	---------	--	----------	----------

(3) 4 Electrodos

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## CHEVROLET (Continúa)

### LUV

2005-98	L4-2.2L	GCO-BL15Y		0.044 IN
1997	L4-2.3L	GCO-N7BYC		0.044 IN

### MALIBU

2009-08	L4-2.4L	GCO-RES9YCC4		0.06 IN
2009-08	L4-2.4L Híbrido	GCO-RES9YCC4		0.06 IN
2009-04	V6-3.5L	GCO-RS9YCC		0.06 IN
2008-04	L4-2.2L	GCO-RS9YCC		0.06 IN
2003-97	V6-3.1L	GCO-RES9YCC4		0.06 IN
1999-97	L4-2.4L	GCO-RES9YCC4		0.06 IN
1981-79	V8-5.7L	GCO-BL15Y		0.035 IN

### MATIZ

2014-13	L4-1.0L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2012	L4-1.0L	GCO-RN9YC, GCO-UXF79 <sup>(3)</sup>		0.044 IN
2011	L4-1.0L	GCO-UX79 <sup>(3)</sup>		0.044 IN

### MERIVA

2007-04	L4-1.8L	GCO-RN9YC		0.04 IN
---------	---------	-----------	--	---------

### MONTE CARLO

2000-98	V6-3.8L		GPL-3013	0.060 In
1984-81	V8-5.7L	GCO-BL15Y		

### NOVA

1978-77	V8-5.7L	GCO-BL15Y		0.035 IN
1978-75	L6-4.1L	GCO-BL15Y		0.035 IN

### OPTRA

2010-08	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2007-06	L4-2.0L	GCO-RC9YC		0.035 IN

### S10

2003-00	L4-2.2L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2002-01	L4-2.2L	GCO-RES9YCC4, GCO-UXF79 <sup>(3)</sup>		0.06 IN
2000	L4-2.2L	GCO-RC9BMC, GCO-UXF79 <sup>(3)</sup>		0.04 IN
1999-98	L4-2.2L	GCO-RC9BMC		0.04 IN
1997-94	L4-2.2L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
1993-91	V6-3.1L	GCO-BL15Y		0.045 IN

BUJÍAS

CHEVROLET

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		COBRE	PLATINO	CLBR
AÑO	MOTOR			

**CHEVROLET (Continúa)****SILVERADO 1500**

2015-08	V6-4.3L		GPL-3013	0.060 In
2006-03	V6-4.3L		GPL-3013	0.060 In

**SILVERADO 1500 CLASSIC**

2007	V6-4.3L		GPL-3013	0.060 In
------	---------	--	----------	----------

**SILVERADO 2500**

2002-00	V8-5.7L		GPL-3013	0.060 In
---------	---------	--	----------	----------

**SONIC**

2013-12	L4-1.6L	GCO-RC12MC4		0.035 IN
---------	---------	-------------	--	----------

**SONORA**

2006-03	V8-5.3L	GCO-RS9YCC		0.06 IN
2002-00	V8-5.7L	GCO-RS9YCC		0.06 IN

**SPARK**

2018-16	L4-1.4L	GCO-RA7YC		0.035 In
2015-12	L4-1.2L	GCO-UXF79 <sup>(3)</sup> , GCO-RA7YC		0.040 IN, 0.035 IN
2011	L4-1.2L	GCO-RN9YC, GCO-UXF79 <sup>(3)</sup> , GCO-RA7YC		0.040 IN, 0.035 IN

**SPARK CLASSIC**

2016	L4-1.2L	GCO-UXF79 <sup>(3)</sup> , GCO-RA7YC		0.040 IN, 0.035 IN
------	---------	---	--	-----------------------

**TAHOE**

2009-00	V8-5.3L	GCO-RS9YCC		0.06 IN
---------	---------	------------	--	---------

**TORNADO**

2009-04	L4-1.8L	GCO-RN9YC		0.04 IN
---------	---------	-----------	--	---------

**TRACKER**

2007-05	L4-2.0L	GCO-UX79 <sup>(3)</sup>		0.044 IN
2004-99	L4-2.0L	GCO-RN9YC		0.044 IN
2000-98	L4-1.6L	GCO-RN9YC		0.045 IN

**TRAILBLAZER**

2009-02	L6-4.2L	GCO-RS9YCC		0.044 IN
---------	---------	------------	--	----------

**TRAVERSE**

2015-09	V6-3.6L		GPL-7437	0.044 in
---------	---------	--	----------	----------

**TRAX**

2013	L4-1.8L	GCO-RC12MC4		0.035 IN
------	---------	-------------	--	----------

<b>GONHER</b>		COBRE	PLATINO	CLBR
AÑO	MOTOR			

**CHEVROLET (Continúa)****UPLANDER**

2008-06	V6-3.9L		GPL-7437	0.06 IN
2006-05	V6-3.5L		GPL-7437	0.06 IN

**VECTRA**

2005-03	V6-3.2L	GCO-UXF79 <sup>(3)</sup>		0.035 IN
---------	---------	--------------------------	--	----------

**VENTURE**

2005-97	V6-3.4L	GCO-RES9YCC4		0.06 IN
---------	---------	--------------	--	---------

**ZAFIRA**

2005	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.035 IN
2004-02	L4-1.8L	GCO-RC9BMC		0.04 IN

**CHRYSLER****200**

2015-12	L4-2.4L	GCO-RC12MC4		0.044 In
---------	---------	-------------	--	----------

**300**

2021	V6-3.6L		GPL-9407	0.044 IN
2020-12	V6-3.6L		GPL-9407	0.044 IN
2009-05	V8-5.7L	GCO-RE14MCC4		0.045 IN

**ASPEN**

2009	V8-5.7L	GCO-RE14MCC4		0.05 IN
2008-07	V8-5.7L	GCO-RE14MCC4		0.045 IN

**CIRRUS**

2009	L4-2.4L		GPL-3071	0.05 IN
2007	L4-2.4L	GCO-RE14MCC4		0.05 IN
2006-97	L4-2.4L Turbo	GCO-RE14MCC4		0.05 IN
2000-96	V6-2.5L	GCO-RC10YC4		0.044 IN
2000	L4-2.4L	GCO-RE14MCC4		0.05 IN
1997	L4-2.4L	GCO-RE14MCC4		0.05 IN
1996-95	L4-2.4L		GPL-3071	0.05 IN

**CONCORDE**

2001	V6-3.2L	GCO-UXF79 <sup>(3)</sup>		
------	---------	--------------------------	--	--

**CORDOBA**

1982-80	V8-5.9L	GCO-N12YC		0.035 In
---------	---------	-----------	--	----------

**CROSSFIRE**

2005-04	V6-3.2L	GCO-UXF79 <sup>(3)</sup>		
---------	---------	--------------------------	--	--

**GRAND VOYAGER**

2002-96	V6-3.8L	GCO-UXF79 <sup>(3)</sup>		0.050 IN
---------	---------	--------------------------	--	----------

**IMPERIAL**

1991	V6-3.3L	GCO-UX79 <sup>(3)</sup>		
------	---------	-------------------------	--	--

(3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## CHRYSLER (Continúa)

### LEBARON

1995 -92	L4-2.5L Turbo	GCO-N12YC		0.035 IN
1993	L4-2.5L	GCO-N12YC		0.035 IN
1991	L4-2.5L Turbo	GCO-UXF79 <sup>(3)</sup>		0.035 IN
1987 -84	L4-2.2L Turbo	GCO-N12YC		0.035 IN
1987 -83	L4-2.2L	GCO-N12YC		0.035 IN
1982 -79	V8-5.9L	GCO-N12YC		0.035 IN

### NEW YORKER

1994 -92	V6-3.0L	GCO-N7BYC		0.044 IN
1993 -92	L4-2.5L Turbo	GCO-N12YC		0.035 IN
1989 -85	L4-2.2L Turbo	GCO-UXF79 <sup>(3)</sup>		0.035 IN
1986 -85	L4-2.2L	GCO-UXF79 <sup>(3)</sup>		0.035 IN

### PACIFICA

2020-17	V6-3.6L		GPL-9407	0.044 IN
2020-17	V6-3.6L Híbrido		GPL-9407	0.044 IN
2008	V6-4.0L	GCO-UXF79 <sup>(3)</sup>		0.050 IN
2007	V6-3.8L	GCO-RE14MCC4		0.05 IN
2006-04	V6-3.5L	GCO-RC12MC4		0.05 IN
2005	V6-3.8L	GCO-RE14MCC4		0.05 IN

### PHANTOM

1993 -92	L4-2.2L Turbo	GCO-N12YC		0.035 IN
1990	L4-2.5L Turbo	GCO-UXF79 <sup>(3)</sup>		0.035 IN
1989 -87	L4-2.2L Turbo	GCO-N12YC		0.035 IN

### PT CRUISER

2009-01	L4-2.4L	GCO-RE14MCC4		0.05 IN
2008-03	L4-2.4L Turbo	GCO-RE14MCC4		0.05 IN

### SEBRING

2000-95	V6-2.5L	GCO-RC10YC4		0.044 IN
---------	---------	-------------	--	----------

### TOWN & COUNTRY

2014 -11	V6-3.6L		GPL-9407	0.044 IN
2007-00	V6-3.8L	GCO-RE14MCC4		0.05 IN
1999 -96	V6-3.8L	GCO-UXF79 <sup>(3)</sup>		0.050 IN

### VOYAGER

2008-00	V6-3.3L	GCO-RE14MCC4		0.05 IN
---------	---------	--------------	--	---------

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## DODGE

### ATOS

2012 -10	L4-1.1L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN
2009-05	L4-1.1L	GCO-RC12YC, GCO-RC10YC4		0.04 IN, 0.044 IN
2004-01	L4-1.0L	GCO-RC12YC		0.04 IN

### ATTITUDE

2011	L4-1.4L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2011	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2010	L4-1.4L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN
2010	L4-1.6L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN
2009-06	L4-1.4L	GCO-RC12YC, GCO-RC10YC4		0.045 IN, 0.044 IN
2009-06	L4-1.6L	GCO-RC12YC, GCO-RC10YC4		0.045 IN, 0.044 IN

### AVENGER

2009-08	L4-2.4L	GCO-RE14MCC4		0.05 IN
---------	---------	--------------	--	---------

### CALIBER

2009-08	L4-2.4L Turbo	GCO-RE14MCC4		0.05 IN
2009-07	L4-2.4L	GCO-RE14MCC4		0.05 IN

### CARAVAN

1997 -96	L4-2.4L		GPL-3071	0.050 In
1993	L4-2.5L	GCO-RN12YC		0.035 In

### CHALLENGER

2021	V6-3.6L		GPL-9407	0.044 IN
2020-11	V6-3.6L		GPL-9407	0.044 IN
2009-08	V8-6.1L	GCO-RE14MCC4		0.045 IN
2009	V8-5.7L	GCO-RE14MCC4		0.05 IN

### CHARGER

2020-11	V6-3.6L		GPL-9407	0.044 IN
2009-06	V8-6.1L	GCO-RE14MCC4		0.045 IN
2009	V8-5.7L	GCO-RE14MCC4		0.05 IN
2008-06	V8-5.7L	GCO-RE14MCC4		0.045 IN
2008	V8-5.7L	GCO-REC10YC4		0.045 IN

### D150

1993 -91	V6-3.9L	GCO-RN12YC		0.035 In
----------	---------	------------	--	----------

BUJÍAS

CHRYSLER

(3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		COBRE	PLATINO	CLBR
AÑO	MOTOR			

**DODGE (Continúa)****D250**

1993	V6-3.9L	GCO-RC12YC		0.035 In
1992-88	V8-5.9L	GCO-RN12YC		0.035 In

**D300**

1980-76	V8-5.9L	GCO-RN12YC		0.035 In
---------	---------	------------	--	-------------

**D350**

1992-81	V8-5.9L	GCO-RN12YC		0.035 In
---------	---------	------------	--	-------------

**DAKOTA**

2012-04	V6-3.7L	GCO-RC9MC4		0.035 IN
2002-93	L4-2.5L	GCO-RC12YC		0.035 IN

**DART**

1989-82	L4-2.2L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
1982-79	L6-3.7L	GCO-BL15Y		0.035 IN
1980	V8-5.2L	GCO-N12YC		0.035 IN
1978	L6-3.7L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
1977-76	L6-3.7L	GCO-N14Y		0.035 IN
1976	V8-5.9L	GCO-N12YC		0.035 IN

**DURANGO**

2015-12	V6-3.6L		GPL-9407	0.044 IN
2009	V8-5.7L	GCO-RE14MCC4		0.05 IN
2009	V8-5.7L Híbrido	GCO-RE14MCC4		0.045 IN
2008-04	V8-5.7L	GCO-RE14MCC4		0.045 IN
2003-98	V8-5.9L	GCO-RC12MC4		0.04 IN
2000-98	V8-5.2L	GCO-RC12MC4		0.04 IN

**GRAND CARAVAN**

2020-11	V6-3.6L		GPL-9407	0.044 IN
---------	---------	--	----------	-------------

**H100**

2005-03	L4-2.4L	GCO-RN9YC		0.04 IN
---------	---------	-----------	--	------------

**I10**

2014-12	L4-1.1L		GPL-3071	0.044 IN
---------	---------	--	----------	-------------

**JOURNEY**

2019-11	V6-3.6L		GPL-9407	0.044 IN
2011-10	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.035 IN
2010	L4-2.4L	GCO-RC12MC4		0.044 IN

<b>GONHER</b>		COBRE	PLATINO	CLBR
AÑO	MOTOR			

**DODGE (Continúa)****JOURNEY (Continúa)**

2009	L4-2.4L	GCO-RC9MC4		0.045 IN
------	---------	------------	--	-------------

**MONACO**

1977-75	V8-5.2L	GCO-N12YC		0.035 IN
1970-69	V8-5.2L	GCO-N12YC		0.035 IN

**NEON**

2005-03	L4-2.4L Turbo	GCO-RE14MCC4		0.05 IN
2005-95	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.035 IN

**NITRO**

2012-11	V6-3.7L	GCO-RC9MC4		0.035 IN
2010	V6-3.7L	GCO-UXF79 <sup>(3)</sup> , GCO-RC9MC4		0.044 IN, 0.035 IN
2009-07	V6-3.7L	GCO-RC9MC4		0.035 IN

**RAM 1500**

2009-03	V6-3.7L	GCO-RC9MC4		0.035 IN
2008-07	V8-4.7L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2002-97	V6-3.9L	GCO-UXF79 <sup>(3)</sup>		0.035 IN
2001-97	V8-5.2L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
1996-94	V6-3.9L	GCO-RC12YC	GPL-3071	0.035 In
1996-94	V8-5.2L	GCO-RC12YC	GPL-3071	0.035 In
1996-94	V8-5.9L	GCO-RC12YC	GPL-3071	0.035 In

**RAM 2500**

2009-02	V8-4.7L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
1997	V8-5.9L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>		0.035 In
1996-95	V8-5.9L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>	GPL-3071	0.035 In
1996-94	V10 8.0L	GCO-RC12YC		0.045 IN
1996-94	V8-5.2L	GCO-RC12YC	GPL-3071	0.035 In
1996-94	V8-5.9L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>	GPL-3071	0.035 In

**RAM 2500 VAN**

1997-96	V8-5.2L	GCO-RC12YC	GPL-3071	0.035 In
---------	---------	------------	----------	-------------

(3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## DODGE (Continúa)

### RAM 3500

2009	V8-5.7L	GCO-RE14MCC4		0.045 In
2006-03	V8-5.7L	GCO-RE14MCC4		0.045 In
1997-94	V8-5.9L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>	GPL-3071	0.035 In
1997-94	V8-5.9L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>	GPL-3071	0.035 In

### RAM 3500 VAN

1997	V8-5.9L	GCO-RC12YC	GPL-3071	0.035 In
------	---------	------------	----------	-------------

### RAMCHARGER

1996-94	V8-5.9L	GCO-RC12YC		0.040 IN
---------	---------	------------	--	-------------

### ROYAL MONACO

1977	V8-5.9L	GCO-N12YC		0.040 IN
------	---------	-----------	--	-------------

### SHADOW

1994-93	L4-2.2L	GCO-RN12YC, GCO-UXF79 <sup>(3)</sup>		0.035 In
1994-93	L4-2.5L	GCO-RN12YC, GCO-UXF79 <sup>(3)</sup>		0.035 In

### STRATUS

2006-98	L4-2.4L Turbo	GCO-RC12YC		0.045 IN
2006-95	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.035 IN
2006-95	L4-2.4L	GCO-RC12YC		0.045 IN

### VAN 1000

2009-08	L4-2.4L	GCO-RE14MCC4		0.05 IN
---------	---------	--------------	--	---------

### VERNA

2006-04	L4-1.5L	GCO-RC12YC, GCO-RC10YC4		0.045 IN, 0.044 IN
2006-04	L4-1.6L	GCO-RC12YC, GCO-RC10YC4		0.045 IN, 0.044 IN

### VIPER

2006-04	V10 8.3L	GCO-RC9MC4		0.045 IN
2000	V10 8.0L	GCO-RC12MC4		0.045 IN

### W250

1993	V8-5.9L	GCO-RN12YC		0.035 In
------	---------	------------	--	-------------

## FAW

### F1

2008	L3-1.0L	GCO-UXF79 <sup>(3)</sup>		
------	---------	--------------------------	--	--

(3) 4 Electrodo

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## FAW (Continúa)

### F4

2008	L4-1.4L	GCO-UXF79 <sup>(3)</sup>		
------	---------	--------------------------	--	--

## FIAT

### 500L

2019-15	L4-1.4L Turbo	GCO-RA7YC		0.028 In
---------	------------------	-----------	--	-------------

### ALBEA

2009	L4-1.8L	GCO-RN9YC		0.04 IN
------	---------	-----------	--	---------

### IDEA

2009-08	L4-1.8L	GCO-RN9YC		0.035 IN
---------	---------	-----------	--	-------------

### PALIO

2008-06	L4-1.8L	GCO-RN9YC		0.035 IN
2005-04	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.035 IN

### STILO

2007	L5-2.4L	GCO-RC9YC		0.035 IN
------	---------	-----------	--	-------------

### STRADA

2008	L4-1.8L	GCO-RN9YC		0.032 IN
2007	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.032 IN

## FORD

### AEROSTAR

1997-95	V6-3.0L		GPL-3013	0.054 IN
1997-93	V6-4.0L		GPL-3013	0.044 IN
1995-94	V6-4.0L		GPL-3013	0.054 IN
1993-91	V6-3.0L		GPL-3013	0.054 IN

### CLUB WAGON

1998-97	V8-5.4L	GCO-RS9YCC		0.054 IN
1996-95	V8-5.8L	GCO-BL15Y		0.044 IN

### CONTOUR

2000-95	L4-2.0L		GPL-7437	0.054 IN
2000-95	V6-2.5L	GCO-RS9YCC		0.054 IN

### COURIER

2007-01	L4-1.6L	GCO-RES9YCC4		0.05 IN
---------	---------	--------------	--	---------

### CROWN VICTORIA

1995-93	V8-4.6L		GPL-3013	0.054 In
---------	---------	--	----------	-------------

BUJÍAS

DODGE

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		COBRE	PLATINO	CLBR
AÑO	MOTOR			

**FORD (Continúa)****E-150**

2004	V8-4.6L	GCO-RS9YCC		0.054 IN
2003-02	V6-4.2L	GCO-RS14LC		0.054 IN

**ECONOLINE**

2004	V8-4.6L	GCO-RS9YCC		0.054 IN
------	---------	------------	--	----------

**ECOSPORT**

2011-04	L4-2.0L	GCO-RS9YCC		0.05 IN
---------	---------	------------	--	---------

**EDGE**

2009-07	V6-3.5L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

**ESCAPE**

2019-09	L4-2.5L		GPL-7437	0.052 IN
2009-01	V6-3.0L	GCO-RS9YCC		0.054 IN

**ESCORT**

2003-97	L4-2.0L		GPL-7437	
1996-93	L4-1.8L	GCO-RC12YC		0.05 IN
1996-93	L4-1.9L	GCO-RS9YCC		0.054 IN

**EXCURSION**

2005-00	V10 6.8L	GCO-RS9YCC		0.054 IN
---------	----------	------------	--	----------

**EXPEDITION**

2009-97	V8-5.4L	GCO-RS9YCC		0.054 IN
2004	V8-4.6L	GCO-RS9YCC		0.054 IN
2003-97	V8-4.6L		GPL-3013	0.054 IN

**EXPLORER**

2009-02	V8-4.6L	GCO-RS9YCC		0.054 IN
2009-97	V6-4.0L	GCO-RS9YCC		0.054 IN
2009-91	V6-4.0L		GPL-3013	0.054 IN
2001-96	V8-5.0L	GCO-RS9YCC		0.054 IN

**F-150**

2021	V6-3.3L		GPL-7437	0.052 IN
2020-18	V6-3.3L		GPL-7437	0.052 IN
2009-98	V6-4.2L	GCO-RS14LC		0.054 IN
1997	V8-4.6L	GCO-RS9YCC		0.054 IN

<b>GONHER</b>		COBRE	PLATINO	CLBR
AÑO	MOTOR			

**FORD (Continúa)****F-350**

1993	V8-5.8L	GCO-F11Y		0.044 IN
1990-89	V8-5.8L	GCO-F11Y		0.044 IN

**FIESTA**

2001-98	L4-1.3L	GCO-RS9YCC		0.04 IN
---------	---------	------------	--	---------

**FIVE HUNDRED**

2007-05	V6-3.0L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

**FOCUS**

2010	L4-2.0L	GCO-RS14LC		0.054 IN
2009-06	L4-2.0L	GCO-RS9YCC		0.054 IN
2009-00	L4-2.0L		GPL-7437	0.05 IN
2007	L5-2.5L Turbo		GPL-3071	0.04 IN
2000	L4-2.0L	GCO-RS9YCC		0.05 IN

**FREESTAR**

2007-04	V6-4.2L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

**FUSION**

2020-17	L4-2.0L Híbrido		GPL-7437	0.052 IN
2009-07	L4-2.3L	GCO-RS9YCC		0.054 IN
2009-06	V6-3.0L	GCO-RS9YCC		0.054 IN

**GHIA**

1991	L4-2.3L		GPL-3013	0.054 IN
------	---------	--	----------	----------

**GRAND MARQUIS**

2004-95	V8-4.6L		GPL-3013	0.054 IN
---------	---------	--	----------	----------

**IKON**

2007-03	L4-1.6L	GCO-RES9YCC4		0.054 IN
---------	---------	--------------	--	----------

**KA**

2008-03	L4-1.6L	GCO-RES9YCC4		0.05 IN
---------	---------	--------------	--	---------

**LOBO**

2009-04	V8-4.6L	GCO-RS9YCC		0.054 IN
2006-04	V8-5.4L	GCO-RS9YCC		0.054 IN
1997	V8-4.6L	GCO-RS9YCC		0.054 IN

**MONDEO**

2007-02	V6-2.5L	GCO-RS9YCC		0.04 IN
2007	L4-2.0L		GPL-7437	0.054 IN
2006-01	L4-2.0L	GCO-RS9YCC		0.04 IN

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

**FORD (Continúa)**

**MONDEO (Continúa)**

2001	V6-2.5L	GCO-RS9YCC		0.054 IN
------	---------	------------	--	----------

**MUSTANG**

2009-05	V8-4.6L		GPL-3013	0.054 IN
2004-03	V8-4.6L	GCO-RES9YCC4		0.054 IN
2004-03	V8-4.6L	GCO-RES9YCC4	GPL-3013	0.054 IN
2002-01	V8-4.6L		GPL-3013	0.054 IN
2000-96	V8-4.6L	GCO-RES9YCC4		0.054 IN
1995-94	V8-5.0L	GCO-BL15Y		0.054 IN
1984-80	V8-5.0L		GPL-3013	0.044 IN

**P-350**

1997-92	V8-5.8L	GCO-BL15Y		0.044 IN
---------	---------	-----------	--	----------

**RANGER**

2011-10	L4-2.3L	GCO-RS9YCC		0.054 IN
2009	L4-2.3L	GCO-RES9YCC4, GCO-RS9YCC		0.054 IN
2008-01	L4-2.3L	GCO-RES9YCC4		0.054 IN
2008-93	V6-3.0L	GCO-RS9YCC		0.054 IN
1997	L4-2.3L		GPL-3013	0.054 IN
1996-93	L4-2.3L	GCO-RES9YCC4		0.054 IN

**TAURUS**

1995-93	V6-3.8L	GCO-RS9YCC		0.054 IN
1991	V6-3.8L	GCO-RS14LC		0.054 IN
1990	V6-3.8L	GCO-RS9YCC		0.054 IN
1988	V6-3.8L	GCO-RS9YCC		0.054 IN

**THUNDERBIRD**

2005-02	V8-3.9L		GPL-3013	0.045 IN
1997-95	V6-3.8L	GCO-RS9YCC		0.054 IN
1995	V8-4.6L	GCO-RS9YCC		0.054 IN
1994-89	V6-3.8L	GCO-RS14LC		0.054 IN
1988-85	V6-3.8L	GCO-RS9YCC		0.054 IN

**TOPAZ**

1994-89	L4-2.3L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

**FORD (Continúa)**

**WINDSTAR**

2003-97	V6-3.8L		GPL-3013	0.054 IN
1996-95	V6-3.8L	GCO-RS14LC		0.054 IN

**GEO**

**TRACKER**

1995-94	L4-1.6L		GPL-3071	0.032 IN
---------	---------	--	----------	----------

**GMC**

**ACADIA**

2009-07	V6-3.6L	GCO-RS9YCC		0.06 IN
---------	---------	------------	--	---------

**CANYON**

2009-07	L5-3.7L		GPL-7437	0.06 IN
---------	---------	--	----------	---------

**K1500**

1999-96	V8-5.7L		GPL-3013	0.060 In
1997-96	V8-5.0L		GPL-3013	0.060 In

**K2500**

1999-96	V8-5.7L		GPL-3013	0.060 In
---------	---------	--	----------	----------

**K3500**

2000-96	V8-5.7L		GPL-3013	0.060 In
---------	---------	--	----------	----------

**SAVANA 1500**

2002	V8-5.0L		GPL-3013	0.060 In
------	---------	--	----------	----------

**SAVANA 2500**

2002	V8-5.0L		GPL-3013	0.060 In
------	---------	--	----------	----------

**SIERRA**

2009-08	V8-6.2L	GCO-RS9YCC		0.06 IN
2009-07	V8-5.3L	GCO-RS9YCC		0.06 IN

**SIERRA 1500**

2007-99	V6-4.3L		GPL-3013	0.060 In
---------	---------	--	----------	----------

**TERRAIN**

2013	V6-3.6L		GPL-7437	0.044 In
------	---------	--	----------	----------

**YUKON**

2009-07	V8-6.2L	GCO-RS9YCC		0.06 IN
2009-00	V8-5.3L	GCO-RS9YCC		0.06 IN

**BUJÍAS**  
**FORD**

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>HONDA</b>				

**ACCORD**

2016-10	L4-2.4L		GPL-9407	0.044 IN
2009-08	L4-2.4L	GCO-RC12MC4	GPL-9407	0.045 IN, 0.044 IN
2009-08	V6-3.5L	GCO-RC12MC4		0.045 IN
2007-03	L4-2.4L	GCO-RC12MC4		0.045 IN
2007-99	V6-3.0L	GCO-RC12MC4		0.045 IN
2002-98	L4-2.3L	GCO-UXF79 <sup>(3)</sup>		0.044 IN

**CITY**

2010	L4-1.5L	GCO-RC12MC4		0.052 IN
2010	L4-1.5L	GCO-RC9YC		0.052 IN

**CIVIC**

2015-07	L4-1.8L		GPL-9407	0.044 IN
2009-07	L4-1.3L Híbrido	GCO-RC12MC4		0.040 IN
2009-06	L4-1.8L	GCO-RC9MC4	GPL-9407	0.035 IN, 0.044 IN
2005-01	L4-1.7L	GCO-RC9MC4		0.035 IN
2000-93	L4-1.6L	GCO-RC12YC		0.045 IN

**CR-V**

2017	L4-2.4L	GCO-REA8MCX		0.044 IN
2016-10	L4-2.4L		GPL-9407	0.044 IN
2009	L4-2.4L	GCO-UXF79 <sup>(3)</sup> , GCO-RC9MC4		0.044 IN, 0.035 IN
2008-07	L4-2.4L	GCO-RC9MC4		0.035 IN
2006-02	L4-2.4L	GCO-UXF79 <sup>(3)</sup> , GCO-RC9MC4		0.044 IN, 0.035 IN

**CR-Z**

2013	L4-1.5L Híbrido	GCO-RC9YC		0.044 IN
------	-----------------	-----------	--	----------

**FIT**

2009-06	L4-1.5L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
---------	---------	--------------------------	--	----------

**HR-V**

2017-16	L4-1.8L		GPL-9407	0.044 IN
---------	---------	--	----------	----------

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>HONDA (Continúa)</b>				

**ODYSSEY**

2017-11	V6-3.5L		GPL-9407	0.044 IN
2009-05	V6-3.5L	GCO-RC12MC4		0.045 IN
2004-02	V6-3.5L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2001-99	V6-3.5L	GCO-RC12MC4		0.045 IN

**PASSPORT**

1995-94	V6-3.2L	GCO-RC12YC	GPL-3071	0.044 IN
---------	---------	------------	----------	----------

**PILOT**

2017-09	V6-3.5L		GPL-9407	0.044 IN
2008-03	V6-3.5L	GCO-UXF79 <sup>(3)</sup>		0.044 IN

**RIDGELINE**

2014-09	V6-3.5L		GPL-9407	0.044 IN
---------	---------	--	----------	----------

**HUMMER****H2**

2007-05	V8-6.0L	GCO-RS9YCC		0.06 IN
---------	---------	------------	--	---------

**H3**

2009-08	V8-5.3L	GCO-RS9YCC		0.06 IN
2009-07	L5-3.7L		GPL-7437	0.06 IN

**HYUNDAI****ELANTRA**

2017	L4-2.0L		GPL-9407	0.044 IN
2015	L4-1.8L		GPL-9407	0.044 IN

**TUCSON**

2017	L4-2.0L		GPL-9407	0.044 IN
------	---------	--	----------	----------

**INFINITI****I30**

2001-98	V6-3.0L		GPL-3071	0.044 IN
---------	---------	--	----------	----------

**I35**

2003-02	V6-3.5L	GCO-REC10YC4		0.044 IN
---------	---------	--------------	--	----------

**Q45**

2002	V8-4.5L		GPL-3071	0.044 IN
1997	V8-4.1L	GCO-RC12YC		0.045 IN
1995-94	V8-4.5L		GPL-3071	0.044 IN

(3) 4 Electrodos

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## JAGUAR

### S-TYPE

2006-05	V8-4.2L	GCO-RC10YC4		0.044 IN
2002-99	V8-4.0L	GCO-UXF79 <sup>(3)</sup>		

### XF

2009	V8-4.2L	GCO-RC10YC4	GPL-3071	0.050 In
------	---------	-------------	----------	----------

### XJ8

2009	V8-4.2L	GCO-RC10YC4	GPL-3071	0.050 In
2005	V8-4.2L	GCO-RC10YC4		0.044 IN
2002-00	V8-4.0L	GCO-RC10YC4		0.044 IN
1999	V8-4.0L	GCO-RC10YC4	GPL-3071	0.050 In
1998	V8-4.0L	GCO-RC10YC4		0.044 IN

### XJR

2002-99	V8-4.0L	GCO-RC10YC4		0.044 IN
---------	---------	-------------	--	----------

### XKR

2006	V8-4.2L	GCO-RC10YC4		0.044 IN
------	---------	-------------	--	----------

## JEEP

### CHEROKEE

2020-14	V6-3.2L		GPL-9407	0.044 IN
2014	L4-2.4L	GCO-REC10YC4		0.045 IN

### COMMANDER

2009	V8-5.7L	GCO-RE14MCC4		0.05 IN
2008-06	V8-4.7L	GCO-RC12MC4		0.045 IN
2008-06	V8-5.7L	GCO-RE14MCC4		0.045 IN

### COMPASS

2009-07	L4-2.4L	GCO-RE14MCC4		0.05 IN
2009	L4-2.4L	GCO-RC12MC4		0.043 IN
2007	L4-2.0L	GCO-RC12MC4		0.043 IN

### GLADIATOR

2021	V6-3.6L		GPL-9407	0.044 IN
2020	V6-3.6L		GPL-9407	0.044 IN

### GRAND CHEROKEE

2021	V6-3.6L		GPL-9407	0.044 IN
2020	V6-3.6L		GPL-9407	0.044 IN
2017 -11	V6-3.6L		GPL-9407	0.044 IN

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## JEEP (Continúa)

### GRAND CHEROKEE (Continúa)

2010	V8-6.1L	GCO-RE14MCC4		0.045 IN
2009-07	V8-4.7L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2009-05	V6-3.7L	GCO-RC9MC4		0.035 IN
2009-05	V8-5.7L	GCO-RE14MCC4		0.045 IN
2009	V8-6.1L	GCO-RE14MCC4		0.05 IN
2008-06	V8-6.1L	GCO-RE14MCC4		0.045 IN
2008	V8-5.7L	GCO-REC10YC4		0.045 IN
2007	V8-4.7L	GCO-RC12MC4, GCO-UXF79 <sup>(3)</sup>		0.045 IN
2006-05	V8-4.7L	GCO-RC12MC4		0.045 IN
2004-99	V8-4.7L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
1999	L6-4.0L	GCO-UXF79 <sup>(3)</sup>		0.035 IN
1998	V8-5.2L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
1998	V8-5.9L		GPL-3071	0.035 IN
1997 -93	V8-5.2L		GPL-3071	0.035 IN

### LIBERTY

2012	V6-3.7L	GCO-RC9MC4		0.035 IN
2011 -10	V6-3.7L	GCO-UXF79 <sup>(3)</sup> , GCO-RC9MC4		0.044 IN, 0.035 IN
2009-02	V6-3.7L	GCO-RC9MC4		0.035 IN

### PATRIOT

2011 -07	L4-2.4L	GCO-RC9MC4		0.044 IN
----------	---------	------------	--	----------

### WRANGLER

2021	V6-3.6L		GPL-9407	0.044 IN
2020	V6-3.6L		GPL-9407	0.044 IN
2020	V6-3.6L		GPL-9407	0.044 IN
2017 -12	V6-3.6L		GPL-9407	0.044 IN
2009-07	V6-3.8L		GPL-7437	0.054 IN
2006-05	L6-4.0L	GCO-RC12MC4, GCO-RC12YC		0.045 IN, 0.04 IN
2006-97	L6-4.0L	GCO-RC12YC		0.04 IN
2002-97	L4-2.5L	GCO-RC12MC4		0.04 IN
1995 -93	L4-2.5L	GCO-RC12YC		0.035 IN
1995 -93	L6-4.0L	GCO-RC12YC		0.04 IN

BUJÍAS

JAGUAR

(3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		COBRE	PLATINO	CLBR
AÑO	MOTOR			
<b>KIA</b>				

**FORTE**

2017	L4-2.0L		GPL-9407	0.044 IN
------	---------	--	----------	----------

**RIO**

2016	L4-1.6L		GPL-9407	0.044 IN
------	---------	--	----------	----------

**SORENTO**

2017 -16	L4-2.4L		GPL-9407	0.044 IN
----------	---------	--	----------	----------

**SOUL**

2017 -16	L4-2.0L		GPL-9407	0.044 IN
----------	---------	--	----------	----------

**SPORTAGE**

2017	L4-2.4L	GCO-REC10YC4		0.044 IN
------	---------	--------------	--	----------

**LAND ROVER****LR2**

2012 -08	L6-3.2L	GCO-REC10YC4		
----------	---------	--------------	--	--

**LR3**

2008-06	V8-4.4L	GCO-UXF79 <sup>(3)</sup>		
---------	---------	--------------------------	--	--

**LR4**

2013 -10	V8-5.0L	GCO-REC10YC4		
----------	---------	--------------	--	--

**RANGE ROVER**

2009-06	V8-4.4L	GCO-UXF79 <sup>(3)</sup>		
2001-99	V8-4.6L		GPL-3071	0.04 IN

**LINCOLN****AVIATOR**

2005-03	V8-4.6L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

**BLACKWOOD**

2003-02	V8-5.4L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

**CONTINENTAL**

2002-95	V8-4.6L		GPL-3013	0.054 IN
---------	---------	--	----------	----------

**LS**

2006-00	V8-3.9L		GPL-3071	0.044 IN
---------	---------	--	----------	----------

**MARK LT**

2007-06	V8-5.4L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

**MARK VIII**

1998 -97	V8-4.6L		GPL-3013	0.054 IN
1996	V8-4.6L		GPL-3013	0.05 IN
1995 -93	V8-4.6L		GPL-3013	0.054 IN

(3) 4 Electrodos

<b>GONHER</b>		COBRE	PLATINO	CLBR
AÑO	MOTOR			
<b>LINCOLN (Continúa)</b>				

**MKX**

2009-07	V6-3.5L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

**NAVIGATOR**

2009	V8-5.4L		GPL-3013	0.054 IN
2009	V8-5.4L	GCO-RS9YCC	GPL-3013	0.054 IN
2008-05	V8-5.4L	GCO-RS9YCC		0.054 IN
2005-98	V8-5.4L		GPL-3013	0.054 IN

**TOWN CAR**

2009	V8-4.6L		GPL-3013	0.054 IN
2007-92	V8-4.6L		GPL-3013	0.054 IN
1991	V8-4.6L	GCO-RS9YCC		0.054 IN

**ZEPHYR**

2006	V6-3.0L	GCO-RS9YCC		0.054 IN
------	---------	------------	--	----------

**MAZDA****2**

2017 -15	L4-1.5L	GCO-RC10YC4		0.044 IN
2014 -12	L4-1.5L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN
2012	L4-1.5L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN

**3**

2017 -14	L4-2.0L	GCO-REA8MCX		0.044 IN
2010 -06	L4-2.0L		GPL-7437	
2009-08	L4-2.3L Turbo		GPL-7437	
2009-06	L4-2.3L		GPL-7437	

**5**

2009-06	L4-2.3L		GPL-7437	
---------	---------	--	----------	--

**6**

2008-03	L4-2.3L		GPL-7437	
2008-03	V6-3.0L		GPL-7437	

**CX-5**

2015 -13	L4-2.0L	GCO-REA8MCX		0.044 IN
----------	---------	-------------	--	----------

**CX-7**

2009-07	L4-2.3L Turbo		GPL-7437	0.05 IN
---------	------------------	--	----------	---------

**CX-9**

2007	V6-3.5L		GPL-7437	0.05 IN
------	---------	--	----------	---------

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## MAZDA (Continúa)

### MX-5

2008-06	L4-2.0L		GPL-7437	0.055 IN
---------	---------	--	----------	-------------

## MERCEDES-BENZ

### A160

2005-04	L4-1.6L		GPL-3071	
2001-00	L4-1.6L		GPL-3071	

### A190

2005-04	L4-1.9L		GPL-3071	
2001	L4-1.9L		GPL-3071	

### C220

1997 -95	L4-2.2L		GPL-3071	
----------	---------	--	----------	--

### C230

2000-96	L4-2.3L		GPL-3071	
---------	---------	--	----------	--

### C240

2002-01	V6-2.6L		GPL-3071	
---------	---------	--	----------	--

### C280

2000-99	V6-2.8L	GCO-RC12YC		
1998 -95	L6-2.8L	GCO-UXF79 <sup>(3)</sup>		

### C32 AMG

2004-02	V6-3.2L		GPL-3071	
---------	---------	--	----------	--

### C320

2005-01	V6-3.2L		GPL-3071	
---------	---------	--	----------	--

### C36 AMG

1997 -96	L6-3.6L	GCO-UXF79 <sup>(3)</sup>		
----------	---------	--------------------------	--	--

### C43 AMG

2000-98	V8-4.3L	GCO-RC12YC		
---------	---------	------------	--	--

### CLK320

2003-98	V6-3.2L	GCO-RC12YC		
---------	---------	------------	--	--

### E280

1999	V6-2.8L	GCO-RC12YC		
------	---------	------------	--	--

### E420

1997	V8-4.2L	GCO-RC12YC		
1995	V8-4.2L	GCO-RC12YC		

### E430

2001	V8-4.3L		GPL-3071	
------	---------	--	----------	--

### G65 AMG

2018 -14	V12 6.0L Turbo	GCO-RC10YC4		0.044 IN
----------	-------------------	-------------	--	-------------

### ML320

2002-98	V6-3.2L	GCO-RC12YC		
---------	---------	------------	--	--

### S430

2003-01	V8-4.3L	GCO-RC12YC		
---------	---------	------------	--	--

(3) 4 Electrodo

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## MERCEDES-BENZ (Continúa)

### S500

2002-96	V8-5.0L	GCO-RC12YC		
---------	---------	------------	--	--

### S600

1998 -96	V12 6.0L	GCO-RC12YC		
----------	----------	------------	--	--

### S600L

1995	V12 6.0L	GCO-RC12YC		
------	----------	------------	--	--

### SL320

1997 -96	L6-3.2L	GCO-RC12YC		
----------	---------	------------	--	--

### SL500

2003-96	V8-5.0L	GCO-RC12YC		
---------	---------	------------	--	--

### SL55 AMG

2002	V8-5.0L	GCO-RC12YC		
------	---------	------------	--	--

### SL600

2002-96	V12 6.0L	GCO-RC12YC		
---------	----------	------------	--	--

### SL65 AMG

2019 -13	V12 6.0L Turbo	GCO-RC10YC4		0.044 IN
----------	-------------------	-------------	--	-------------

### SLK230

2004-01	L4-2.3L		GPL-3071	
1998 -97	L4-2.3L		GPL-3071	

## MERCURY

### MARINER

2009-05	V6-3.0L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	-------------

### MILAN

2009-06	V6-3.0L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	-------------

### MONTEGO

2007-05	V6-3.0L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	-------------

### SABLE

2004-03	V6-3.0L		GPL-3013	0.054 IN
---------	---------	--	----------	-------------

### TOPAZ

1994 -93	L4-2.3L		GPL-3013	0.045 IN
----------	---------	--	----------	-------------

## MINI

### COOPER

2003-02	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
---------	---------	--------------------------	--	--

## MITSUBISHI

### ASX

2013	L4-2.0L	GCO-RC9YC		0.044 IN
------	---------	-----------	--	-------------

BUJÍAS

MAZDA

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER.</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

**MITSUBISHI (Continúa)****ECLIPSE**

2012 -11	V6-3.8L	GCO-RC10YC4		0.044 IN
2009-08	V6-3.8L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN
2007-06	V6-3.8L		GPL-3071	0.045 IN
2005-03	V6-3.0L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN
2002-00	V6-3.0L		GPL-3071	0.045 IN

**ENDEAVOR**

2011 -10	V6-3.8L	GCO-RC10YC4		0.044 IN
2009-04	V6-3.8L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN

**GALANT**

2009-05	L4-2.4L		GPL-3071	0.045 IN
2009	V6-3.8L		GPL-3071	0.045 IN
2007-04	V6-3.8L		GPL-3071	0.045 IN
2004	L4-2.4L		GPL-3071	0.044 IN
2003-94	L4-2.4L		GPL-3071	0.045 IN
2003	V6-3.0L	GCO-RC10YC4		0.044 IN
2003	V6-3.0L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN
2002-99	V6-3.0L		GPL-3071	0.045 IN

**GRANDIS**

2009-07	L4-2.4L		GPL-3071	0.045 IN
---------	---------	--	----------	----------

**LANCER**

2010	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		
2010	L4-2.4L	GCO-RC12YC		0.045 IN
2009-08	L4-2.0L	GCO-RC12YC		0.045 IN
2009	L4-2.4L		GPL-3071	0.045 IN
2007-04	L4-2.0L	GCO-RC12YC, GCO-RC10YC4		0.045 IN, 0.044 IN
2007	L4-2.0L	GCO-RC10YC4		0.044 IN
2006-05	L4-2.4L		GPL-3071	0.045 IN

(3) 4 Electrodo

<b>GONHER.</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

**MITSUBISHI (Continúa)****LANCER (Continúa)**

2006-04	L4-2.0L Turbo	GCO-RC12YC, GCO-RC10YC4		0.045 IN, 0.044 IN
2004	L4-2.0L	GCO-RC10YC4		0.044 IN
2004	L4-2.0L	GCO-RC9YC, GCO-RC10YC4		0.045 IN, 0.044 IN

**MONTERO**

2019 -08	V6-3.8L	GCO-RC10YC4		0.044 IN
2006-05	V6-3.8L	GCO-RC10YC4		0.044 IN
2006-05	V6-3.8L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN
2004	V6-3.8L	GCO-RC10YC4 <sup>(3)</sup>		0.044 IN
2004	V6-3.8L	GCO-RC10YC4		0.044 IN
2003	V6-3.8L	GCO-RC10YC4 <sup>(3)</sup>		0.044 IN
2003	V6-3.8L	GCO-RC10YC4		0.044 IN

**MONTERO SPORT**

2006-03	V6-3.5L	GCO-RC10YC4		0.044 IN
---------	---------	-------------	--	----------

**OUTLANDER**

2016 -14	L4-2.4L		GPL-9407	0.044 IN
2013 -10	L4-2.4L	GCO-RC10YC4		0.044 IN
2009-08	L4-2.4L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN
2009-07	V6-3.0L		GPL-3071	0.045 IN

**SPACE STAR**

2004	L4-1.8L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN
2003	L4-1.8L	GCO-RC10YC4		0.044 IN

**NISSAN****200SX**

1997 -95	L4-2.0L	GCO-RC12YC	GPL-3071	0.044 IN
----------	---------	------------	----------	----------

**240SX**

1998	L4-2.4L		GPL-3071	0.044 IN
1993	L4-2.4L		GPL-3071	0.044 IN

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## NISSAN (Continúa)

### 300ZX

1996	V6-3.0L		GPL-3071	0.044 IN
1996	V6-3.0L Turbo		GPL-3071	0.044 IN
1995-91	V6-3.0L	GCO-UXF79 <sup>(3)</sup>		
1995	V6-3.0L Turbo	GCO-UXF79 <sup>(3)</sup>		

### 350Z

2008-04	V6-3.5L		GPL-7437	0.05 IN
---------	---------	--	----------	---------

### ALMERA

2005-01	L4-1.8L	GCO-REC10YC4		0.05 IN
---------	---------	--------------	--	---------

### ALTIMA

2016-07	V6-3.5L	GCO-REA8MCX		0.044 IN
2009-07	L4-2.5L Híbrido	GCO-REC10YC4		0.05 IN
2009-02	L4-2.5L	GCO-REC10YC4		0.05 IN
2001	L4-2.4L	GCO-REC10YC4		0.05 IN
2000	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
1999-93	L4-2.4L		GPL-3071	0.044 IN

### APRIO

2010-08	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
---------	---------	--------------------------	--	----------

### ARMADA

2009-05	V8-5.6L		GPL-7437	0.05 IN
---------	---------	--	----------	---------

### FRONTIER

2008-06	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2004-99	V6-3.3L		GPL-3071	0.044 IN
2004-98	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.044 IN

### HIKARI

1992-88	L4-1.6L	GCO-N12YC		0.045 IN
1992-88	L4-1.6L Turbo	GCO-N12YC		0.045 IN

### ICHI VAN

1994-91	L4-2.4L	GCO-N12YC		0.044 IN
---------	---------	-----------	--	----------

### KICKS

2017	L4-1.6L	GCO-REA8MCX		0.044 IN
------	---------	-------------	--	----------

### LUCINO

2000-96	L4-1.6L		GPL-3071	0.044 IN
2000	L4-2.0L		GPL-3071	0.044 IN
1999-96	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.044 IN

(3) 4 Electrodo

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## NISSAN (Continúa)

### MARCH

2017-13	L4-1.6L	GCO-REA8MCX		0.044 IN
2012	L4-1.6L	GCO-UXF79 <sup>(3)</sup> , GCO-REA8MCX		0.044 IN

### MAXIMA

2007-04	V6-3.5L		GPL-7437	0.05 IN
2001-96	V6-3.0L		GPL-3071	0.044 IN
1995	V6-3.0L	GCO-RC12YC		0.045 IN
1993-91	V6-3.0L	GCO-RC12YC		0.045 IN

### MICRA

2007-05	L4-1.4L	GCO-REC10YC4		0.044 IN
---------	---------	--------------	--	----------

### MURANO

2007-04	V6-3.5L		GPL-7437	0.05 IN
---------	---------	--	----------	---------

### NP300

2015-10	L4-2.4L	GCO-RC12YC	GPL-3071	0.044 IN
---------	---------	------------	----------	----------

### NV350 URVAN

2017-14	L4-2.5L	GCO-REA8MCX		0.044 IN
---------	---------	-------------	--	----------

### PATHFINDER

2017-13	V6-3.5L	GCO-REA8MCX		0.044 IN
2004-01	V6-3.5L	GCO-RC10YC4		0.044 IN
2000-97	V6-3.3L	GCO-RC12YC		0.045 IN

### PICKUP

2010-94	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
1993-91	L4-2.4L	GCO-N12YC		0.044 IN

### PLATINA

2010	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2009-02	L4-1.6L	GCO-RC12YC		0.045 IN

### QUEST

2002	V6-3.3L	GCO-RC12YC		0.039 IN
2001-99	V6-3.3L		GPL-3071	0.039 IN
1998-93	V6-3.0L	GCO-RC12YC		0.045 IN

### ROGUE

2012-08	L4-2.5L	GCO-REA8MCX		0.044 IN
---------	---------	-------------	--	----------

BUJÍAS

NISSAN

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER.</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>NISSAN (Continúa)</b>				

**SAMURAI**

1986	L4-1.6L	GCO-N12YC		0.035 IN
------	---------	-----------	--	----------

**SENTRA**

2017-13	L4-1.8L	GCO-REA8MCX		0.044 IN
2012-10	L4-2.0L	GCO-UXF79 <sup>(3)</sup> , GCO-REA8MCX		0.044 IN
2009-07	L4-2.0L	GCO-REA8MCX	GPL-3071	0.044 IN
2009-07	L4-2.0L	GCO-UXF79 <sup>(3)</sup> , GCO-REA8MCX	GPL-3071	0.044 IN
2009-02	L4-2.5L	GCO-REC10YC4		0.05 IN
2006-00	L4-1.8L	GCO-REC10YC4		0.05 IN
2001-96	L4-2.0L		GPL-3071	0.044 IN
2000-93	L4-1.6L		GPL-3071	0.044 IN
1994-93	L4-2.0L		GPL-3071	0.044 IN

**TIIDA**

2017-07	L4-1.8L	GCO-REA8MCX		0.044 IN
---------	---------	-------------	--	----------

**TITAN**

2009-04	V8-5.6L		GPL-7437	0.05 IN
---------	---------	--	----------	---------

**TSUBAME**

2004-93	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
---------	---------	--------------------------	--	--

**TSURU**

2015-97	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
1997	L4-1.6L	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>		0.044 IN
1996-95	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
1996	L4-1.6L		GPL-3071	0.044 IN
1995	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
1994-93	L4-2.0L		GPL-3071	0.044 IN
1992-86	L4-1.6L	GCO-N12YC		0.035 IN
1985-84	L4-1.5L	GCO-N12YC		0.044 IN

**URVAN**

2012-08	L4-2.5L	GCO-REA8MCX		0.044 IN
2007-00	L4-2.4L		GPL-3071	0.044 IN

**VERSA**

2017-16	L4-1.6L	GCO-REA8MCX		0.044 IN
2015-12	L4-1.6L	GCO-UXF79 <sup>(3)</sup> , GCO-REA8MCX		0.044 IN

(3) 4 Electrodo

<b>GONHER.</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			
<b>NISSAN (Continúa)</b>				

**XTERRA**

2004-00	V6-3.3L		GPL-3071	
---------	---------	--	----------	--

**X-TRAIL**

2017-08	L4-2.5L	GCO-REA8MCX		0.044 IN
---------	---------	-------------	--	----------

**OLDSMOBILE****88**

1999-92	V6-3.8L	GCO-RES9YCC4		
---------	---------	--------------	--	--

**CUTLASS**

1996	V6-3.1L		GPL-3013	
------	---------	--	----------	--

**SILHOUETTE**

1995	V6-3.8L	GCO-RES9YCC4		0.06 IN
1994-93	V6-3.8L		GPL-3013	0.06 IN

**PEUGEOT****206**

2009-02	L4-1.4L	GCO-RC12YC		0.032 IN
2009-02	L4-1.6L		GPL-7437	0.06 IN
2001	L4-1.4L	GCO-UXF79 <sup>(3)</sup>		

**207**

2011-10	L4-1.4L	GCO-UXF79 <sup>(3)</sup>		
2009-08	L4-1.6L Turbo		GPL-7437	0.06 IN
2009	L4-1.4L	GCO-RC12YC		0.032 IN

**306**

2000-98	L4-1.8L		GPL-7437	0.06 IN
1997	L4-1.6L		GPL-7437	0.06 IN

**405**

1999-98	L4-2.0L	GCO-RC12YC		0.032 IN
---------	---------	------------	--	----------

**406**

2003-01	L4-2.0L		GPL-7437	0.06 IN
2002-01	V6-3.0L		GPL-7437	0.06 IN

**407**

2009-07	L4-2.2L		GPL-7437	0.06 IN
---------	---------	--	----------	---------

**607**

2003-02	V6-2.9L	GCO-REC10YC4		0.040 IN
---------	---------	--------------	--	----------

**GRAND RAID**

2009-07	L4-1.6L		GPL-7437	0.06 IN
---------	---------	--	----------	---------

**PARTNER**

2009-04	L4-1.6L		GPL-7437	0.06 IN
---------	---------	--	----------	---------

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## PLYMOUTH

### BARRACUDA

1969	V8-5.2L	GCO-N12YC		0.035 IN
------	---------	-----------	--	----------

### BREEZE

1996	L4-2.0L	GCO-RC9YC, GCO-UXF79 <sup>(3)</sup>		0.035 In
------	---------	--	--	----------

### LASER

1994-93	L4-1.8L	GCO-RN9YC		0.044 In
1994-93	L4-2.0L	GCO-RN9YC		0.044 In
1993	L4-2.0L Turbo	GCO-RN9YC		0.044 In

### VOYAGER

1995-93	L4-2.5L	GCO-RN12YC		0.035 In
---------	---------	------------	--	----------

## PONTIAC

### AZTEK

2005-01	V6-3.4L		GPL-3013	0.060 In
---------	---------	--	----------	----------

### BONNEVILLE

2005-93	V6-3.8L	GCO-RES9YCC4		0.06 IN
---------	---------	--------------	--	---------

### FIREBIRD

2002-93	V8-5.7L	GCO-RES9YCC4		0.05 IN
---------	---------	--------------	--	---------

### G3

2009-07	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
---------	---------	--------------------------	--	----------

### G4

2006-05	L4-2.2L		GPL-7437	
2006	L4-2.4L		GPL-7437	

### G5

2009-07	L4-2.2L		GPL-7437	
2008-07	L4-2.4L		GPL-7437	

### G6

2009-07	V6-3.6L	GCO-RS9YCC		0.040 IN
2009-05	V6-3.5L	GCO-RS9YCC		0.060 IN

### GRAND AM

2005	V6-3.4L		GPL-3013	0.06 IN
2004-02	V6-3.4L	GCO-RS9YCC		0.06 IN
2001-99	V6-3.4L		GPL-3013	0.06 IN

### GRAND PRIX

2008-97	V6-3.8L	GCO-RS9YCC		0.06 IN
2003-93	V6-3.1L		GPL-3013	0.06 IN

### MATIZ

2010	L4-1.0L	GCO-UX79 <sup>(3)</sup>		
2009-04	L4-1.0L	GCO-RN9YC		0.035 IN

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## PONTIAC (Continúa)

### MONTANA

2009-06	V6-3.9L	GCO-RS9YCC		0.06 IN
2006-05	V6-3.5L	GCO-RS9YCC		0.06 IN

### SOLSTICE

2009-06	L4-2.4L		GPL-7437	0.04 IN
---------	---------	--	----------	---------

### SUNFIRE

2005-95	L4-2.2L		GPL-7437	0.06 IN
2002	L4-2.4L		GPL-7437	0.06 IN
2001-99	L4-2.4L		GPL-3013	0.06 IN
1998-96	L4-2.4L		GPL-7437	0.06 IN

### TORRENT

2009-06	V6-3.4L	GCO-RS9YCC		0.06 IN
---------	---------	------------	--	---------

### TRANS SPORT

1995-93	V6-3.8L		GPL-3013	0.060 In
---------	---------	--	----------	----------

## PORSCHE

### 911

2007-05	H6-3.6L	GCO-UXF79 <sup>(3)</sup>		
2007	H6-3.6L Turbo	GCO-UXF79 <sup>(3)</sup>		
2005	H6-3.6L Turbo	GCO-UXF79 <sup>(3)</sup>		

### BOXSTER

2007-05	H6-2.7L	GCO-UXF79 <sup>(3)</sup>		
---------	---------	--------------------------	--	--

### CAYMAN

2007	H6-2.7L	GCO-UXF79 <sup>(3)</sup>		
2007	H6-3.4L	GCO-UXF79 <sup>(3)</sup>		

### PANAMERA

2015-14	V6-3.0L Híbrido	GCO-UXF79 <sup>(3)</sup>		0.032 IN
2015-14	V6-3.0L Turbo	GCO-UXF79 <sup>(3)</sup>		0.032 IN

## RAM

### 700

2018-15	L4-1.6L	GCO-RC9YC		0.036 IN
---------	---------	-----------	--	----------

## RENAULT

### ALLIANCE

1986-85	L4-1.7L	GCO-UX79 <sup>(3)</sup>		
1984	L4-1.7L	GCO-N12YC		0.025 IN

### CLIO

2009-02	L4-1.6L	GCO-RC12YC		0.045 IN
2006-02	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		

### ENCORE

1986-85	L4-1.7L	GCO-UX79 <sup>(3)</sup>		
---------	---------	-------------------------	--	--

(3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		COBRE	PLATINO	CLBR
AÑO	MOTOR			

**RENAULT (Continúa)****EURO CLIO**

2008-07	L4-1.6L	GCO-RC12YC		0.045 IN
---------	---------	------------	--	-------------

**KANGOO**

2009-07	L4-1.6L	GCO-RC12YC		0.045 IN
---------	---------	------------	--	-------------

**KANGOO EXPRESS**

2009-04	L4-1.6L	GCO-RC12YC		
---------	---------	------------	--	--

**LAGUNA**

2006	L4-2.0L Turbo	GCO-UXF79 <sup>(3)</sup>		
2004-03	V6-2.9L	GCO-UXF79 <sup>(3)</sup>		

**MEGANE**

2010	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
2009-07	L4-2.0L Turbo	GCO-UXF79 <sup>(3)</sup>		
2009-01	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		
2009	L4-1.6L	GCO-RC12YC		0.045 IN
2008	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
2005	L4-2.0L Turbo	GCO-UXF79 <sup>(3)</sup>		

**R12**

1978 -75	L4-1.6L	GCO-N12YC		
----------	---------	-----------	--	--

**R18**

1986 -85	L4-2.0L	GCO-RES9YCC4		
1984 -80	L4-1.6L	GCO-N12YC		

**SANDERO**

2011 -10	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
----------	---------	--------------------------	--	--

**SCALA**

2012 -11	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
----------	---------	--------------------------	--	--

**SCENIC**

2004-01	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		
---------	---------	--------------------------	--	--

**SCENIC II**

2008-05	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		
---------	---------	--------------------------	--	--

**STEPWAY**

2011	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
------	---------	--------------------------	--	--

**SEAT****ALHAMBRA**

2007-04	L4-1.8L Turbo	GCO-RC8VTYC4 <sup>(2)</sup>		0.035 IN
---------	------------------	-----------------------------	--	-------------

**CORDOBA**

2009-04	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.035 IN
2009-04	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2003	L4-2.0L	GCO-RC8VTYC4 <sup>(2)</sup>		0.040 IN

<b>GONHER</b>		COBRE	PLATINO	CLBR
AÑO	MOTOR			

**SEAT (Continúa)****CORDOBA (Continúa)**

2002-01	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.035 IN
---------	---------	--------------------------	--	-------------

**IBIZA**

2013 -09	L4-2.0L	GCO-RC8VTYC4 <sup>(2)</sup>		0.040 IN
2012 -04	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2008-03	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2008	L4-1.8L Turbo	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2002-01	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040 IN

**LEON**

2009-08	L4-2.0L Turbo	GCO-RC12MC4		0.04 IN
2009	L4-1.8L Turbo	GCO-RC8VTYC4 <sup>(2)</sup>		0.035 IN
2008	L4-2.0L	GCO-RC12MC4		0.04 IN
2006-01	L4-1.8L Turbo	GCO-UXF79 <sup>(3)</sup>		0.035 IN
2005-01	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.035 IN

**NUEVO IBIZA**

2010	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		
2010	L4-2.0L	GCO-RC8VTYC4 <sup>(2)</sup>		

**TOLEDO**

2005-01	L4-1.8L	GCO-RC8VTYC4 <sup>(2)</sup>		0.040 IN
2004-01	L4-1.8L Turbo	GCO-RC8VTYC4 <sup>(2)</sup>		0.040 IN

**SUBARU****LEGACY**

2007-06	H4-2.5L	GCO-RC10YC4		0.044 IN
2007-06	H4-2.5L Turbo	GCO-RC10YC4		0.044 IN

**OUTBACK**

2009	H4-2.5L	GCO-RC10YC4		0.044 IN
2008-06	H4-2.5L Turbo	GCO-RC10YC4		0.044 IN

**SUZUKI****AERIO**

2007-06	L4-2.3L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN
---------	---------	---	--	-------------

**GRAND VITARA**

2008	V6-2.7L	GCO-RC10YC4		0.044 IN
2007-06	V6-2.7L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN

(2) 3 Electrodo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## SUZUKI (Continúa)

### SWIFT

2007	L4-1.5L	GCO-UXF79 <sup>(3)</sup>		
------	---------	--------------------------	--	--

### SX4

2011 -08	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		
----------	---------	--------------------------	--	--

## TOYOTA

### 4RUNNER

2008	V8-4.7L	GCO-RC10YC4		0.044 IN
2007-04	V8-4.7L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN
2007	V6-4.0L		GPL-3071	0.045 IN
2003	V8-4.7L	GCO-RC10YC4		0.044 IN

### CAMRY

2009-07	V6-3.5L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2009-03	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2006-05	V6-3.0L	GCO-UXF79 <sup>(3)</sup>		0.044 IN

### COROLLA

2017 -10	L4-1.8L	GCO-REA8MCX		0.044 IN
2009	L4-1.8L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4, GCO-REA8MCX		0.044 IN
2009	L4-2.4L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2008-07	L4-1.8L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN
2006-93	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.044 IN

### HIACE

2007-06	L4-2.7L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
---------	---------	--------------------------	--	----------

### HILUX

2007-04	L4-2.7L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
---------	---------	--------------------------	--	----------

### LAND CRUISER

2009-08	V8-5.7L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2007	V8-4.7L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2006-04	V8-4.7L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN

### MATRIX

2009-08	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2007-04	L4-1.8L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN
2003	L4-1.8L	GCO-RC10YC4		0.044 IN

(3) 4 Electrodos

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## TOYOTA (Continúa)

### MR2 SPYDER

2006-05	L4-1.8L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN
---------	---------	---	--	----------

### PRIUS C

2018	L4-1.5L Híbrido	GCO-RC12YC, GCO-UXF79 <sup>(3)</sup>		0.043 IN
------	--------------------	---	--	----------

### RAV4

2008-04	L4-2.4L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN
---------	---------	---	--	----------

### SEQUOIA

2008	V8-4.7L	GCO-RC10YC4		0.044 IN
------	---------	-------------	--	----------

### SIENNA

2006-04	V6-3.3L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN
---------	---------	---	--	----------

### SOLARA

2006	V6-3.3L	GCO-RC10YC4		0.044 IN
------	---------	-------------	--	----------

### TACOMA

2011 -10	V6-4.0L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2009-07	V6-4.0L		GPL-3071	0.045 IN

### TUNDRA

2009-08	V8-4.7L		GPL-3071	0.045 IN
2009-05	V6-4.0L		GPL-3071	0.045 IN
2007	V8-4.7L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN
2006-00	V8-4.7L		GPL-3071	0.045 IN

### YARIS

2011	L4-1.5L	GCO-RC12YC		0.044 IN
2010-06	L4-1.5L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
2005	L4-1.3L	GCO-UXF79 <sup>(3)</sup> , GCO-RC10YC4		0.044 IN
2004	L4-1.3L	GCO-RC10YC4		0.044 IN

## VAM

### GREMLIN

1981 -76	L6-4.2L	GCO-N12YC		0.035 IN
1975 -74	L6-4.2L	GCO-UX79 <sup>(3)</sup>		

### JAVELIN

1973 -72	L6-4.6L	GCO-N12YC		0.035 IN
----------	---------	-----------	--	----------

BUJÍAS

SUZUKI

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

**VAM (Continúa)****PACER**

1979	L6-4.6L	GCO-N12YC		0.035 IN
1978 -76	L6-4.6L	GCO-UX79 <sup>(3)</sup>		

**VOLKSWAGEN****ATLANTIC**

1987 -85	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.028 IN
1987	L4-1.7L	GCO-N12YC		0.028 IN
1986 -83	L4-1.7L	GCO-UX79 <sup>(3)</sup>		0.028 IN
1984	L4-1.8L	GCO-N12YC		0.028 IN
1982	L4-1.7L	GCO-N12YC		0.027 IN
1981	L4-1.6L	GCO-UX79 <sup>(3)</sup>		0.028 IN

**BEETLE**

2011 -10	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2008	L4-2.0L	GCO-RC8VTC4 <sup>(2)</sup>		0.040 IN
2007	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2005-98	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040 IN

**CABRIO**

1999 -98	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
----------	---------	--------------------------	--	----------

**CARIBE**

1987 -86	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.028 IN
1987	L4-1.7L	GCO-N12YC		0.028 IN
1986 -81	L4-1.7L	GCO-UX79 <sup>(3)</sup>		0.028 IN
1985 -84	L4-1.8L	GCO-N12YC		0.028 IN
1980 -77	L4-1.6L	GCO-UX79 <sup>(3)</sup>		0.028 IN

**CLASICO**

2014 -11	L4-2.0L	GCO-RC8VTC4 <sup>(2)</sup>		0.040 IN
----------	---------	----------------------------	--	----------

**COMBI**

2001-88	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.028 IN
---------	---------	-------------------------	--	----------

**CORSAR**

1988 -84	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.028 IN
----------	---------	-------------------------	--	----------

**CROSSFOX**

2012 -11	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2009-07	L4-1.6L	GCO-RC8VTC4 <sup>(2)</sup>		0.04 IN

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

**VOLKSWAGEN (Continúa)****DERBY**

2009-08	L4-1.8L	GCO-N7BYC		0.032 IN
2007	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.032 IN
2006-95	L4-1.8L	GCO-N7BYC		0.032 IN
2003-02	L4-2.0L	GCO-RC8VTC4 <sup>(2)</sup>		0.032 IN

**EUROVAN**

2004-01	L5-2.5L	GCO-UXF79 <sup>(3)</sup>		0.032 IN
2000	V6-2.8L	GCO-RC8VTC4 <sup>(2)</sup> , GCO-RC10YC4		0.044 IN

**GOL**

2011 -09	L4-1.6L	GCO-RC8VTC4 <sup>(2)</sup>		0.04 IN
----------	---------	----------------------------	--	---------

**GOL SEDAN**

2011 -10	L4-1.6L	GCO-RC8VTC4 <sup>(2)</sup>		0.044 IN
----------	---------	----------------------------	--	----------

**GOLF**

2007-06	L4-2.0L	GCO-RC8VTC4 <sup>(2)</sup>		0.04 IN
2005-02	L4-1.8L Turbo		GPL-3071	0.032 IN
2005-95	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.032 IN
2001	L4-1.8L Turbo	GCO-RC10YC4	GPL-3071	0.044 IN, 0.032 IN
1999 -96	L4-1.8L	GCO-N7BYC, GCO-RC10YC4		0.032 IN, 0.044 IN
1999 -96	V6-2.8L	GCO-RC9BMC		0.04 IN
1995 -92	L4-1.8L	GCO-N7BYC		0.032 IN
1991 -88	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.032 IN
1987	L4-1.8L	GCO-N12YC		0.028 IN

**GTI**

2009-07	L4-2.0L Turbo	GCO-RC12MC4		0.04 IN
---------	---------------	-------------	--	---------

**JETTA**

2012	L4-2.0L Turbo	GCO-RC8VTC4 <sup>(2)</sup>		0.040 IN
2010	L4-2.0L	GCO-RC8VTC4 <sup>(2)</sup>		0.040 IN
2009-08	L4-2.0L	GCO-UXF79 <sup>(3)</sup> , GCO-RC9BMC		0.040 IN, 0.04 IN
2009-08	L4-2.0L Turbo	GCO-RC9BMC		0.04 IN

(2) 3 Electrodo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## VOLKSWAGEN (Continúa)

### JETTA (Continúa)

2008	L4-2.0L Turbo	GCO-UXF79 <sup>(3)</sup> , GCO-RC9BMC		0.040 IN, 0.04 IN
2007-00	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2007	L4-2.0L Turbo	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2005-04	L4-1.8L Turbo	GCO-RC8VTC4 <sup>(2)</sup>		0.032 IN
2003	L4-1.8L Turbo	GCO-RC12YC		0.032 IN
2002-01	V6-2.8L	GCO-RC12YC		0.04 IN
2002-00	L4-1.8L Turbo	GCO-RC8VTC4 <sup>(2)</sup>		0.032 IN
2000-95	V6-2.8L	GCO-RC9BMC		0.04 IN
1999-98	L4-2.0L	GCO-RC8VTC4 <sup>(2)</sup>		0.04 IN
1999-93	L4-1.8L	GCO-N7BYC		0.032 IN
1999	L4-1.8L Turbo	GCO-N7BYC		0.032 IN
1997-93	L4-2.0L	GCO-RC9BMC		0.04 IN
1992-87	L4-1.8L	GCO-UX79 <sup>(3)</sup>		0.032 IN

### JETTA CITY

2009-08	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
---------	---------	--------------------------	--	----------

### LUPO

2009-07	L4-1.6L	GCO-RC8VTC4 <sup>(2)</sup>		0.040 IN
2006-05	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040 IN

### PASSAT

2017-12	V6-3.6L		GPL-9407	0.044 IN
2005-99	V6-2.8L	GCO-RC8VTC4 <sup>(2)</sup>		0.04 IN
2005	L4-1.8L Turbo	GCO-RC12MC4		0.04 IN
2004-00	L4-1.8L Turbo	GCO-RC8VTC4 <sup>(2)</sup> , GCO-RC10YC4		0.028 IN, 0.044 IN
1999	L4-1.8L Turbo	GCO-RC12MC4		0.04 IN
1997-96	V6-2.8L	GCO-RC9BMC		0.04 IN
1993	L4-2.0L	GCO-RC8VTC4 <sup>(2)</sup>		0.028 IN
1992-91	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.028 IN

### POINTER

2009-08	L4-1.8L	GCO-RC8VTC4 <sup>(2)</sup>		0.040 IN
2007-06	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2005-98	L4-1.8L	GCO-N7BYC		0.040 IN

<b>GONHER</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## VOLKSWAGEN (Continúa)

### POINTER (Continúa)

2002-00	L4-2.0L	GCO-N7BYC		0.040 IN
---------	---------	-----------	--	----------

### POINTER TRUCK

2007-06	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2005-98	L4-1.8L	GCO-N7BYC		0.040 IN

### POLO

2007-03	L4-1.6L	GCO-RC8VTC4 <sup>(2)</sup>		0.04 IN
2007	L4-2.0L	GCO-RC8VTC4 <sup>(2)</sup>		0.04 IN
2006-03	L4-2.0L	GCO-UXF79 <sup>(3)</sup>		0.033 IN

### ROUTAN

2009	V6-3.8L	GCO-RE14MCC4		0.05 IN
------	---------	--------------	--	---------

### SAVEIRO

2011	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.044 IN
------	---------	--------------------------	--	----------

### SEDAN

2004-91	H4-1.6L	GCO-N12YC		0.025 IN
---------	---------	-----------	--	----------

### SHARAN

2008-02	L4-1.8L Turbo	GCO-RC8VTC4 <sup>(2)</sup>		0.032 IN
---------	---------------	----------------------------	--	----------

### SPORTVAN

2010	L4-1.6L	GCO-UXF79 <sup>(3)</sup>		0.040 IN
2009-07	L4-1.6L	GCO-RC8VTC4 <sup>(2)</sup>		0.040 IN

### TIGUAN

2009	L4-2.0L Turbo	GCO-RC12MC4		0.04 IN
------	---------------	-------------	--	---------

### TOUAREG

2014-13	V6-3.0L Híbrido	GCO-UXF79 <sup>(3)</sup>		0.028 IN
2009-08	V6-3.6L	GCO-RC12MC4		0.04 IN
2008-04	V8-4.2L		GPL-3071	0.045 IN

### VAN

2008	L4-1.8L	GCO-UXF79 <sup>(3)</sup>		0.032 IN
2007-03	L4-1.8L	GCO-RC8VTC4 <sup>(2)</sup>		0.04 IN

## VOLVO

### C30

2009-08	L5-2.5L Turbo		GPL-3071	
2009	L5-2.4L		GPL-3071	

BUJÍAS

VOLKSWAGEN

(2) 3 Electrodo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

<b>GONHER®</b>		<b>COBRE</b>	<b>PLATINO</b>	<b>CLBR</b>
<b>AÑO</b>	<b>MOTOR</b>			

## VOLVO (Continúa)

### C70

2005-02	L5-2.4L Turbo		GPL-3071	0.04 IN
---------	------------------	--	----------	---------

### S40

2009-04	L5-2.5L Turbo		GPL-3071	
---------	------------------	--	----------	--

### S60

2008-06	L5-2.4L Turbo		GPL-3071	0.04 IN
2005	L5-2.3L Turbo		GPL-3071	
2003-01	L5-2.4L Turbo		GPL-3071	0.04 IN

### S80

2006-04	L6-2.9L Turbo		GPL-3071	
2003-00	L6-2.9L		GPL-3071	

### V50

2007-06	L5-2.5L Turbo		GPL-3071	
---------	------------------	--	----------	--

### XC70

2007-04	L5-2.5L Turbo		GPL-3071	0.04 IN
---------	------------------	--	----------	---------

### XC90

2007-04	L5-2.5L Turbo		GPL-3071	0.04 IN
2006-03	L6-2.9L Turbo		GPL-3071	0.04 IN

<b>GONHER</b>				
Marca Modelo	Cilindrada (cc)	Año	GONHER	Calibración

### AHM

AH110	110	2004 >	GCO-Z9Y	0.028 in
ATTILA	125	2004-2006	GCO-Z9Y	0.028 in
CITY	125	2006-2008	GCO-Z9Y	0.028 in
COMET 125	125	2005-2006	GCO-Z9Y	0.028 in
COMET 150	150	2006-2009	GCO-Z9Y	0.028 in
FORTUNE	110	2004-2009	GCO-Z9Y	0.028 in
MAGIC	50	2005 >	GCO-Z9Y	0.028 in
MAGIC	90	2010-2012	GCO-Z9Y	0.028 in
PLAY BIKE	110	2006 >	GCO-Z9Y	0.028 in
R110	110	2008-2011	GCO-Z9Y	0.028 in
RIDER 250	250	2004-2010	GCO-Z9Y	0.028 in
SHARK	125	2005 >	GCO-Z9Y	0.028 in
SPIDER	50	2006 >	GCO-Z9Y	0.028 in
SPIDER	90	2006 >	GCO-Z9Y	0.028 in
SPIDER	110	2006 >	GCO-Z9Y	0.028 in
SPIDER	200	2007-2011	GCO-Z9Y	0.028 in
SPIDER	200	2009-2012	GCO-Z9Y	0.028 in
200FA				

### HONDA

AERO, GYRO, SPREE	50		GCO-Z9Y	0.024 in
AT	70		GCO-Z9Y	0.024 in
C	80		GCO-Z9Y	0.024 in
C (12MM)	90		GCO-Z9Y	0.024 in
CA	70		GCO-Z9Y	0.024 in
CA	250		GCO-Z9Y	0.024 in
CA 105 T	55		GCO-Z9Y	0.024 in
CD (10MM)	90		GCO-Z9Y	0.024 in
CD M	65		GCO-Z9Y	0.024 in
CE	75		GCO-Z9Y	0.024 in
CF	70		GCO-Z9Y	0.024 in
CF CHALY	50		GCO-Z9Y	0.024 in
CF II	70		GCO-Z9Y	0.024 in
CF III	50		GCO-Z9Y	0.024 in
CH	80		GCO-Z9Y	0.024 in
CJ	125		GCO-Z9Y	0.024 in
CL	50		GCO-Z9Y	0.024 in
CL	70		GCO-Z9Y	0.024 in
CM	125		GCO-Z9Y	0.024 in
CMX250C	250	1996-2005	GCO-Z9Y	0.028 in
REBEL				
CR III	70		GCO-Z9Y	0.024 in
CR L, LA	50		GCO-Z9Y	0.024 in
CS	50		GCO-Z9Y	0.024 in
CS	70		GCO-Z9Y	0.024 in
CT	50		GCO-Z9Y	0.024 in
CY	50	1980-1985	GCO-Z9Y	0.024 in
LS	70		GCO-Z9Y	0.024 in
MD	70		GCO-Z9Y	0.024 in
MD	90		GCO-Z9Y	0.024 in
MINI	70		GCO-Z9Y	0.024 in
P L	50		GCO-Z9Y	0.024 in
PF	50		GCO-Z9Y	0.024 in
PS	50		GCO-Z9Y	0.024 in
QA	50		GCO-Z9Y	0.024 in
S ROLLER	50		GCO-Z9Y	0.024 in
SL	70		GCO-Z9Y	0.024 in
SS M	50		GCO-Z9Y	0.024 in
ROLLER				

<b>GONHER</b>				
Marca Modelo	Cilindrada (cc)	Año	GONHER	Calibración

### HONDA (Continuación)

SS V, ZK2	50		GCO-Z9Y	0.024 in
ROLLER				
T	250		GCO-Z9Y	0.024 in
TL	50		GCO-Z9Y	0.024 in
TRAIL	70		GCO-Z9Y	0.024 in
TRAIL	70		GCO-Z9Y	0.024 in
XE	50		GCO-Z9Y	0.024 in
XE	75		GCO-Z9Y	0.024 in
XE II	50		GCO-Z9Y	0.024 in
XL	70		GCO-Z9Y	0.024 in
XL	75		GCO-Z9Y	0.024 in
XL (S M 10 MM)	100		GCO-Z9Y	0.024 in
XL K	75		GCO-Z9Y	0.024 in
XL S	80		GCO-Z9Y	0.024 in
XR K	75		GCO-Z9Y	0.024 in
YR	75		GCO-Z9Y	0.024 in

### ISLO

ATC70	70	1973-1981	GCO-Z9Y	0.024 in
HERO 100	100	2002-2003	GCO-Z9Y	0.028 in
TRX90EX	90	2008 >	GCO-Z9Y	0.028 in

### ITALIKA

ARGENTA (AT-110)	110	2005-2014	GCO-Z9Y	0.028 in
AT110	110	2011-2014	GCO-Z9Y	0.028 in
AT110 SPORT	110	2011-2012	GCO-Z9Y	0.028 in
ATV150	150	2006-2011	GCO-Z9Y	0.028 in
ATV150	150	2013-2014	GCO-Z9Y	0.028 in
CON REVERSA				
ATV150 SPORT	150	2011-2012	GCO-Z9Y	0.028 in
CITY	125	2007-2009	GCO-Z9Y	0.028 in
CS-125				
CS125	125	2010-2014	GCO-Z9Y	0.028 in
DIABOLO-125	125	2007-2009	GCO-Z9Y	0.028 in
DIABOLO-150	150	2007-2009	GCO-Z9Y	0.028 in
DS125	125	2005-2009	GCO-Z9Y	0.028 in
DS150	150	2013-2014	GCO-Z9Y	0.028 in
FT110	110	2010-2014	GCO-Z9Y	0.028 in
GS150	150	2013-2014	GCO-Z9Y	0.028 in
LEDS				
GTS175	175	2010-2014	GCO-Z9Y	0.028 in
JUMBO	110	2007 >	GCO-Z9Y	0.024 in
PS90	90	2010-2014	GCO-Z9Y	0.028 in
ST170	170	2005-2008	GCO-Z9Y	0.028 in
STRADA (ST-70)	70	2007-2009	GCO-Z9Y	0.028 in
STRADA (ST-90)	90	2009-2014	GCO-Z9Y	0.028 in
TS-170	170	2009 >	GCO-Z9Y	0.028 in
VENDETTA				
VS-90	90	2006-2008	GCO-Z9Y	0.028 in
VS90	90	2006-2008	GCO-Z9Y	0.028 in
WS-150	150	2008-2009	GCO-Z9Y	0.028 in
WS175	175	2012-2014	GCO-Z9Y	0.028 in
XS125	125	2010-2014	GCO-Z9Y	0.028 in
XS150	150	2010-2012	GCO-Z9Y	0.028 in

<b>GONHER</b>				
Marca Modelo	Cilindrada (cc)	Año	GONHER	Calibración

### KAWASAKI

4S-100	100	1993-1995	GCO-Z9Y	0.028 in
AN	80		GCO-Z9Y	0.028 in
AN090 (NEOMAX)	100	1995 >	GCO-Z9Y	0.028 in
AN110 (KAZE-R)	110	2000-2002	GCO-Z9Y	0.028 in
AN90 (NEOMAX, MAX II)	90	1998-1999	GCO-Z9Y	0.028 in
AX1	90		GCO-Z9Y	0.024 in
KAZE	110	1995 >	GCO-Z9Y	0.024 in
KLT	110		GCO-Z9Y	0.024 in
KLT	160		GCO-Z9Y	0.024 in
KLX110	110	2008-2009	GCO-Z9Y	0.028 in
KZE	110	1995 >	GCO-Z9Y	0.024 in
MOJAVE	110		GCO-Z9Y	0.024 in
NINJA 250R	250	2008-2010	GCO-Z9Y	0.020 in

### KYMCO

CALYPSO 125	125	1997 >	GCO-Z9Y	0.020 in
PEOPLE	125	1999 >	GCO-Z9Y	0.024 in

### MOTO GUZZI

V35 IMOLA II	350	1979-1986	GCO-Z9Y	0.020 in
V50 MONZA II	500	1984-1987	GCO-Z9Y	0.024 in
V65 LARIO	650		GCO-Z9Y	0.024 in
V75 DUNA	750		GCO-Z9Y	0.024 in

### SUZUKI

FD110	110	2005 >	GCO-Z9Y	0.032 in
FD110CK4	110	2004 >	GCO-Z9Y	0.032 in
FK110SD (SMASH)	110	2008 >	GCO-Z9Y	0.032 in

### SYM

F1-125	125	2010 >	GCO-Z9Y	0.028 in
JET 125	125	2010 >	GCO-Z9Y	0.028 in
MOVING 125	125	2010 >	GCO-Z9Y	0.028 in
RS-21 125	125	2005 >	GCO-Z9Y	0.028 in

### VENTO

COLT 250	250	2009 >	GCO-Z9Y	0.028 in
FIRENZE	125	2005 >	GCO-Z9Y	0.028 in
PHANTON	150	2005-2006	GCO-Z9Y	0.028 in
REBELLIAN 250	250	2008 >	GCO-Z9Y	0.028 in
V-THUNDER 300	300	2009 >	GCO-Z9Y	0.028 in

<b>GONHER</b>				
Marca Modelo	Cilindrada (cc)	Año	GONHER	Calibración

### YAMAHA

BELUGA XC125	125	1997 >	GCO-Z9Y	0.020 in
JOG 100	100	2009 >	GCO-Z9Y	0.028 in
T 105 (CRYPTON)	105	1999-2008	GCO-Z9Y	0.028 in
T 50	50		GCO-Z9Y	0.028 in
XC 125D	125	1986-1993	GCO-Z9Y	0.028 in
XV 250 V-STAR	250	2009 >	GCO-Z9Y	0.028 in
XV VIRAGO V TWIN	125	1997 >	GCO-Z9Y	0.024 in
YFM 100	100		GCO-Z9Y	0.024 in
YFM 80	80	1985-2004	GCO-Z9Y	0.028 in
YFM 80R	80	2002 >	GCO-Z9Y	0.028 in
YFM E, F	80	1993 >	GCO-Z9Y	0.024 in

<b>AC DELCO</b> <b>GONHER</b>		<b>BERU</b> <b>GONHER</b>		<b>DENSO</b> <b>GONHER</b>		<b>NGK</b> <b>GONHER</b>	
44XLS	GCO-N12YC	Z6 14K-8DU	GCO-BN12Y	KJ20CR-L11	GCO-RC9MC4	BPR5EFS	GCO-BN12Y
FR1LS	GCO-RC9YC	Z7414FR-8LDU0X4	GCO-RC9BMC	MA16P-U	GCO-F11Y	BPR5E-A	GCO-RN12YC
FR2LS	GCO-RC12YC	Z8 14R-8DU	GCO-RN12YC	PT16VR-13	GCO-RES9YCC4	BPR6E-11	GCO-RC10YC4
R42LTS	GCO-BN12Y	Z80 14K-9DU	GCO-BN14Y	Q16PR-U11	GCO-RC12YC	BPR6EFS	GCO-RS9YCC
R43TS	GCO-BL15Y	<b>BOSCH</b> <b>GONHER</b>		Q20PR-U	GCO-RC9YC	BPR6ES	GCO-RN9YC
R43XLS	GCO-RN12YC	F7LTCR	GCO-RC8VTC4	Q20PR-U11	GCO-RC10YC4	BPR6EY	GCO-RN9YC
S102F	GCO-Z9Y	FR7DC	GCO-RC9YC	T16EPR-U	GCO-BN12Y	BPR6EY	GCO-UX79
<b>AUTOLITE</b> <b>GONHER</b>		FR7LCX	GCO-RC9MC4	T16NR-U11	GCO-RS14LC	C7HSA	GCO-Z9Y
106	GCO-BN14Y	FR8DCX	GCO-RC10YC4	T16P-U	GCO-BL15Y	DCPR7E	GCO-RA7YC
2544	GCO-RS14LC	FR8DCX	GCO-RC12YC	T20EPR-U	GCO-RS9YCC	LF5A-11	GCO-REC10YC4
2545	GCO-RS14LC	FR8LDC	GCO-RC10YC4	U22FSU	GCO-Z9Y	LZKAR7A	GCO-RE8MCCX
2546	GCO-RS14LC	FR8MC9	GCO-REC10YC4	W16EPR-U	GCO-RN12YC	LZTR4A-11	GCO-RE14MCC4
26	GCO-BL15Y	FR9HC	GCO-RC12MC4	W16EP-U	GCO-N12YC	TR4	GCO-BN12Y
275	GCO-L92Y	HR7DCX	GCO-RS9YCC	W16EP-U	GCO-N14Y	TR5-1	GCO-RS14LC
3923	GCO-RC10YC4	HR8MEV	GCO-RES9YCC4	W20EPR-U	GCO-RN9YC	TR55	GCO-RS14LC
3923	GCO-RC9YC	UR3AS	GCO-Z9Y	XE20HR-U9	GCO-RE8MCCX	TR5B-13	GCO-RES9YCC4
3924	GCO-RC12YC	VR8SE	GCO-RE8MCCX	XU22EPR-U	GCO-RA7YC	WR4-1	GCO-F11Y
3924	GCO-RC9YC	WR8DP	GCO-N12YC	<b>MOTOCRAFT</b> <b>GONHER</b>		ZFR5F	GCO-RC10YC4
4194	GCO-Z9Y	WR9DC	GCO-RN12YC	AF52C	GCO-BL15Y	ZFR5F11	GCO-RC9MC4
4253	GCO-RN9YC	YR7DC	GCO-RA7YC	AGRF22PP1	GCO-RES9YCC4	ZFR5F-11	GCO-RC12MC4
4263	GCO-RN9YC	YR7DE	GCO-RA7YC	AGSP52C	GCO-RC12YC	ZFR6K-11	GCO-RC12MC4
5224	GCO-RC12MC4	<b>CHAMPION</b> <b>GONHER</b>		ASF22C	GCO-BL15Y	<b>PLATINO</b>	
5224	GCO-RC9MC4	BL15Y	GCO-BL15Y	ASF32C	GCO-BL15Y	<b>AUTOLITE</b> <b>GONHER</b>	
5263	GCO-RE14MCC4	BN12Y	GCO-BN12Y	ASF52C	GCO-BL15Y	AP3923	GPL-3071
55	GCO-N12YC	BN14Y	GCO-BN14Y	BSF82C	GCO-F11Y	AP3924	GPL-3071
64	GCO-N7BYC	F11Y	GCO-F11Y	MAE42C	GCO-L92Y	AP605	GPL-3013
65	GCO-RN12YC	L92Y	GCO-L92Y	MAG42C	GCO-N14Y	APP5344	GPL-7437
66	GCO-RN12YC	N12YC	GCO-N12YC	MAG52C	GCO-N14Y	<b>BERU</b> <b>GONHER</b>	
747	GCO-F11Y	N12YC	GCO-UX79	MAGS32C	GCO-N12YC	Z 400	GPL-3071
765	GCO-BN12Y	N14Y	GCO-N14Y	MAGS52C	GCO-BN14Y	Z 402	GPL-3013
APP5344	GCO-RES9YCC4	N7BYC	GCO-N7BYC	MAGS52C	GCO-RN12YC	Z9714KR-6MPX	GPL-7437
<b>BERU</b> <b>GONHER</b>		RA7YC	GCO-RA7YC	MAGS54C	GCO-BN14Y	<b>BOSCH</b> <b>GONHER</b>	
12VR-8 SE	GCO-RE8MCCX	RC10YC4	GCO-RC10YC4	MAGSF52C	GCO-BN12Y	FR8DPX	GPL-3071
14F-8LUR	GCO-RC10YC4	RC12MC4	GCO-RC12MC4	MAGSP32C	GCO-RC9YC	HR8DPX	GPL-3013
14FR-6 DPUX02	GCO-RC10YC4	RC12YC	GCO-RC12YC	MBF82C	GCO-F11Y	<b>CHAMPION</b> <b>GONHER</b>	
14FR-7LUX	GCO-RC9MC4	RC12YC	GCO-UXF79	<b>NGK</b> <b>GONHER</b>		3013	GPL-3013
UX 79	GCO-UX79	RC87YCL	GCO-UXF79	AP4FS	GCO-F11Y	3071	GPL-3071
UXF 79	GCO-UXF79	RC8VTC4	GCO-RC8VTC4	APR4FS	GCO-F11Y	7437	GPL-7437
UXK-79	GCO-RS9YCC	RC8VTC4	GCO-UXF79	BKR5E-11	GCO-RC12YC	9407	GPL-9407
Z 1	GCO-N12YC	RC9BMC	GCO-RC9BMC	BKR5E-11	GCO-UXF79	<b>DENSO</b> <b>GONHER</b>	
Z 117	GCO-RS14LC	RC9MC4	GCO-RC9MC4	BKR5EK	GCO-RC9BMC	IT16	GPL-3013
Z 118	GCO-L92Y	RC9YC	GCO-RC9YC	BKR5EKU	GCO-RC9BMC	<b>MOTOCRAFT</b> <b>GONHER</b>	
Z 15	GCO-RC9YC	RE14MCC4	GCO-RE14MCC4	BKR6E	GCO-RC9YC	AZFS32FE	GPL-7437
Z 174	GCO-BL15Y	REA8MCCX	GCO-REA8MCCX	BKR6ES	GCO-RC9YC	MAWSF32P	GPL-3013
Z 199	GCO-Z9Y	REC10YC4	GCO-REC10YC4	BKUR6ET-10	GCO-RC8VTC4	MAZFS22FE	GPL-7437
Z 2	GCO-N7BYC	RES9YCC4	GCO-RES9YCC4	BKUR6ET-10	GCO-UXF79	<b>NGK</b> <b>GONHER</b>	
Z 20	GCO-RN9YC	RN12YC	GCO-RN12YC	BKUR6ET-11	GCO-RC8VTC4	BKR6EVX-11	GPL-3071
Z 209	GCO-RS9YCC	RN9YC	GCO-RN9YC	BP4EFS	GCO-BN14Y	ILZKR7B11	GPL-9407
Z 216	GCO-RE14MCC4	RN9YC	GCO-UX79	BP4ES	GCO-N14Y	PTR5A-13	GPL-7437
Z 73	GCO-RC12YC	RS14LC	GCO-RS14LC	BP4FS	GCO-BL15Y	PTR5A-15	GPL-7437
Z 76	GCO-N14Y	RS9YCC	GCO-RS9YCC	BP5EFS	GCO-BN12Y		
Z 90	GCO-RC8VTC4	Z9Y	GCO-Z9Y	BP5ES	GCO-N12YC		
Z175 18K-9BU	GCO-F11Y	<b>DENSO</b> <b>GONHER</b>		BP5ES-A	GCO-N12YC		
Z177 14KR-8MUV	GCO-RES9YCC4	K16PR- U11	GCO-RC10YC4	BP5ES-A	GCO-UX79		
Z183 14FR-8MUJ2	GCO-REC10YC4	K20PBR-S10	GCO-RC8VTC4	BP5HS	GCO-L92Y		
Z299 14FR-7LUX0	GCO-RC12MC4	KJ16CR-L11	GCO-RC12MC4	BP6ET	GCO-N7BYC		
Z358	GCO-RA7YC			BPR4EFS	GCO-BN14Y		

# ESPECIFICACIONES DE BUJÍAS

GONHER	ROSCA	ASIENTO	RESISTENCIA	ALCANCE DE ROSCA	HEXÁGONO	TIPO	CANTIDAD DE ELECTRODOS	GAP
GCO-BL15Y	M14X1.25	CONICO	SI	11.2 mm	16 mm	COBRE	1	1.1 mm
GCO-BN12Y	M14X1.25	CONICO	NO	17.25 mm	16 mm	COBRE	1	1.1 mm
GCO-BN14Y	M14X1.25	CONICO	NO	17.25 mm	16 mm	COBRE	1	1.1 mm
GCO-F11Y	M18X1.5	CONICO	NO	13.6 mm	20.8 mm	COBRE	1	1.1 mm
GCO-L92Y	M14X1.25	PLANO	NO	12.7 mm	20.8 mm	COBRE	1	0.7 mm
GCO-N12YC	M14X1.25	PLANO	NO	19 mm	20.8 mm	COBRE	1	0.7 mm
GCO-N14Y	M14X1.25	PLANO	NO	19 mm	20.8 mm	COBRE	1	0.8 mm
GCO-N7BYC	M14X1.25	PLANO	NO	19 mm	20.8 mm	COBRE	3	1.0 mm
GCO-RC12MC4	M14X1.25	PLANO	NO	19 mm	16 mm	COBRE	1	1.0 mm
GCO-RC12YC	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	1	1.1 mm
GCO-RC8VTYC4	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	3	1.0 mm
GCO-RC9BMC	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	2	1.0 mm
GCO-RC9YC	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	1	0.9 mm
GCO-RE14MCC4	M14X1.25	CONICO	SI	25 mm	16 mm	COBRE	1	1.0 mm
GCO-REC10YC4	M14X1.25	PLANO	SI	26.5 mm	16 mm	COBRE	1	1.1 mm
GCO-RES9YCC4	M14X1.25	CONICO	SI	25 mm	16 mm	COBRE	1	1.1 mm
GCO-RN12YC	M14X1.25	PLANO	SI	19 mm	20.8 mm	COBRE	1	0.7 mm
GCO-RN9YC	M14X1.25	PLANO	SI	19 mm	20.8 mm	COBRE	1	0.8 mm
GCO-RS14LC	M14X1.25	CONICO	SI	17 mm	16 mm	COBRE	1	1.1 mm
GCO-RS9YCC	M14X1.25	CONICO	SI	17.5 mm	16 mm	COBRE	1	1.1 mm
GCO-UX79	M14X1.25	PLANO	SI	19 mm	20.8 mm	COBRE	4	1.1 mm
GCO-UXF79	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	4	1.1 mm
GCO-Z9Y	M10X1.0	PLANO	NO	12.7 mm	16 mm	COBRE	1	0.7 mm
GPL-3013	M14X1.25	CONICO	SI	17.25 mm	16 mm	PLATINO	1	1.1 mm
GPL-3071	M14X1.25	PLANO	SI	19 mm	16 mm	PLATINO	1	0.7 mm
GPL-7437	M14X1.25	CONICO	SI	25 mm	16 mm	PLATINO	1	1.3 mm

# GARANTÍA

Para nosotros la satisfacción del cliente es el objetivo principal. Por ello, en todos nuestros productos ofrecemos garantías de fabricación. Cuando se utilicen las **Bujías GONHER, Gonhermex S.A. de C.V.**, garantiza sus productos contra cualquier defecto de fabricación durante un período de 1 año para bujías de cobre y 2 años para bujías de platino a partir de su compra.

En el caso de daño al motor atribuible en forma directa a falla de una bujía **GONHER** que ha sido instalada en forma correcta, **Gonhermex, S.A. de C.V.** pagará la reparación a una condición equivalente a la que exista antes de la falla. El daño deberá ser comprobado por un técnico autorizado por **Gonhermex S.A. de C.V.** antes de cualquier reparación.

**Gonhermex S.A. de C.V.** no es responsable por cualquier otro daño o perjuicio ni cuando las bujías hayan sido utilizadas en condiciones distintas a las normales y no cubre pérdidas causadas por una instalación incorrecta, errores en la aplicación o modificaciones del producto.

Esta garantía podrá hacerse válida en **Gonhermex S.A. de C.V.**, o cualquiera de los distribuidores autorizados.

GONHERMEX DE MÉXICO, S.A. DE C.V.  
Av. Manuel Ordoñez No. 600 C.P. 66350  
Santa Catarina, N.L., México  
Tel: (81) 8153-31-00



# GONHER®

En marcha contigo



Consulta el  
catálogo

[grupogonher.com](http://grupogonher.com)

EMPRESA 100% MEXICANA

