

GONHER®
AUTOPARTES

CATÁLOGO 2025



» **BUJÍAS**



En marcha contigo.

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

ACURA

MDX

2020-14	V6-3.5L		GPL-9407	0.044 IN
2006-05	V6-3.5L	GCO-UXF79 ⁽³⁾ , GCO-RC12MC4		0.044 IN

RL

2011 -09	V6-3.7L	GCO-UXF79 ⁽³⁾		
----------	---------	--------------------------	--	--

TLX

2020-15	V6-3.5L		GPL-9407	0.044 IN
---------	---------	--	----------	----------

ALFA ROMEO

166

2003-02	V6-3.0L		GPL-3071	0.045 IN
---------	---------	--	----------	----------

GT

2008-07	L4-2.0L	GCO-UXF79 ⁽³⁾		
---------	---------	--------------------------	--	--

GTV

2003	V6-3.0L		GPL-3071	0.045 IN
------	---------	--	----------	----------

SPIDER

2003	V6-3.0L		GPL-3071	0.045 IN
------	---------	--	----------	----------

AUDI

A1

2011	L4-1.4L Turbo		GPL-3071	0.035 IN
------	---------------	--	----------	----------

A3

2008	L4-1.4L Turbo	GCO-RC9YC		0.028 IN
2004	L4-1.8L Turbo	GCO-REC10YC4		0.032 IN
2004	L4-2.0L	GCO-RC9YC		0.032 IN
2004	L4-2.0L	GCO-REC10YC4		0.032 IN
2003-98	L4-1.8L Turbo	GCO-RC12MC4		0.04 IN

A3 QUATTRO

2004	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
------	---------------	-----------	--	----------

A4

2006-02	L4-1.8L Turbo	GCO-RC12MC4		0.04 IN
2006	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
2001-98	L4-1.8L Turbo	GCO-RC8VTC4 ⁽²⁾		0.04 IN
1997	V6-2.8L	GCO-RC8VTC4 ⁽²⁾		0.04 IN

A4 QUATTRO

2005	V6-3.2L	GCO-RC9YC		
------	---------	-----------	--	--

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

AUDI (Continúa)

A5

2011	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
------	---------------	-----------	--	----------

A5 QUATTRO

2011	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
------	---------------	-----------	--	----------

A6

2001-98	V6-2.8L	GCO-RC12MC4		0.04 IN
---------	---------	-------------	--	---------

A6 QUATTRO

2002	V6-3.0L	GCO-RC12YC		0.032 IN
------	---------	------------	--	----------

A7 QUATTRO

2012	V6-3.0L	GCO-RC12YC		0.032 IN
------	---------	------------	--	----------

A8

2000	V8-3.7L	GCO-UXF79 ⁽³⁾		
------	---------	--------------------------	--	--

A8 QUATTRO

2013	V6-3.0L	GCO-RC12YC		0.032 IN
1997	V8-4.2L	GCO-RC12YC		0.032 IN

ALLROAD QUATTRO

2004-01	V6-2.7L Turbo	GCO-UXF79 ⁽³⁾		
---------	---------------	--------------------------	--	--

CABRIOLET

1998 -97	V6-2.8L	GCO-RC8VTC4 ⁽²⁾		
----------	---------	----------------------------	--	--

Q3

2013	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
------	---------------	-----------	--	----------

Q3 QUATTRO

2017	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
------	---------------	-----------	--	----------

Q5

2010	L4-2.0L Turbo	GCO-RC9YC		0.032 IN
------	---------------	-----------	--	----------

Q7

2018 -17	V6-3.0L	GCO-UXF79 ⁽³⁾		
2015 -12	V6-3.0L	GCO-UXF79 ⁽³⁾		
2009-07	V8-4.2L		GPL-3071	0.045 IN
2007	V6-3.6L	GCO-RC12MC4		0.04 IN

S3

2004-00	L4-1.8L Turbo		GPL-3071	0.045 IN
---------	---------------	--	----------	----------

S4

2016 -12	V6-3.0L	GCO-UXF79 ⁽³⁾		
2010	V6-3.0L	GCO-RC12YC		
2008-04	V8-4.2L		GPL-3071	0.065 IN

BUJÍAS

ACURA

(2) 3 Electrodo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

AUDI (Continúa)**S4 (Continúa)**

2000	V6-2.7L Turbo		GPL-3071	0.045 IN
------	---------------	--	----------	----------

S5

2009-08	V8-4.2L		GPL-3071	0.045 IN
---------	---------	--	----------	----------

S6

2009-07	V10 5.2L		GPL-3071	0.045 IN
2004-01	V8-4.2L	GCO-UXF79 ⁽³⁾		

S8

2009-07	V10 5.2L		GPL-3071	0.045 IN
2002-01	V8-4.2L	GCO-UXF79 ⁽³⁾		

SQ5

2014	V6-3.0L	GCO-RC12YC		0.032 IN
------	---------	------------	--	----------

TT

2009-07	L4-2.0L Turbo		GPL-3071	0.045 IN
2006-99	L4-1.8L Turbo		GPL-3071	0.045 IN

BAIC**BJ40**

2022	L4-2.3L Turbo	GCO-RC10YC4		0.032 IN
2018	L4-2.3L Turbo	GCO-RC10YC4		0.032 IN

D20

2020	L4-1.5L	GCO-RN12YC		
2018-17	L4-1.5L	GCO-RN12YC		

X25

2020-17	L4-1.5L	GCO-RN12YC		
---------	---------	------------	--	--

X65

2020-18	L4-2.0L Turbo	GCO-RC10YC4		0.032 IN
---------	---------------	-------------	--	----------

BENTLEY**CONTINENTAL**

2007	W12 6.0L Turbo	GCO-RC9YC		0.032 IN
------	----------------	-----------	--	----------

BMW**125I**

2012-08	L6-3.0L	GCO-REC10YC4		0.044 In
---------	---------	--------------	--	----------

760LI

2006	V12 6.0L		GPL-3071	
------	----------	--	----------	--

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

BMW (Continúa)**X3**

2012-11	L6-3.0L Turbo	GCO-UXF79 ⁽³⁾		
2012-04	L6-3.0L	GCO-UXF79 ⁽³⁾		
2007-04	L6-2.5L	GCO-UXF79 ⁽³⁾		

X5

2011-01	L6-3.0L	GCO-UXF79 ⁽³⁾		
2011	L6-3.0L Turbo	GCO-UXF79 ⁽³⁾		
2009-05	V8-4.8L	GCO-RC12MC4		0.04 IN
2006-02	V8-4.4L	GCO-UXF79 ⁽³⁾		
2000	V8-4.4L	GCO-UXF79 ⁽³⁾		

X6

2010-09	L6-3.0L	GCO-UXF79 ⁽³⁾		
2010-09	V8-4.4L Turbo	GCO-UXF79 ⁽³⁾		
2009	L6-3.0L Turbo	GCO-UXF79 ⁽³⁾		

Z4

2011	L6-3.0L	GCO-REC10YC4		0.020 IN
2010-07	L6-2.5L	GCO-REC10YC4		0.044 In
2009-07	L6-3.0L	GCO-REC10YC4		0.044 In
2005-03	L6-2.5L	GCO-UXF79 ⁽³⁾		

Z8

2003-01	V8-4.9L	GCO-UXF79 ⁽³⁾		
---------	---------	--------------------------	--	--

BUICK**CENTURY**

2005-89	V6-3.1L	GCO-RES9YCC4		0.06 IN
1988-84	V6-2.8L	GCO-BL15Y		0.044 IN

ENCLAVE

2016-10	V6-3.6L		GPL-7437	0.044 In
---------	---------	--	----------	----------

LACROSSE

2013-10	V6-3.6L		GPL-7437	0.044 In
---------	---------	--	----------	----------

LESABRE

2000-97	V6-3.8L		GPL-3013	0.060 IN
1995-93	V6-3.8L		GPL-3013	0.060 IN

PARK AVENUE

1996-93	V6-3.8L		GPL-3013	0.060 IN
---------	---------	--	----------	----------

REGAL

2004-93	V6-3.8L	GCO-RES9YCC4		0.06 IN
---------	---------	--------------	--	---------

(3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO MOTOR				

BUICK (Continúa)

RENDEZVOUS

2007-06	V6-3.5L		GPL-3013	0.060 IN
---------	---------	--	----------	----------

ROADMASTER

1996-94	V8-5.7L		GPL-3013	0.060 IN
---------	---------	--	----------	----------

SKYLARK

1998-96	V6-3.1L		GPL-3013	0.060 IN
1997-96	L4-2.4L		GPL-3013	0.060 IN
1995	L4-2.3L		GPL-3013	0.060 IN
1993	V6-3.3L		GPL-3013	0.060 IN

TERRAZA

2005	V6-3.5L		GPL-3013	0.060 IN
------	---------	--	----------	----------

CADILLAC

ALLANTE

1993	V8-4.6L		GPL-3013	0.060 IN
------	---------	--	----------	----------

ATS

2013	L4-2.0L Turbo		GPL-7437	0.044 IN
------	---------------	--	----------	----------

CATERA

2001-99	V6-3.0L	GCO-UXF79 ⁽³⁾ , GCO-RC12YC	GPL-3071	0.040 IN, 0.040 IN
1998-97	V6-3.0L	GCO-UXF79 ⁽³⁾		

CTS

2011-10	V6-3.6L	GCO-UXF79 ⁽³⁾		
2009-08	V6-3.6L	GCO-RC9BMC		0.044 IN
2007-04	V6-3.6L	GCO-UXF79 ⁽³⁾		
2004-03	V6-3.2L	GCO-RC9BMC		0.044 IN

DEVILLE

2005	V8-4.6L	GCO-RES9YCC4		0.052 IN
2004-02	V8-4.6L	GCO-RS9YCC		0.052 IN
2001-97	V8-4.6L		GPL-3013	0.05 IN
1996	V8-4.6L	GCO-RS9YCC		
1995-94	V8-4.6L	GCO-RES9YCC4		0.052 IN
1995-92	V8-4.9L	GCO-RS9YCC		
1991	V8-4.9L		GPL-3013	0.06 IN

ELDORADO

2002-93	V8-4.6L	GCO-RES9YCC4		0.052 IN
---------	---------	--------------	--	----------

GONHER®		COBRE	PLATINO	CLBR
AÑO MOTOR				

CADILLAC (Continúa)

ESCALADE

2009-07	V8-6.2L		GPL-7437	0.052 IN
2009	V8-6.0L Híbrido		GPL-7437	0.052 IN
2006-02	V8-6.0L		GPL-7437	0.052 IN

FLEETWOOD

1996-93	V8-5.7L		GPL-3013	0.050 IN
---------	---------	--	----------	----------

SEVILLE

2004-03	V8-4.6L	GCO-RS9YCC		0.052 IN
2002-01	V8-4.6L	GCO-RES9YCC4		0.052 IN
2000	V8-4.6L		GPL-3013	0.05 IN
1999-93	V8-4.6L	GCO-RES9YCC4		0.052 IN

SRX

2007-04	V8-4.6L		GPL-3013	0.04 IN
2006-04	V6-3.6L		GPL-7437	0.052 IN

STS

2009-07	V6-3.6L		GPL-7437	0.052 IN
2009-07	V8-4.6L		GPL-7437	0.052 IN
2006-05	V8-4.6L		GPL-3013	0.05 IN

XLR

2009	V8-4.6L		GPL-3013	0.04 IN
2007-04	V8-4.6L		GPL-3013	0.04 IN

CHEVROLET

ASTRA

2008-06	L4-1.8L	GCO-RC9BMC		0.044 IN
2008	L4-2.0L	GCO-UXF79 ⁽³⁾		0.035 IN
2008	L4-2.0L Turbo	GCO-UXF79 ⁽³⁾		0.035 IN
2007-06	L4-2.0L Turbo	GCO-RN9YC		0.04 IN
2006-04	L4-2.0L	GCO-RN9YC		0.04 IN
2006-04	L4-2.4L	GCO-UXF79 ⁽³⁾		0.035 IN
2003-00	L4-1.8L	GCO-RC9BMC, GCO-RC10DMC ⁽¹⁾		0.044 IN, 0.036 IN

AVALANCHE

2009-07	V8-5.3L	GCO-RS9YCC		0.06 IN
---------	---------	------------	--	---------

BUJÍAS

BUICK

(1) Producto nuevo, (3) 4 Electrodos

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

CHEVROLET (Continúa)**AVEO**

2017 -13	L4-1.6L	GCO-RC8YC4 ⁽¹⁾		0.044 IN
2012	L4-1.6L	GCO-RC8YC4 ⁽¹⁾ , GCO-UXF79 ⁽³⁾		0.044 IN, 0.035 IN
2011 -09	L4-1.6L	GCO-UXF79 ⁽³⁾ , GCO-RC9MC4		0.035 IN
2008	L4-1.6L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4, GCO-RC8YC4 ⁽¹⁾		0.035 IN, 0.044 IN
2007-04	L4-1.6L	GCO-RC8YC4 ⁽¹⁾		0.044

BEAT

2021-18	L4-1.2L	GCO-RA7YC		0.040 In
---------	---------	-----------	--	----------

BLAZER

2005-02	V6-4.3L	GCO-BL15Y		0.045 IN
2001-98	V6-4.3L	GCO-RES9YCC4		0.06 IN
1997-96	V6-4.3L		GPL-3013	0.06 IN
1995	V6-4.3L	GCO-BL15Y		0.045 IN

C10

1981 -80	L6-4.1L	GCO-N14Y		
1981 -80	L6-4.8L	GCO-N14Y		
1981 -80	V8-5.7L	GCO-N14Y		

C20

1986	V8-5.7L	GCO-N14Y		
------	---------	----------	--	--

C2500

2000-96	V8-5.7L		GPL-3013	0.050 IN
---------	---------	--	----------	----------

C2500 SUBURBAN

1999-96	V8-5.7L		GPL-3013	0.060 IN
---------	---------	--	----------	----------

C30

1982 -80	L6-4.1L	GCO-N14Y		
1982 -80	L6-4.8L	GCO-N14Y		
1982 -80	V8-5.7L	GCO-N14Y		

CAMARO

2014 -10	V6-3.6L		GPL-7437	0.044 In
2013	V8-6.2L	GCO-RS14LC		0.040 In
2002-96	V8-5.7L	GCO-RS9YCC		0.040 IN
2002-95	V6-3.8L	GCO-RES9YCC4		0.06 IN
1995-93	V8-5.7L		GPL-3013	0.060 IN

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

CHEVROLET (Continúa)**CAPRICE**

1996-93	V8-5.7L	GCO-BL15Y		0.035 IN
1982-79	V8-5.7L	GCO-BL15Y		0.035 IN

CAVALIER

2005	L4-2.2L	GCO-RES9YCC4		0.045 IN
2004-03	L4-2.2L	GCO-RS9YCC		0.06 IN
2002-99	L4-2.2L	GCO-RES9YCC4		0.045 IN
2002-97	L4-2.4L	GCO-RES9YCC4		0.050 IN
2002	L4-2.2L	GCO-RS9YCC, GCO-RES9YCC4		0.06 IN, 0.045 IN
1998	L4-2.2L	GCO-RS9YCC		0.050 IN
1997-93	L4-2.2L	GCO-RES9YCC4		0.045 IN
1996	L4-2.4L	GCO-RS9YCC		0.050 IN
1995	L4-2.4L	GCO-RES9YCC4		0.050 IN
1994-91	V6-3.1L	GCO-RES9YCC4		0.045 IN
1994-90	V6-2.8L	GCO-RES9YCC4		0.045 IN

CELEBRITY

1989-87	V6-2.8L	GCO-RES9YCC4		0.044 IN
1986-82	V6-2.8L	GCO-BL15Y		0.045 IN

CHEVY

2012-96	L4-1.6L	GCO-RN9YC		0.04 IN
2002-94	L4-1.4L	GCO-RN9YC		0.04 IN

CHEVY MONZA

2003	L4-1.6L	GCO-RN9YC		0.04 IN
------	---------	-----------	--	---------

CHEVY PICKUP

2003-99	L4-1.6L	GCO-UX79 ⁽³⁾		0.035 IN
---------	---------	-------------------------	--	----------

CHEYENNE

2021-16	V8-5.3L		GPL-7437	0.044 IN
2021-14	V8-6.2L		GPL-7437	0.044 IN
2015-07	V8-5.3L	GCO-RS14YC ⁽¹⁾	GPL-7437	0.044 IN

CITATION

1986-82	V6-2.8L	GCO-BL15Y		0.045 IN
---------	---------	-----------	--	----------

COLORADO

2009-07	L5-3.7L		GPL-7437	0.06 IN
2006-04	L5-3.5L		GPL-7437	0.06 IN

(1) Producto nuevo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO MOTOR				

CHEVROLET (Continúa)

CORSA

2008-03	L4-1.8L	GCO-RN9YC		0.04 IN
2002	L4-1.4L	GCO-RN9YC		0.035 IN

CORVETTE

2004	V8-5.7L	GCO-RS9YCC		0.06 IN
1996-92	V8-5.7L		GPL-3013	0.06 IN

CRUZE

2011 -10	L4-1.8L	GCO-UXF79 ⁽³⁾		0.028 IN
----------	---------	--------------------------	--	----------

EQUINOX

2009-05	V6-3.4L	GCO-RS9YCC, GCO-RS14YC6 ⁽¹⁾		0.06 IN
---------	---------	---	--	---------

EXPRESS CARGO

2021 -18	V6-4.3L		GPL-7437	0.044 IN
----------	---------	--	----------	----------

IMPALA

2005-00	V6-3.8L	GCO-RS9YCC		0.06 IN
1996-95	V8-5.7L	GCO-BL15Y		0.035 IN
1975	V8-5.7L	GCO-BL15Y		0.035 IN

K2500 SUBURBAN

1999-96	V8-5.7L		GPL-3013	0.060 IN
---------	---------	--	----------	----------

LUMINA

1999-98	V6-3.8L		GPL-3013	0.060 IN
---------	---------	--	----------	----------

LUMINA APV

1995	V6-3.8L		GPL-3013	0.060 IN
------	---------	--	----------	----------

LUV

2005-98	L4-2.2L	GCO-BL15Y		0.044 IN
1997	L4-2.3L	GCO-N7BYC		0.044 IN

MALIBU

2009-08	L4-2.4L	GCO-RES9YCC4		0.06 IN
2009-08	L4-2.4L Híbrido	GCO-RES9YCC4		0.06 IN
2009-04	V6-3.5L	GCO-RS9YCC		0.06 IN
2008-04	L4-2.2L	GCO-RS9YCC		0.06 IN
2003-97	V6-3.1L	GCO-RES9YCC4		0.06 IN
1999-97	L4-2.4L	GCO-RES9YCC4		0.06 IN
1981-79	V8-5.7L	GCO-BL15Y		0.035 IN

GONHER®		COBRE	PLATINO	CLBR
AÑO MOTOR				

CHEVROLET (Continúa)

MATIZ

2014 -13	L4-1.0L	GCO-UXF79 ⁽³⁾		0.044 IN
2012	L4-1.0L	GCO-RN9YC, GCO-UXF79 ⁽³⁾		0.044 IN
2011	L4-1.0L	GCO-UX79 ⁽³⁾		0.044 IN

MERIVA

2007-04	L4-1.8L	GCO-RN9YC		0.04 IN
---------	---------	-----------	--	---------

MONTE CARLO

2000-98	V6-3.8L		GPL-3013	0.060 IN
1984-81	V8-5.7L	GCO-BL15Y		

NOVA

1978 -77	V8-5.7L	GCO-BL15Y		0.035 IN
1978 -75	L6-4.1L	GCO-BL15Y		0.035 IN

OPTRA

2010-08	L4-2.0L	GCO-UXF79 ⁽³⁾ , GCO-RC10DMC ⁽¹⁾		0.044 IN, 0.032 IN
2007-06	L4-2.0L	GCO-RC9YC, GCO-RC10DMC ⁽¹⁾		0.035 IN, 0.032 IN

S10

2003-00	L4-2.2L	GCO-UXF79 ⁽³⁾		0.040 IN
2002-01	L4-2.2L	GCO-RES9YCC4, GCO-UXF79 ⁽³⁾		0.06 IN
2000	L4-2.2L	GCO-RC9BMC, GCO-UXF79 ⁽³⁾		0.04 IN
1999-98	L4-2.2L	GCO-RC9BMC		0.04 IN
1997-94	L4-2.2L	GCO-UXF79 ⁽³⁾		0.040 IN
1993-91	V6-3.1L	GCO-BL15Y		0.045 IN

SILVERADO 1500

2015 -14	V6-4.3L		GPL-3013	0.060 IN
2013-03	V6-4.3L	GCO-RS14YC6 ⁽¹⁾	GPL-3013	0.060 IN
2002-99	V6-4.3L	GCO-RS14YC6 ⁽¹⁾		0.060 IN

SILVERADO 1500 CLASSIC

2007	V6-4.3L		GPL-3013	0.060 IN
------	---------	--	----------	----------

SILVERADO 2500

2002-00	V8-5.7L		GPL-3013	0.060 IN
---------	---------	--	----------	----------

BUJÍAS

CHEVROLET

(1) Producto nuevo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

CHEVROLET (Continúa)**SONIC**

2013 -12	L4-1.6L	GCO-RC12MC4		0.035 IN
----------	---------	-------------	--	----------

SONORA

2006-03	V8-5.3L	GCO-RS9YCC, GCO-RS14YC ⁽¹⁾		0.06 IN
2002-00	V8-5.7L	GCO-RS9YCC		0.06 IN

SPARK

2018 -16	L4-1.4L	GCO-RA7YC		0.035 IN
2015 -12	L4-1.2L	GCO-UXF79 ⁽³⁾ , GCO-RA7YC		0.040 IN, 0.035 IN
2011	L4-1.2L	GCO-RN9YC, GCO-UXF79 ⁽³⁾ , GCO-RA7YC		0.040 IN, 0.035 IN

SPARK CLASSIC

2016	L4-1.2L	GCO-UXF79 ⁽³⁾ , GCO-RA7YC		0.040 IN, 0.035 IN
------	---------	---	--	-----------------------

SUBURBAN 1500

2006-00	V8-5.3L	GCO-RS14YC6 ⁽¹⁾		0.06 IN
---------	---------	----------------------------	--	---------

TAHOE

2014 -00	V8-5.3L	GCO-RS9YCC, GCO-RS12YC ⁽¹⁾		0.06 IN, 0.04 IN
2009-00	V8-4.8L	GCO-RS12YC ⁽¹⁾		1.0 mm

TORNADO

2009-04	L4-1.8L	GCO-RN9YC		0.04 IN
---------	---------	-----------	--	---------

TRACKER

2007-05	L4-2.0L	GCO-UX79 ⁽³⁾		0.044 IN
2004-99	L4-2.0L	GCO-RN9YC		0.044 IN
2000-98	L4-1.6L	GCO-RN9YC		0.045 IN

TRAILBLAZER

2009-02	L6-4.2L	GCO-RS9YCC		0.044 IN
---------	---------	------------	--	----------

TRAVERSE

2015 -09	V6-3.6L		GPL-7437	0.044 IN
----------	---------	--	----------	----------

TRAX

2013	L4-1.8L	GCO-RC12MC4		0.035 IN
------	---------	-------------	--	----------

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

CHEVROLET (Continúa)**UPLANDER**

2009	V6-3.9L	GCO-RS14YC ⁽¹⁾		0.044 IN
2008-07	V6-3.9L	GCO-RS14YC ⁽¹⁾	GPL-7437	0.044 IN, 0.06 IN
2006-05	V6-3.5L	GCO-RS14YC6 ⁽¹⁾	GPL-7437	0.06 IN
2006	V6-3.9L		GPL-7437	0.06 IN

VECTRA

2005-03	V6-3.2L	GCO-UXF79 ⁽³⁾		0.035 IN
---------	---------	--------------------------	--	----------

VENTURE

2005-97	V6-3.4L	GCO-RES9YCC4		0.06 IN
---------	---------	--------------	--	---------

ZAFIRA

2005	L4-1.8L	GCO-UXF79 ⁽³⁾		0.035 IN
2004-02	L4-1.8L	GCO-RC9BMC		0.04 IN

CHRYSLER**200**

2015	L4-2.4L	GCO-RC12MC4		0.044 IN
2014 -12	L4-2.4L	GCO-RC12MC4, GCO-RC12MCC4 ⁽¹⁾		0.044 IN
2013	V6-3.6L	GCO-RC12MC4, GCO-RC12MCC4 ⁽¹⁾		0.044 IN
2011	L4-2.4L	GCO-RC12MCC4 ⁽¹⁾		0.044 IN

300

2021 -12	V6-3.6L		GPL-9407	0.044 IN
2009-05	V8-5.7L	GCO-RE14MCC4		0.045 IN

ASPEN

2009	V8-5.7L	GCO-RE14MCC4		0.05 IN
2008-07	V8-5.7L	GCO-RE14MCC4		0.045 IN

CIRRUS

2009	L4-2.4L		GPL-3071	0.05 IN
2007	L4-2.4L	GCO-RE14MCC4		0.05 IN
2006-97	L4-2.4L Turbo	GCO-RE14MCC4		0.05 IN
2000-96	V6-2.5L	GCO-RC10YC4		0.044 IN
2000	L4-2.4L	GCO-RE14MCC4		0.05 IN
1997	L4-2.4L	GCO-RE14MCC4		0.05 IN
1996-95	L4-2.4L		GPL-3071	0.05 IN

CONCORDE

2001	V6-3.2L	GCO-UXF79 ⁽³⁾		
------	---------	--------------------------	--	--

(1) Producto nuevo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER		COBRE	PLATINO	CLBR
AÑO MOTOR				

CHRYSLER (Continúa)

CORDOBA

1982 -80	V8-5.9L	GCO-N12YC		0.035 IN
----------	---------	-----------	--	----------

CROSSFIRE

2005-04	V6-3.2L	GCO-UXF79 ⁽³⁾		
---------	---------	--------------------------	--	--

GRAND VOYAGER

2002-96	V6-3.8L	GCO-UXF79 ⁽³⁾		0.050 IN
---------	---------	--------------------------	--	----------

IMPERIAL

1991	V6-3.3L	GCO-UX79 ⁽³⁾		
------	---------	-------------------------	--	--

LEBARON

1995 -92	L4-2.5L Turbo	GCO-N12YC		0.035 IN
1993	L4-2.5L	GCO-N12YC		0.035 IN
1991	L4-2.5L Turbo	GCO-UX79 ⁽³⁾		0.035 IN
1987 -84	L4-2.2L Turbo	GCO-N12YC		0.035 IN
1987 -83	L4-2.2L	GCO-N12YC		0.035 IN
1982 -79	V8-5.9L	GCO-N12YC		0.035 IN

NEW YORKER

1994 -92	V6-3.0L	GCO-N7BYC		0.044 IN
1993 -92	L4-2.5L Turbo	GCO-N12YC		0.035 IN
1989 -85	L4-2.2L Turbo	GCO-UX79 ⁽³⁾		0.035 IN
1986 -85	L4-2.2L	GCO-UX79 ⁽³⁾		0.035 IN

PACIFICA

2020-17	V6-3.6L		GPL-9407	0.044 IN
2020-17	V6-3.6L Híbrido		GPL-9407	0.044 IN
2008	V6-4.0L	GCO-UXF79 ⁽³⁾		0.050 IN
2007	V6-3.8L	GCO-RE14MCC4		0.05 IN
2006-04	V6-3.5L	GCO-RC12MC4		0.05 IN
2005	V6-3.8L	GCO-RE14MCC4		0.05 IN

PHANTOM

1993 -92	L4-2.2L Turbo	GCO-N12YC		0.035 IN
1990	L4-2.5L Turbo	GCO-UX79 ⁽³⁾		0.035 IN
1989 -87	L4-2.2L Turbo	GCO-N12YC		0.035 IN

PT CRUISER

2009-01	L4-2.4L	GCO-RE14MCC4		0.05 IN
2008-03	L4-2.4L Turbo	GCO-RE14MCC4		0.05 IN

GONHER		COBRE	PLATINO	CLBR
AÑO MOTOR				

CHRYSLER (Continúa)

SEBRING

2000-95	V6-2.5L	GCO-RC10YC4		0.044 IN
---------	---------	-------------	--	----------

TOWN & COUNTRY

2014 -11	V6-3.6L		GPL-9407	0.044 IN
2007-00	V6-3.8L	GCO-RE14MCC4		0.05 IN
1999 -96	V6-3.8L	GCO-UX79 ⁽³⁾		0.050 IN

VOYAGER

2008-00	V6-3.3L	GCO-RE14MCC4		0.05 IN
---------	---------	--------------	--	---------

DODGE

ATOS

2012 -10	L4-1.1L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4	GPL-3346 ⁽¹⁾	0.044 IN
2009-05	L4-1.1L	GCO-RC12YC, GCO-RC10YC4	GPL-3346 ⁽¹⁾	0.04 IN, 0.044 IN
2004-01	L4-1.0L	GCO-RC12YC	GPL-3346 ⁽¹⁾	0.04 IN, 0.044 IN

ATTITUDE

2011	L4-1.4L	GCO-UXF79 ⁽³⁾	GPL-3346 ⁽¹⁾	0.044 IN
2011	L4-1.6L	GCO-UXF79 ⁽³⁾	GPL-3346 ⁽¹⁾	0.044 IN
2010	L4-1.4L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4	GPL-3346 ⁽¹⁾	0.044 IN
2010	L4-1.6L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4	GPL-3346 ⁽¹⁾	0.044 IN
2009-06	L4-1.4L	GCO-RC12YC, GCO-RC10YC4	GPL-3346 ⁽¹⁾	0.045 IN, 0.044 IN
2009-06	L4-1.6L	GCO-RC12YC, GCO-RC10YC4	GPL-3346 ⁽¹⁾	0.045 IN, 0.044 IN

AVENGER

2014 -10	L4-2.4L	GCO-RC12MCC4 ⁽¹⁾	GPL-3318 ⁽¹⁾	0.044 IN
2010 -08	L4-2.0L		GPL-3318 ⁽¹⁾	0.044 IN
2009-08	L4-2.4L	GCO-RE14MCC4, GCO-RC12MCC4 ⁽¹⁾	GPL-3318 ⁽¹⁾	0.05 IN, 0.044 IN

CALIBER

2009-08	L4-2.4L Turbo	GCO-RE14MCC4		0.05 IN
2009-07	L4-2.4L	GCO-RE14MCC4		0.05 IN

BUJÍAS

CHRYSLER

(1) Producto nuevo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

DODGE (Continúa)**CARAVAN**

1997 -96	L4-2.4L		GPL-3071	0.050 IN
1993	L4-2.5L	GCO-RN12YC		0.035 IN

CHALLENGER

2021 -11	V6-3.6L		GPL-9407	0.044 IN
2009-08	V8-6.1L	GCO-RE14MCC4		0.045 IN
2009	V8-5.7L	GCO-RE14MCC4		0.05 IN

CHARGER

2020-11	V6-3.6L		GPL-9407	0.044 IN
2009-06	V8-6.1L	GCO-RE14MCC4		0.045 IN
2009	V8-5.7L	GCO-RE14MCC4		0.05 IN
2008-06	V8-5.7L	GCO-RE14MCC4		0.045 IN
2008	V8-5.7L	GCO-REC10YC4		0.045 IN

D150

1993 -91	V6-3.9L	GCO-RN12YC		0.035 IN
----------	---------	------------	--	----------

D250

1993	V6-3.9L	GCO-RC12YC		0.035 IN
1992 -88	V8-5.9L	GCO-RN12YC		0.035 IN

D300

1980 -76	V8-5.9L	GCO-RN12YC		0.035 IN
----------	---------	------------	--	----------

D350

1992 -81	V8-5.9L	GCO-RN12YC		0.035 IN
----------	---------	------------	--	----------

DAKOTA

2012 -04	V6-3.7L	GCO-RC9MC4		0.035 IN
2003-97	V6-3.9L	GCO-RC12LC4 ⁽¹⁾		0.04 IN
2002-93	L4-2.5L	GCO-RC12YC		0.035 IN

DART

1989 -82	L4-2.2L	GCO-UXF79 ⁽³⁾		0.044 IN
1982 -79	L6-3.7L	GCO-BL15Y		0.035 IN
1980	V8-5.2L	GCO-N12YC		0.035 IN
1978	L6-3.7L	GCO-UXF79 ⁽³⁾		0.044 IN
1977 -76	L6-3.7L	GCO-N14Y		0.035 IN
1976	V8-5.9L	GCO-N12YC		0.035 IN

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

DODGE (Continúa)**DURANGO**

2021 -11	V8-5.7L	GCO-REC12MCC4 ⁽¹⁾		0.044 IN
2015 -12	V6-3.6L		GPL-9407	0.044 IN
2009	V8-5.7L	GCO-RE14MCC4		0.05 IN
2009	V8-5.7L Híbrido	GCO-RE14MCC4		0.045 IN
2008-04	V8-5.7L	GCO-RE14MCC4		0.045 IN
2003-98	V8-5.9L	GCO-RC12MC4		0.04 IN
2000-98	V8-5.2L	GCO-RC12MC4, GCO-RC12LC4 ⁽¹⁾		0.04 IN

GRAND CARAVAN

2020-11	V6-3.6L		GPL-9407	0.044 IN
---------	---------	--	----------	----------

H100

2005-03	L4-2.4L	GCO-RN9YC		0.04 IN
---------	---------	-----------	--	---------

I10

2014 -12	L4-1.1L		GPL-3071	0.044 IN
----------	---------	--	----------	----------

JOURNEY

2020-12	L4-2.4L	GCO-RC12MCC4 ⁽¹⁾		0.044 IN
2019 -11	V6-3.6L		GPL-9407	0.044 IN
2011	L4-2.4L	GCO-UXF79 ⁽³⁾ , GCO-RC12MCC4 ⁽¹⁾		0.035 IN, 0.044 IN
2010	L4-2.4L	GCO-UXF79 ⁽³⁾ , GCO-RC12MCC4 ⁽¹⁾ , GCO-RC12MC4		0.035 IN, 0.044 IN
2009	L4-2.4L	GCO-RC9MC4, GCO-RC12MCC4 ⁽¹⁾		0.045 IN, 0.044 IN

MONACO

1977 -75	V8-5.2L	GCO-N12YC		0.035 IN
1970 -69	V8-5.2L	GCO-N12YC		0.035 IN

NEON

2005-03	L4-2.4L Turbo	GCO-RE14MCC4		0.05 IN
2005-95	L4-2.0L	GCO-UXF79 ⁽³⁾		0.035 IN

NITRO

2012 -11	V6-3.7L	GCO-RC9MC4		0.035 IN
2010	V6-3.7L	GCO-UXF79 ⁽³⁾ , GCO-RC9MC4		0.044 IN, 0.035 IN

(1) Producto nuevo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			
DODGE (Continúa)				
NITRO (Continúa)				
2009-07	V6-3.7L	GCO-RC9MC4		0.035 IN
RAM 1500				
2009-03	V6-3.7L	GCO-RC9MC4		0.035 IN
2008-07	V8-4.7L	GCO-UXF79 ⁽³⁾		0.040 IN
2002-97	V6-3.9L	GCO-UXF79 ⁽³⁾ , GCO-RC12LC4 ⁽¹⁾		0.035 IN, 0.04 IN
2001-97	V8-5.2L	GCO-UXF79 ⁽³⁾		0.040 IN
1996-94	V6-3.9L	GCO-RC12YC	GPL-3071	0.035 IN
1996-94	V8-5.2L	GCO-RC12YC	GPL-3071	0.035 IN
1996-94	V8-5.9L	GCO-RC12YC	GPL-3071	0.035 IN
RAM 2500				
2010-09	V8-5.7L	GCO-REC12MCC4 ⁽¹⁾		0.044 IN
2009-02	V8-4.7L	GCO-UXF79 ⁽³⁾		0.040 IN
1997	V8-5.9L	GCO-RC12YC, GCO-UXF79 ⁽³⁾		0.035 IN
1996-95	V8-5.9L	GCO-RC12YC, GCO-UXF79 ⁽³⁾	GPL-3071	0.035 IN
1996-94	V10 8.0L	GCO-RC12YC		0.045 IN
1996-94	V8-5.2L	GCO-RC12YC	GPL-3071	0.035 IN
1996-94	V8-5.9L	GCO-RC12YC, GCO-UXF79 ⁽³⁾	GPL-3071	0.035 IN, 0.035 IN
RAM 2500 VAN				
1997-96	V8-5.2L	GCO-RC12YC	GPL-3071	0.035 IN
RAM 3500				
2009	V8-5.7L	GCO-RE14MCC4		0.045 IN
2006-03	V8-5.7L	GCO-RE14MCC4		0.045 IN
1997-94	V8-5.9L	GCO-RC12YC, GCO-UXF79 ⁽³⁾	GPL-3071	0.035 IN
1997-94	V8-5.9L	GCO-RC12YC, GCO-UXF79 ⁽³⁾	GPL-3071	0.035 IN, 0.035 IN
RAM 3500 VAN				
1997	V8-5.9L	GCO-RC12YC	GPL-3071	0.035 IN
RAMCHARGER				
1996-94	V8-5.9L	GCO-RC12YC		0.040 IN

(1) Producto nuevo, (3) 4 Electrodo

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			
DODGE (Continúa)				
ROYAL MONACO				
1977	V8-5.9L	GCO-N12YC		0.040 IN
SHADOW				
1994-93	L4-2.2L	GCO-RN12YC, GCO-UXF79 ⁽³⁾		0.035 IN
1994-93	L4-2.5L	GCO-RN12YC, GCO-UXF79 ⁽³⁾		0.035 IN
STRATUS				
2006-98	L4-2.4L Turbo	GCO-RC12YC		0.045 IN
2006-95	L4-2.0L	GCO-UXF79 ⁽³⁾		0.035 IN
2006-95	L4-2.4L	GCO-RC12YC		0.045 IN
VAN 1000				
2009-08	L4-2.4L	GCO-RE14MCC4		0.05 IN
VERNA				
2006-04	L4-1.5L	GCO-RC12YC, GCO-RC10YC4		0.045 IN, 0.044 IN
2006-04	L4-1.6L	GCO-RC12YC, GCO-RC10YC4		0.045 IN, 0.044 IN
VIPER				
2006-04	V10 8.3L	GCO-RC9MC4		0.045 IN
2000	V10 8.0L	GCO-RC12MC4		0.045 IN
W250				
1993	V8-5.9L	GCO-RN12YC		0.035 IN
FAW				
F1				
2008	L3-1.0L	GCO-UXF79 ⁽³⁾		
F4				
2008	L4-1.4L	GCO-UXF79 ⁽³⁾		
FIAT				
500L				
2019-15	L4-1.4L Turbo	GCO-RA7YC		0.028 IN
ALBEA				
2009	L4-1.8L	GCO-RN9YC		0.04 IN
IDEA				
2009-08	L4-1.8L	GCO-RN9YC		0.035 IN

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

FIAT (Continúa)**PALIO**

2008-06	L4-1.8L	GCO-RN9YC		0.035 IN
2005-04	L4-1.6L	GCO-UXF79 ⁽³⁾		0.035 IN

STILO

2007	L5-2.4L	GCO-RC9YC		0.035 IN
------	---------	-----------	--	----------

STRADA

2008	L4-1.8L	GCO-RN9YC		0.032 IN
2007	L4-1.8L	GCO-UX79 ⁽³⁾		0.032 IN

FORD**AEROSTAR**

1997-95	V6-3.0L		GPL-3013	0.054 IN
1997-93	V6-4.0L		GPL-3013	0.044 IN
1995-94	V6-4.0L		GPL-3013	0.054 IN
1993-91	V6-3.0L		GPL-3013	0.054 IN

CLUB WAGON

1998-97	V8-5.4L	GCO-RS9YCC		0.054 IN
1996-95	V8-5.8L	GCO-BL15Y		0.044 IN

CONTOUR

2000-95	L4-2.0L		GPL-7437	0.054 IN
2000-95	V6-2.5L	GCO-RS9YCC		0.054 IN

COURIER

2007-01	L4-1.6L	GCO-RES9YCC4		0.05 IN
---------	---------	--------------	--	---------

CROWN VICTORIA

1995-93	V8-4.6L		GPL-3013	0.054 In
---------	---------	--	----------	----------

E-150

2004	V8-4.6L	GCO-RS9YCC		0.054 IN
2003-02	V6-4.2L	GCO-RS14LC		0.054 In

ECONOLINE

2004	V8-4.6L	GCO-RS9YCC		0.054 IN
------	---------	------------	--	----------

ECOSPORT

2011-04	L4-2.0L	GCO-RS9YCC		0.05 IN
---------	---------	------------	--	---------

EDGE

2009-07	V6-3.5L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

FORD (Continúa)**ESCAPE**

2019-09	L4-2.5L		GPL-7437	0.052 IN
2009-01	V6-3.0L	GCO-RS9YCC		0.054 IN

ESCORT

2003-97	L4-2.0L		GPL-7437	
1996-93	L4-1.8L	GCO-RC12YC		0.05 IN
1996-93	L4-1.9L	GCO-RS9YCC		0.054 IN

EXCURSION

2005-00	V10 6.8L	GCO-RS9YCC		0.054 IN
---------	----------	------------	--	----------

EXPEDITION

2009-97	V8-5.4L	GCO-RS9YCC		0.054 IN
2004	V8-4.6L	GCO-RS9YCC		0.054 IN
2003-97	V8-4.6L		GPL-3013	0.054 IN

EXPLORER

2009-02	V8-4.6L	GCO-RS9YCC		0.054 IN
2009-97	V6-4.0L	GCO-RS9YCC		0.054 IN
2009-91	V6-4.0L		GPL-3013	0.054 IN
2001-96	V8-5.0L	GCO-RS9YCC		0.054 IN

F-100 RANGER

2001-96	V6-3.0L	GCO-RS9YCC, GCO-RS12YC ⁽¹⁾		0.054 IN, 0.044 IN
---------	---------	--	--	-----------------------

F-150

2021-18	V6-3.3L		GPL-7437	0.052 IN
2009-98	V6-4.2L	GCO-RS14LC		0.054 In
1997	V8-4.6L	GCO-RS9YCC		0.054 IN

F-350

1993	V8-5.8L	GCO-F11Y		0.044 In
1990-89	V8-5.8L	GCO-F11Y		0.044 In

FIESTA

2001-98	L4-1.3L	GCO-RS9YCC		0.04 IN
---------	---------	------------	--	---------

FIVE HUNDRED

2007-05	V6-3.0L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

(1) Producto nuevo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO MOTOR				

FORD (Continúa)

FOCUS

2010	L4-2.0L	GCO-RS14LC		0.054 IN
2009-06	L4-2.0L	GCO-RS9YCC		0.054 IN
2009-00	L4-2.0L		GPL-7437	0.05 IN
2000	L4-2.0L	GCO-RS9YCC		0.05 IN

FOCUS ST

2011 -07	L5-2.5L Turbo		GPL-REC8PYB ⁽¹⁾	0.032 IN
----------	---------------	--	----------------------------	----------

FREESTAR

2007-04	V6-4.2L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

FUSION

2020-17	L4-2.0L Híbrido		GPL-7437	0.052 IN
2009-07	L4-2.3L	GCO-RS9YCC		0.054 IN
2009-06	V6-3.0L	GCO-RS9YCC		0.054 IN

GHIA

1991	L4-2.3L		GPL-3013	0.054 IN
------	---------	--	----------	----------

GRAND MARQUIS

2004-95	V8-4.6L		GPL-3013	0.054 IN
---------	---------	--	----------	----------

IKON

2007-03	L4-1.6L	GCO-RES9YCC4		0.054 IN
---------	---------	--------------	--	----------

KA

2008-03	L4-1.6L	GCO-RES9YCC4		0.05 IN
---------	---------	--------------	--	---------

LOBO

2009-04	V8-4.6L	GCO-RS9YCC		0.054 IN
2006-04	V8-5.4L	GCO-RS9YCC		0.054 IN
1997	V8-4.6L	GCO-RS9YCC		0.054 IN

MONDEO

2007-02	V6-2.5L	GCO-RS9YCC		0.04 IN
2007	L4-2.0L		GPL-7437	0.054 IN
2006-01	L4-2.0L	GCO-RS9YCC		0.04 IN
2001	V6-2.5L	GCO-RS9YCC		0.054 IN

MUSTANG

2009-05	V8-4.6L		GPL-3013	0.054 IN
2004-03	V8-4.6L	GCO-RES9YCC4		0.054 IN
2004-03	V8-4.6L	GCO-RES9YCC4	GPL-3013	0.054 IN

GONHER®		COBRE	PLATINO	CLBR
AÑO MOTOR				

FORD (Continúa)

MUSTANG (Continúa)

2002-01	V8-4.6L		GPL-3013	0.054 IN
2000-96	V8-4.6L	GCO-RES9YCC4		0.054 IN
1995 -94	V8-5.0L	GCO-BL15Y		0.054 IN
1984 -80	V8-5.0L		GPL-3013	0.044 IN

P-350

1997 -92	V8-5.8L	GCO-BL15Y		0.044 IN
----------	---------	-----------	--	----------

RANGER

2012	L4-2.3L	GCO-RS12YC ⁽¹⁾		0.052 IN
2011 -10	L4-2.3L	GCO-RS9YCC, GCO-RS12YC ⁽¹⁾		0.054 IN, 0.052 IN
2009	L4-2.3L	GCO-RES9YCC4, GCO-RS12YC ⁽¹⁾ , GCO-RS9YCC		0.054 IN, 0.052 IN
2008-07	V6-3.0L	GCO-RS9YCC		0.054 IN
2008-01	L4-2.3L	GCO-RES9YCC4, GCO-RS12YC ⁽¹⁾		0.054 IN, 0.052 IN
2006-93	V6-3.0L	GCO-RS9YCC, GCO-RS12YC ⁽¹⁾		0.054 IN, 0.044 IN
1997	L4-2.3L		GPL-3013	0.054 IN
1996 -93	L4-2.3L	GCO-RES9YCC4		0.054 IN
1992 -91	V6-3.0L	GCO-RS12YC ⁽¹⁾		0.044 IN

TAURUS

1995 -93	V6-3.8L	GCO-RS9YCC		0.054 IN
1991	V6-3.8L	GCO-RS14LC		0.054 IN
1990	V6-3.8L	GCO-RS9YCC		0.054 IN
1988	V6-3.8L	GCO-RS9YCC		0.054 IN

THUNDERBIRD

2005-02	V8-3.9L		GPL-3013	0.045 IN
1997 -95	V6-3.8L	GCO-RS9YCC		0.054 IN
1995	V8-4.6L	GCO-RS9YCC		0.054 IN
1994 -89	V6-3.8L	GCO-RS14LC		0.054 IN
1988 -85	V6-3.8L	GCO-RS9YCC		0.054 IN

BUJÍAS

FORD

(1) Producto nuevo

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

FORD (Continúa)**TOPAZ**

1994 -89	L4-2.3L	GCO-RS9YCC		0.054 IN
----------	---------	------------	--	----------

WINDSTAR

2003-97	V6-3.8L		GPL-3013	0.054 IN
1996 -95	V6-3.8L	GCO-RS14LC		0.054 IN

GEO**TRACKER**

1995 -94	L4-1.6L		GPL-3071	0.032 IN
----------	---------	--	----------	----------

GMC**ACADIA**

2009-07	V6-3.6L	GCO-RS9YCC		0.06 IN
---------	---------	------------	--	---------

CANYON

2009-07	L5-3.7L		GPL-7437	0.06 IN
---------	---------	--	----------	---------

K1500

1999 -96	V8-5.7L		GPL-3013	0.060 IN
1997 -96	V8-5.0L		GPL-3013	0.060 IN

K2500

1999 -96	V8-5.7L		GPL-3013	0.060 IN
----------	---------	--	----------	----------

K3500

2000-96	V8-5.7L		GPL-3013	0.060 IN
---------	---------	--	----------	----------

SAVANA 1500

2002	V8-5.0L		GPL-3013	0.060 IN
------	---------	--	----------	----------

SAVANA 2500

2002	V8-5.0L		GPL-3013	0.060 IN
------	---------	--	----------	----------

SIERRA

2009-08	V8-6.2L	GCO-RS9YCC		0.06 IN
2009-07	V8-5.3L	GCO-RS9YCC		0.06 IN

SIERRA 1500

2007-99	V6-4.3L		GPL-3013	0.060 IN
---------	---------	--	----------	----------

TERRAIN

2013	V6-3.6L		GPL-7437	0.044 IN
------	---------	--	----------	----------

YUKON

2009-07	V8-6.2L	GCO-RS9YCC		0.06 IN
2009-00	V8-5.3L	GCO-RS9YCC		0.06 IN

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

HONDA**ACCORD**

2016 -10	L4-2.4L		GPL-9407	0.044 IN
2009-08	L4-2.4L	GCO-RC12MC4	GPL-9407	0.045 IN, 0.044 IN
2009-08	V6-3.5L	GCO-RC12MC4		0.045 IN
2007-03	L4-2.4L	GCO-RC12MC4		0.045 IN
2007-99	V6-3.0L	GCO-RC12MC4		0.045 IN
2002-98	L4-2.3L	GCO-UXF79 ⁽³⁾		0.044 IN

CITY

2020-15	L4-1.5L	GCO-RC8YC4 ⁽¹⁾		0.052 IN
2010	L4-1.5L	GCO-RC12MC4		0.052 IN
2010	L4-1.5L	GCO-RC9YC		0.052 IN

CIVIC

2015 -07	L4-1.8L		GPL-9407	0.044 IN
2009-07	L4-1.3L Híbrido	GCO-RC12MC4		0.040 IN
2009-06	L4-1.8L	GCO-RC9MC4	GPL-9407	0.035 IN, 0.044 IN
2005-01	L4-1.7L	GCO-RC9MC4	GPL-3318 ⁽¹⁾	0.035 IN, 0.044 IN
2000-93	L4-1.6L	GCO-RC12YC		0.045 IN

CR-V

2017	L4-2.4L	GCO-REA8MCX		0.044 IN
2016 -10	L4-2.4L		GPL-9407	0.044 IN
2009	L4-2.4L	GCO-UXF79 ⁽³⁾ , GCO-RC9MC4		0.044 IN, 0.035 IN
2008-07	L4-2.4L	GCO-RC9MC4		0.035 IN
2006-02	L4-2.4L	GCO-UXF79 ⁽³⁾ , GCO-RC9MC4		0.044 IN, 0.035 IN

CR-Z

2013	L4-1.5L Híbrido	GCO-RC9YC		0.044 IN
------	-----------------	-----------	--	----------

FIT

2009-06	L4-1.5L	GCO-UXF79 ⁽³⁾		0.044 IN
---------	---------	--------------------------	--	----------

(1) Producto nuevo, (3) 4 Electroodos

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

HONDA (Continúa)

HR-V

2017 -16	L4-1.8L		GPL-9407	0.044 IN
----------	---------	--	----------	----------

ODYSSEY

2017 -11	V6-3.5L		GPL-9407	0.044 IN
2009-05	V6-3.5L	GCO-RC12MC4		0.045 IN
2004-02	V6-3.5L	GCO-UXF79 ⁽³⁾		0.044 IN
2001-99	V6-3.5L	GCO-RC12MC4		0.045 IN

PASSPORT

1995 -94	V6-3.2L	GCO-RC12YC	GPL-3071	0.044 IN
----------	---------	------------	----------	----------

PILOT

2017 -09	V6-3.5L		GPL-9407	0.044 IN
2008-03	V6-3.5L	GCO-UXF79 ⁽³⁾		0.044 IN

RIDGELINE

2014 -09	V6-3.5L		GPL-9407	0.044 IN
----------	---------	--	----------	----------

HUMMER

H2

2007-05	V8-6.0L	GCO-RS9YCC		0.06 IN
---------	---------	------------	--	---------

H3

2009-08	V8-5.3L	GCO-RS9YCC		0.06 IN
2009-07	L5-3.7L		GPL-7437	0.06 IN

HYUNDAI

ELANTRA

2017	L4-2.0L		GPL-9407	0.044 IN
2015	L4-1.8L		GPL-9407	0.044 IN

TUCSON

2017	L4-2.0L		GPL-9407	0.044 IN
------	---------	--	----------	----------

INFINITI

I30

2001-98	V6-3.0L		GPL-3071	0.044 IN
---------	---------	--	----------	----------

I35

2003-02	V6-3.5L	GCO-REC10YC4		0.044 IN
---------	---------	--------------	--	----------

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

INFINITI (Continúa)

Q45

2002	V8-4.5L		GPL-3071	0.044 IN
1997	V8-4.1L	GCO-RC12YC		0.045 IN
1995 -94	V8-4.5L		GPL-3071	0.044 IN

JAGUAR

S-TYPE

2006-05	V8-4.2L	GCO-RC10YC4		0.044 IN
2002-99	V8-4.0L	GCO-UXF79 ⁽³⁾		

XF

2009	V8-4.2L	GCO-RC10YC4	GPL-3071	0.050 IN
------	---------	-------------	----------	----------

XJ8

2009	V8-4.2L	GCO-RC10YC4	GPL-3071	0.050 IN
2005	V8-4.2L	GCO-RC10YC4		0.044 IN
2002-00	V8-4.0L	GCO-RC10YC4		0.044 IN
1999	V8-4.0L	GCO-RC10YC4	GPL-3071	0.050 IN
1998	V8-4.0L	GCO-RC10YC4		0.044 IN

XJR

2002-99	V8-4.0L	GCO-RC10YC4		0.044 IN
---------	---------	-------------	--	----------

XKR

2006	V8-4.2L	GCO-RC10YC4		0.044 IN
------	---------	-------------	--	----------

JEEP

CHEROKEE

2020-14	V6-3.2L		GPL-9407	0.044 IN
2014	L4-2.4L	GCO-REC10YC4		0.045 IN

COMMANDER

2009	V8-5.7L	GCO-RE14MCC4		0.05 IN
2008-06	V8-4.7L	GCO-RC12MC4		0.045 IN
2008-06	V8-5.7L	GCO-RE14MCC4		0.045 IN

COMPASS

2009-07	L4-2.4L	GCO-RE14MCC4		0.05 IN
2009	L4-2.4L	GCO-RC12MC4		0.043 IN
2007	L4-2.0L	GCO-RC12MC4		0.043 IN

GLADIATOR

2021 -20	V6-3.6L		GPL-9407	0.044 IN
----------	---------	--	----------	----------

BUJÍAS

HONDA

(3) 4 Electrodo

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

JEEP (Continúa)**GRAND CHEROKEE**

2021 -20	V6-3.6L		GPL-9407	0.044 IN
2017 -11	V6-3.6L		GPL-9407	0.044 IN
2010	V8-6.1L	GCO-RE14MCC4		0.045 IN
2009-08	V8-4.7L	GCO-UXF79 ⁽³⁾		0.040 IN
2009-05	V6-3.7L	GCO-RC9MC4		0.035 IN
2009-05	V8-5.7L	GCO-RE14MCC4		0.045 IN
2009	V8-6.1L	GCO-RE14MCC4		0.05 IN
2008-06	V8-6.1L	GCO-RE14MCC4		0.045 IN
2008	V8-5.7L	GCO-REC10YC4		0.045 IN
2007	V8-4.7L	GCO-UXF79 ⁽³⁾ , GCO-RC12MCC4 ⁽¹⁾ , GCO-RC12MC4		0.040 IN, 0.04 IN, 0.045 IN
2006-05	V8-4.7L	GCO-RC12MC4, GCO-RC12MCC4 ⁽¹⁾		0.045 IN, 0.04 IN
2004-99	V8-4.7L	GCO-UXF79 ⁽³⁾ , GCO-RC12MCC4 ⁽¹⁾		0.040 IN, 0.04 IN
1999	L6-4.0L	GCO-UXF79 ⁽³⁾		0.035 IN
1998	V8-5.2L	GCO-RC12LC4 ⁽¹⁾ , GCO-UXF79 ⁽³⁾		0.044 IN, 0.040 IN
1998	V8-5.9L		GPL-3071	0.035 IN
1997	V8-5.2L	GCO-RC12LC4 ⁽¹⁾	GPL-3071	0.044 IN, 0.035 IN
1996-93	V8-5.2L		GPL-3071	0.035 IN

LIBERTY

2012	V6-3.7L	GCO-RC9MC4		0.035 IN
2011 -10	V6-3.7L	GCO-UXF79 ⁽³⁾ , GCO-RC9MC4		0.044 IN, 0.035 IN
2009-02	V6-3.7L	GCO-RC9MC4		0.035 IN

PATRIOT

2017 -12	L4-2.4L		GPL-3318 ⁽¹⁾	0.044 IN
2011 -07	L4-2.4L	GCO-RC9MC4	GPL-3318 ⁽¹⁾	0.044 IN

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

JEEP (Continúa)**WRANGLER**

2021 -20	V6-3.6L		GPL-9407	0.044 IN
2017 -12	V6-3.6L		GPL-9407	0.044 IN
2009-07	V6-3.8L		GPL-7437	0.054 IN
2006-05	L6-4.0L	GCO-RC12MC4, GCO-RC12YC		0.045 IN, 0.04 IN
2006-97	L6-4.0L	GCO-RC12YC		0.04 IN
2002-97	L4-2.5L	GCO-RC12MC4		0.04 IN
1995 -93	L4-2.5L	GCO-RC12YC		0.035 IN
1995 -93	L6-4.0L	GCO-RC12YC		0.04 IN

KIA**FORTE**

2017	L4-2.0L		GPL-9407	0.044 IN
------	---------	--	----------	----------

RIO

2016	L4-1.6L		GPL-9407	0.044 IN
------	---------	--	----------	----------

SORENTO

2017 -16	L4-2.4L		GPL-9407	0.044 IN
----------	---------	--	----------	----------

SOUL

2017 -16	L4-2.0L		GPL-9407	0.044 IN
----------	---------	--	----------	----------

SPORTAGE

2017	L4-2.4L	GCO-REC10YC4		0.044 IN
------	---------	--------------	--	----------

LAND ROVER**LR2**

2012 -08	L6-3.2L	GCO-REC10YC4		
----------	---------	--------------	--	--

LR3

2008-06	V8-4.4L	GCO-UXF79 ⁽³⁾		
---------	---------	--------------------------	--	--

LR4

2013 -10	V8-5.0L	GCO-REC10YC4		
----------	---------	--------------	--	--

RANGE ROVER

2009-06	V8-4.4L	GCO-UXF79 ⁽³⁾		
2001-99	V8-4.6L		GPL-3071	0.04 IN

LINCOLN**AVIATOR**

2005-03	V8-4.6L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

BLACKWOOD

2003-02	V8-5.4L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

(1) Producto nuevo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

LINCOLN (Continúa)

CONTINENTAL

2002-95	V8-4.6L		GPL-3013	0.054 IN
---------	---------	--	----------	----------

LS

2006-00	V8-3.9L		GPL-3071	0.044 IN
---------	---------	--	----------	----------

MARK LT

2007-06	V8-5.4L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

MARK VIII

1998-97	V8-4.6L		GPL-3013	0.054 IN
1996	V8-4.6L		GPL-3013	0.05 IN
1995-93	V8-4.6L		GPL-3013	0.054 IN

MKX

2009-07	V6-3.5L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

NAVIGATOR

2009	V8-5.4L		GPL-3013	0.054 IN
2009	V8-5.4L	GCO-RS9YCC	GPL-3013	0.054 IN
2008-05	V8-5.4L	GCO-RS9YCC		0.054 IN
2005-98	V8-5.4L		GPL-3013	0.054 IN

TOWN CAR

2009	V8-4.6L		GPL-3013	0.054 IN
2007-92	V8-4.6L		GPL-3013	0.054 IN
1991	V8-4.6L	GCO-RS9YCC		0.054 IN

ZEPHYR

2006	V6-3.0L	GCO-RS9YCC		0.054 IN
------	---------	------------	--	----------

MAZDA

2

2017-15	L4-1.5L	GCO-RC10YC4		0.044 IN
2014-12	L4-1.5L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4		0.044 IN
2012	L4-1.5L	GCO-RC12YC, GCO-UXF79 ⁽³⁾ , GCO-RC10YC4		0.044 IN

3

2017-14	L4-2.0L	GCO-REA8MCX		0.044 IN
2010-06	L4-2.0L		GPL-7437	
2009-08	L4-2.3L Turbo		GPL-7437	
2009-06	L4-2.3L		GPL-7437	

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

MAZDA (Continúa)

5

2009-06	L4-2.3L		GPL-7437	
---------	---------	--	----------	--

6

2008-03	L4-2.3L		GPL-7437	
2008-03	V6-3.0L		GPL-7437	

CX-5

2015-13	L4-2.0L	GCO-REA8MCX		0.044 IN
---------	---------	-------------	--	----------

CX-7

2009-07	L4-2.3L Turbo		GPL-7437	0.05 IN
---------	---------------	--	----------	---------

CX-9

2007	V6-3.5L		GPL-7437	0.05 IN
------	---------	--	----------	---------

MX-5

2008-06	L4-2.0L		GPL-7437	0.055 IN
---------	---------	--	----------	----------

MERCEDES-BENZ

A160

2005-04	L4-1.6L		GPL-3071	
2001-00	L4-1.6L		GPL-3071	

A190

2005-04	L4-1.9L		GPL-3071	
2001	L4-1.9L		GPL-3071	

C220

1997-95	L4-2.2L		GPL-3071	
---------	---------	--	----------	--

C230

2000-96	L4-2.3L		GPL-3071	
---------	---------	--	----------	--

C240

2002-01	V6-2.6L		GPL-3071	
---------	---------	--	----------	--

C280

2000-99	V6-2.8L	GCO-RC12YC		
1998-95	L6-2.8L	GCO-UXF79 ⁽³⁾		

C32 AMG

2004-02	V6-3.2L		GPL-3071	
---------	---------	--	----------	--

C320

2005-01	V6-3.2L		GPL-3071	
---------	---------	--	----------	--

C36 AMG

1997-96	L6-3.6L	GCO-UXF79 ⁽³⁾		
---------	---------	--------------------------	--	--

C43 AMG

2000-98	V8-4.3L	GCO-RC12YC		
---------	---------	------------	--	--

CLK320

2003-98	V6-3.2L	GCO-RC12YC		
---------	---------	------------	--	--

E280

1999	V6-2.8L	GCO-RC12YC		
------	---------	------------	--	--

BUJÍAS

LINCOLN

(3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

MERCEDES-BENZ (Continúa)**E420**

1997	V8-4.2L	GCO-RC12YC		
1995	V8-4.2L	GCO-RC12YC		

E430

2001	V8-4.3L		GPL-3071	
------	---------	--	----------	--

G65 AMG

2018-14	V12 6.0L Turbo	GCO-RC10YC4		0.044 IN
---------	----------------	-------------	--	----------

ML320

2002-98	V6-3.2L	GCO-RC12YC		
---------	---------	------------	--	--

S430

2003-01	V8-4.3L	GCO-RC12YC		
---------	---------	------------	--	--

S500

2002-96	V8-5.0L	GCO-RC12YC		
---------	---------	------------	--	--

S600

1998-96	V12 6.0L	GCO-RC12YC		
---------	----------	------------	--	--

S600L

1995	V12 6.0L	GCO-RC12YC		
------	----------	------------	--	--

SL320

1997-96	L6-3.2L	GCO-RC12YC		
---------	---------	------------	--	--

SL500

2003-96	V8-5.0L	GCO-RC12YC		
---------	---------	------------	--	--

SL55 AMG

2002	V8-5.0L	GCO-RC12YC		
------	---------	------------	--	--

SL600

2002-96	V12 6.0L	GCO-RC12YC		
---------	----------	------------	--	--

SL65 AMG

2019-13	V12 6.0L Turbo	GCO-RC10YC4		0.044 IN
---------	----------------	-------------	--	----------

SLK230

2004-01	L4-2.3L		GPL-3071	
1998-97	L4-2.3L		GPL-3071	

MERCURY**MARINER**

2009-05	V6-3.0L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

MILAN

2009-06	V6-3.0L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

MONTEGO

2007-05	V6-3.0L	GCO-RS9YCC		0.054 IN
---------	---------	------------	--	----------

SABLE

2004-03	V6-3.0L		GPL-3013	0.054 IN
---------	---------	--	----------	----------

(3) 4 Electrodo

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

MERCURY (Continúa)**TOPAZ**

1994-93	L4-2.3L		GPL-3013	0.045 IN
---------	---------	--	----------	----------

MINI**COOPER**

2003-02	L4-1.6L	GCO-UXF79 ⁽³⁾		
---------	---------	--------------------------	--	--

MITSUBISHI**ASX**

2013	L4-2.0L	GCO-RC9YC		0.044 IN
------	---------	-----------	--	----------

ECLIPSE

2012-11	V6-3.8L	GCO-RC10YC4		0.044 IN
2009-08	V6-3.8L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN
2007-06	V6-3.8L		GPL-3071	0.045 IN
2005-03	V6-3.0L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN
2002-00	V6-3.0L		GPL-3071	0.045 IN

ENDEAVOR

2011-10	V6-3.8L	GCO-RC10YC4		0.044 IN
2009-04	V6-3.8L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN

GALANT

2009-05	L4-2.4L		GPL-3071	0.045 IN
2009	V6-3.8L		GPL-3071	0.045 IN
2007-04	V6-3.8L		GPL-3071	0.045 IN
2004	L4-2.4L		GPL-3071	0.044 IN
2003-94	L4-2.4L		GPL-3071	0.045 IN
2003	V6-3.0L	GCO-RC10YC4		0.044 IN
2003	V6-3.0L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN
2002-99	V6-3.0L		GPL-3071	0.045 IN

GRANDIS

2009-07	L4-2.4L		GPL-3071	0.045 IN
---------	---------	--	----------	----------

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO MOTOR				

MITSUBISHI (Continúa)

LANCER

2010	L4-2.0L	GCO-UXF79 ⁽³⁾		
2010	L4-2.4L	GCO-RC12YC		0.045 IN
2009-08	L4-2.0L	GCO-RC12YC		0.045 IN
2009	L4-2.4L		GPL-3071	0.045 IN
2007-04	L4-2.0L	GCO-RC12YC, GCO-RC10YC4		0.045 IN, 0.044 IN
2007	L4-2.0L	GCO-RC10YC4		0.044 IN
2006-05	L4-2.4L		GPL-3071	0.045 IN
2006-04	L4-2.0L Turbo	GCO-RC12YC, GCO-RC10YC4		0.045 IN, 0.044 IN
2004	L4-2.0L	GCO-RC10YC4		0.044 IN
2004	L4-2.0L	GCO-RC9YC, GCO-RC10YC4		0.045 IN, 0.044 IN

MONTERO

2019-08	V6-3.8L	GCO-RC10YC4		0.044 IN
2006-05	V6-3.8L	GCO-RC10YC4		0.044 IN
2006-05	V6-3.8L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN
2004	V6-3.8L	GCO-RC10YC4 ⁽³⁾		0.044 IN
2004	V6-3.8L	GCO-RC10YC4		0.044 IN
2003	V6-3.8L	GCO-RC10YC4 ⁽³⁾		0.044 IN
2003	V6-3.8L	GCO-RC10YC4		0.044 IN

MONTERO SPORT

2006-03	V6-3.5L	GCO-RC10YC4		0.044 IN
---------	---------	-------------	--	----------

OUTLANDER

2016-14	L4-2.4L		GPL-9407	0.044 IN
2013-10	L4-2.4L	GCO-RC10YC4		0.044 IN
2009-08	L4-2.4L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN
2009-07	V6-3.0L		GPL-3071	0.045 IN

(3) 4 Electrodo

GONHER®		COBRE	PLATINO	CLBR
AÑO MOTOR				

MITSUBISHI (Continúa)

SPACE STAR

2004	L4-1.8L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4		0.044 IN
2003	L4-1.8L	GCO-RC10YC4		0.044 IN

NISSAN

200SX

1997 -95	L4-2.0L	GCO-RC12YC	GPL-3071	0.044 IN
----------	---------	------------	----------	----------

240SX

1998	L4-2.4L		GPL-3071	0.044 IN
1993	L4-2.4L		GPL-3071	0.044 IN

300ZX

1996	V6-3.0L		GPL-3071	0.044 IN
1996	V6-3.0L Turbo		GPL-3071	0.044 IN
1995 -91	V6-3.0L	GCO-UXF79 ⁽³⁾		
1995	V6-3.0L Turbo	GCO-UXF79 ⁽³⁾		

350Z

2008-04	V6-3.5L		GPL-7437	0.05 IN
---------	---------	--	----------	---------

ALMERA

2005-01	L4-1.8L	GCO-REC10YC4		0.05 IN
---------	---------	--------------	--	---------

ALTIMA

2016 -07	V6-3.5L	GCO-REA8MCX		0.044 IN
2009-07	L4-2.5L Híbrido	GCO-REC10YC4		0.05 IN
2009-02	L4-2.5L	GCO-REC10YC4		0.05 IN
2001	L4-2.4L	GCO-REC10YC4		0.05 IN
2000	L4-2.4L	GCO-UXF79 ⁽³⁾		0.044 IN
1999 -93	L4-2.4L		GPL-3071	0.044 IN

APRIO

2010-08	L4-1.6L	GCO-UXF79 ⁽³⁾		0.040 IN
---------	---------	--------------------------	--	----------

ARMADA

2009-05	V8-5.6L		GPL-7437	0.05 IN
---------	---------	--	----------	---------

FRONTIER

2008-06	L4-2.4L	GCO-UXF79 ⁽³⁾		0.044 IN
2004-99	V6-3.3L		GPL-3071	0.044 IN
2004-98	L4-2.4L	GCO-UXF79 ⁽³⁾		0.044 IN

BUJÍAS

MITSUBISHI

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

NISSAN (Continúa)**HIKARI**

1992 -88	L4-1.6L	GCO-N12YC		0.045 IN
1992 -88	L4-1.6L Turbo	GCO-N12YC		0.045 IN

ICHI VAN

1994 -91	L4-2.4L	GCO-N12YC		0.044 IN
----------	---------	-----------	--	----------

KICKS

2017	L4-1.6L	GCO-REA8MCX		0.044 IN
------	---------	-------------	--	----------

LUCINO

2000-96	L4-1.6L		GPL-3071	0.044 IN
2000	L4-2.0L		GPL-3071	0.044 IN
1999-96	L4-2.0L	GCO-UXF79 ⁽³⁾		0.044 IN

MARCH

2017 -13	L4-1.6L	GCO-REA8MCX		0.044 IN
2012	L4-1.6L	GCO-UXF79 ⁽³⁾ , GCO-REA8MCX		0.044 IN

MAXIMA

2007-04	V6-3.5L		GPL-7437	0.05 IN
2001-96	V6-3.0L		GPL-3071	0.044 IN
1995	V6-3.0L	GCO-RC12YC		0.045 IN
1993 -91	V6-3.0L	GCO-RC12YC		0.045 IN

MICRA

2007-05	L4-1.4L	GCO-REC10YC4		0.044 IN
---------	---------	--------------	--	----------

MURANO

2007-04	V6-3.5L		GPL-7437	0.05 IN
---------	---------	--	----------	---------

NP300

2015 -10	L4-2.4L	GCO-RC12YC	GPL-3071	0.044 IN
----------	---------	------------	----------	----------

NV350 URVAN

2017 -14	L4-2.5L	GCO-REA8MCX		0.044 IN
----------	---------	-------------	--	----------

PATHFINDER

2017 -13	V6-3.5L	GCO-REA8MCX		0.044 IN
2004-01	V6-3.5L	GCO-RC10YC4		0.044 IN
2000-97	V6-3.3L	GCO-RC12YC		0.045 IN

PICKUP

2010 -94	L4-2.4L	GCO-UXF79 ⁽³⁾		0.044 IN
----------	---------	--------------------------	--	----------

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

NISSAN (Continúa)**PICKUP (Continúa)**

1993 -91	L4-2.4L	GCO-N12YC		0.044 IN
----------	---------	-----------	--	----------

PLATINA

2010	L4-1.6L	GCO-UXF79 ⁽³⁾		0.044 IN
2009-02	L4-1.6L	GCO-RC12YC		0.045 IN

QUEST

2002	V6-3.3L	GCO-RC12YC		0.039 IN
2001-99	V6-3.3L		GPL-3071	0.039 IN
1998 -93	V6-3.0L	GCO-RC12YC		0.045 IN

ROGUE

2012 -08	L4-2.5L	GCO-REA8MCX		0.044 IN
----------	---------	-------------	--	----------

SAMURAI

1986	L4-1.6L	GCO-N12YC		0.035 IN
------	---------	-----------	--	----------

SENTRA

2017 -13	L4-1.8L	GCO-REA8MCX		0.044 IN
2012 -10	L4-2.0L	GCO-UXF79 ⁽³⁾ , GCO-REA8MCX		0.044 IN
2009-07	L4-2.0L	GCO-REA8MCX	GPL-3071	0.044 IN
2009-07	L4-2.0L	GCO-UXF79 ⁽³⁾ , GCO-REA8MCX	GPL-3071	0.044 IN
2009-02	L4-2.5L	GCO-REC10YC4		0.05 IN
2006-00	L4-1.8L	GCO-REC10YC4		0.05 IN
2001-96	L4-2.0L		GPL-3071	0.044 IN
2000-93	L4-1.6L		GPL-3071	0.044 IN
1994 -93	L4-2.0L		GPL-3071	0.044 IN

TIIDA

2017 -07	L4-1.8L	GCO-REA8MCX		0.044 IN
----------	---------	-------------	--	----------

TITAN

2009-04	V8-5.6L		GPL-7437	0.05 IN
---------	---------	--	----------	---------

TSUBAME

2004-93	L4-1.6L	GCO-UXF79 ⁽³⁾		
---------	---------	--------------------------	--	--

TSURU

2015 -97	L4-1.6L	GCO-UXF79 ⁽³⁾		0.044 IN
1997	L4-1.6L	GCO-RC12YC, GCO-UXF79 ⁽³⁾		0.044 IN
1996 -95	L4-2.0L	GCO-UXF79 ⁽³⁾		0.044 IN
1996	L4-1.6L		GPL-3071	0.044 IN

(3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER		COBRE	PLATINO	CLBR
AÑO	MOTOR			
NISSAN (Continúa)				
TSURU (Continúa)				
1995	L4-1.6L	GCO-UXF79 ⁽³⁾		0.044 IN
1994-93	L4-2.0L		GPL-3071	0.044 IN
1992-86	L4-1.6L	GCO-N12YC		0.035 IN
1985-84	L4-1.5L	GCO-N12YC		0.044 IN
URVAN				
2012-08	L4-2.5L	GCO-REA8MCX		0.044 IN
2007-00	L4-2.4L		GPL-3071	0.044 IN
VERSA				
2017-16	L4-1.6L	GCO-REA8MCX		0.044 IN
2015-12	L4-1.6L	GCO-UXF79 ⁽³⁾ , GCO-REA8MCX		0.044 IN
XTERRA				
2004-00	V6-3.3L		GPL-3071	
X-TRAIL				
2017-08	L4-2.5L	GCO-REA8MCX		0.044 IN
OLDSMOBILE				
88				
1999-92	V6-3.8L	GCO-RES9YCC4		
CUTLASS				
1996	V6-3.1L		GPL-3013	
SILHOUETTE				
1995	V6-3.8L	GCO-RES9YCC4		0.06 IN
1994-93	V6-3.8L		GPL-3013	0.06 IN
PEUGEOT				
206				
2009-02	L4-1.4L	GCO-RC12YC		0.032 IN
2009-02	L4-1.6L		GPL-7437	0.06 IN
2001	L4-1.4L	GCO-UXF79 ⁽³⁾		
207				
2011-10	L4-1.4L	GCO-UXF79 ⁽³⁾		
2009-08	L4-1.6L Turbo		GPL-7437	0.06 IN
2009	L4-1.4L	GCO-RC12YC		0.032 IN
306				
2000-98	L4-1.8L		GPL-7437	0.06 IN
1997	L4-1.6L		GPL-7437	0.06 IN
405				
1999-98	L4-2.0L	GCO-RC12YC		0.032 IN

(3) 4 Electrodo

GONHER		COBRE	PLATINO	CLBR
AÑO	MOTOR			
PEUGEOT (Continúa)				
406				
2003-01	L4-2.0L		GPL-7437	0.06 IN
2002-01	V6-3.0L		GPL-7437	0.06 IN
407				
2009-07	L4-2.2L		GPL-7437	0.06 IN
607				
2003-02	V6-2.9L	GCO-REC10YC4		0.040 IN
GRAND RAID				
2009-07	L4-1.6L		GPL-7437	0.06 IN
PARTNER				
2009-04	L4-1.6L		GPL-7437	0.06 IN
PLYMOUTH				
BARRACUDA				
1969	V8-5.2L	GCO-N12YC		0.035 IN
BREEZE				
1996	L4-2.0L	GCO-RC9YC, GCO-UXF79 ⁽³⁾		0.035 IN
LASER				
1994-93	L4-1.8L	GCO-RN9YC		0.044 IN
1994-93	L4-2.0L	GCO-RN9YC		0.044 IN
1993	L4-2.0L Turbo	GCO-RN9YC		0.044 IN
VOYAGER				
1995-93	L4-2.5L	GCO-RN12YC		0.035 IN
PONTIAC				
AZTEK				
2005-01	V6-3.4L		GPL-3013	0.060 IN
BONNEVILLE				
2005-93	V6-3.8L	GCO-RES9YCC4		0.06 IN
FIREBIRD				
2002-93	V8-5.7L	GCO-RES9YCC4		0.05 IN
G3				
2009-07	L4-1.6L	GCO-UXF79 ⁽³⁾		0.040 IN
G4				
2006-05	L4-2.2L		GPL-7437	
2006	L4-2.4L		GPL-7437	
G5				
2009-07	L4-2.2L		GPL-7437	
2008-07	L4-2.4L		GPL-7437	

BUJÍAS

NISSAN

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

PONTIAC (Continúa)**G6**

2009-07	V6-3.6L	GCO-RS9YCC		0.040 IN
2009-05	V6-3.5L	GCO-RS9YCC		0.060 IN

GRAND AM

2005	V6-3.4L		GPL-3013	0.06 IN
2004-02	V6-3.4L	GCO-RS9YCC		0.06 IN
2001-99	V6-3.4L		GPL-3013	0.06 IN

GRAND PRIX

2008-97	V6-3.8L	GCO-RS9YCC		0.06 IN
2003-93	V6-3.1L		GPL-3013	0.06 IN

MATIZ

2010	L4-1.0L	GCO-UX79 ⁽³⁾		
2009-04	L4-1.0L	GCO-RN9YC		0.035 IN

MONTANA

2009-06	V6-3.9L	GCO-RS9YCC		0.06 IN
2006-05	V6-3.5L	GCO-RS9YCC		0.06 IN

SOLSTICE

2009-06	L4-2.4L		GPL-7437	0.04 IN
---------	---------	--	----------	---------

SUNFIRE

2005-95	L4-2.2L		GPL-7437	0.06 IN
2002	L4-2.4L		GPL-7437	0.06 IN
2001-99	L4-2.4L		GPL-3013	0.06 IN
1998-96	L4-2.4L		GPL-7437	0.06 IN

TORRENT

2009-06	V6-3.4L	GCO-RS9YCC		0.06 IN
---------	---------	------------	--	---------

TRANS SPORT

1995-93	V6-3.8L		GPL-3013	0.060 IN
---------	---------	--	----------	----------

PORSCHE**911**

2007-05	H6-3.6L	GCO-UXF79 ⁽³⁾		
2007	H6-3.6L Turbo	GCO-UXF79 ⁽³⁾		
2005	H6-3.6L Turbo	GCO-UXF79 ⁽³⁾		

BOXSTER

2007-05	H6-2.7L	GCO-UXF79 ⁽³⁾		
---------	---------	--------------------------	--	--

CAYMAN

2007	H6-2.7L	GCO-UXF79 ⁽³⁾		
2007	H6-3.4L	GCO-UXF79 ⁽³⁾		

PANAMERA

2015-14	V6-3.0L Híbrido	GCO-UXF79 ⁽³⁾		0.032 IN
2015-14	V6-3.0L Turbo	GCO-UXF79 ⁽³⁾		0.032 IN

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

RAM**1500**

2013-11	V6-3.7L		GPL-3318 ⁽¹⁾	0.044 IN
---------	---------	--	-------------------------	----------

700

2018-15	L4-1.6L	GCO-RC9YC		0.036 IN
---------	---------	-----------	--	----------

RENAULT**ALLIANCE**

1986-85	L4-1.7L	GCO-UX79 ⁽³⁾		
1984	L4-1.7L	GCO-N12YC		0.025 IN

CLIO

2009-02	L4-1.6L	GCO-RC12YC		0.045 IN
2006-02	L4-2.0L	GCO-UXF79 ⁽³⁾		

ENCORE

1986-85	L4-1.7L	GCO-UX79 ⁽³⁾		
---------	---------	-------------------------	--	--

EURO CLIO

2008-07	L4-1.6L	GCO-RC12YC		0.045 IN
---------	---------	------------	--	----------

KANGOO

2009-07	L4-1.6L	GCO-RC12YC		0.045 IN
---------	---------	------------	--	----------

KANGOO EXPRESS

2009-04	L4-1.6L	GCO-RC12YC		
---------	---------	------------	--	--

LAGUNA

2006	L4-2.0L Turbo	GCO-UXF79 ⁽³⁾		
2004-03	V6-2.9L	GCO-UXF79 ⁽³⁾		

MEGANE

2010	L4-1.6L	GCO-UXF79 ⁽³⁾		
2009-07	L4-2.0L Turbo	GCO-UXF79 ⁽³⁾		
2009-01	L4-2.0L	GCO-UXF79 ⁽³⁾		
2009	L4-1.6L	GCO-RC12YC		0.045 IN
2008	L4-1.6L	GCO-UXF79 ⁽³⁾		
2005	L4-2.0L Turbo	GCO-UXF79 ⁽³⁾		

R12

1978-75	L4-1.6L	GCO-N12YC		
---------	---------	-----------	--	--

R18

1986-85	L4-2.0L	GCO-RES9YCC4		
1984-80	L4-1.6L	GCO-N12YC		

SANDERO

2011-10	L4-1.6L	GCO-UXF79 ⁽³⁾		
---------	---------	--------------------------	--	--

SCALA

2012-11	L4-1.6L	GCO-UXF79 ⁽³⁾		
---------	---------	--------------------------	--	--

(1) Producto nuevo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER		COBRE	PLATINO	CLBR
AÑO	MOTOR			

RENAULT (Continúa)

SCENIC

2004-01	L4-2.0L	GCO-UXF79 ⁽³⁾		
---------	---------	--------------------------	--	--

SCENIC II

2008-05	L4-2.0L	GCO-UXF79 ⁽³⁾		
---------	---------	--------------------------	--	--

STEPWAY

2011	L4-1.6L	GCO-UXF79 ⁽³⁾		
------	---------	--------------------------	--	--

SEAT

ALHAMBRA

2007-04	L4-1.8L Turbo	GCO-RC8VTYC4 ⁽²⁾		0.035 IN
---------	---------------	-----------------------------	--	----------

CORDOBA

2009-04	L4-1.6L	GCO-UXF79 ⁽³⁾		0.035 IN
2009-04	L4-2.0L	GCO-UXF79 ⁽³⁾		0.040 IN
2003	L4-2.0L	GCO-RC8VTYC4 ⁽²⁾		0.040 IN
2002-01	L4-1.6L	GCO-UXF79 ⁽³⁾		0.035 IN

IBIZA

2013-09	L4-2.0L	GCO-RC8VTYC4 ⁽²⁾		0.040 IN
2012-04	L4-1.6L	GCO-UXF79 ⁽³⁾		0.040 IN
2008-03	L4-2.0L	GCO-UXF79 ⁽³⁾		0.040 IN
2008	L4-1.8L Turbo	GCO-UXF79 ⁽³⁾		0.040 IN
2002-01	L4-1.6L	GCO-UXF79 ⁽³⁾		0.040 IN

LEON

2009-08	L4-2.0L Turbo	GCO-RC12MC4		0.04 IN
2009	L4-1.8L Turbo	GCO-RC8VTYC4 ⁽²⁾		0.035 IN
2008	L4-2.0L	GCO-RC12MC4		0.04 IN
2006-01	L4-1.8L Turbo	GCO-UXF79 ⁽³⁾		0.035 IN
2005-01	L4-1.8L	GCO-UXF79 ⁽³⁾		0.035 IN

NUEVO IBIZA

2010	L4-1.6L	GCO-UXF79 ⁽³⁾		
2010	L4-2.0L	GCO-RC8VTYC4 ⁽²⁾		

TOLEDO

2005-01	L4-1.8L	GCO-RC8VTYC4 ⁽²⁾		0.040 IN
2004-01	L4-1.8L Turbo	GCO-RC8VTYC4 ⁽²⁾		0.040 IN

GONHER		COBRE	PLATINO	CLBR
AÑO	MOTOR			

SUBARU

LEGACY

2007-06	H4-2.5L	GCO-RC10YC4		0.044 IN
2007-06	H4-2.5L Turbo	GCO-RC10YC4		0.044 IN

OUTBACK

2009	H4-2.5L	GCO-RC10YC4		0.044 IN
2008-06	H4-2.5L Turbo	GCO-RC10YC4		0.044 IN

SUZUKI

AERIO

2007-06	L4-2.3L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4		0.044 IN
---------	---------	--	--	----------

GRAND VITARA

2008	V6-2.7L	GCO-RC10YC4		0.044 IN
2007-06	V6-2.7L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4		0.044 IN

SWIFT

2011-08	L4-1.5L	GCO-RC8YC4 ⁽¹⁾		0.044 IN
2007	L4-1.5L	GCO-RC8YC4 ⁽¹⁾ , GCO-UXF79 ⁽³⁾		0.044 IN

SX4

2011-08	L4-2.0L	GCO-UXF79 ⁽³⁾		
---------	---------	--------------------------	--	--

TOYOTA

4RUNNER

2008	V8-4.7L	GCO-RC10YC4		0.044 IN
2007-04	V8-4.7L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4		0.044 IN
2007	V6-4.0L		GPL-3071	0.045 IN
2003	V8-4.7L	GCO-RC10YC4		0.044 IN

AVANZA

2015-07	L4-1.5L	GCO-RA6HC ⁽¹⁾		0.036 IN
---------	---------	--------------------------	--	----------

CAMRY

2009-07	V6-3.5L	GCO-UXF79 ⁽³⁾		0.044 IN
2009-03	L4-2.4L	GCO-UXF79 ⁽³⁾		0.044 IN
2006-05	V6-3.0L	GCO-UXF79 ⁽³⁾		0.044 IN

COROLLA

2017-10	L4-1.8L	GCO-REA8MCX		0.044 IN
---------	---------	-------------	--	----------

BUJÍAS

RENAULT

(1) Producto nuevo, (2) 3 Electrodo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

TOYOTA (Continúa)**COROLLA (Continúa)**

2009	L4-1.8L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4, GCO-REA8MCX		0.044 IN
2009	L4-2.4L	GCO-UXF79 ⁽³⁾		0.044 IN
2008-07	L4-1.8L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4		0.044 IN
2006-93	L4-1.8L	GCO-UXF79 ⁽³⁾		0.044 IN

HIACE

2007-06	L4-2.7L	GCO-UXF79 ⁽³⁾		0.044 IN
---------	---------	--------------------------	--	-------------

HILUX

2007-04	L4-2.7L	GCO-UXF79 ⁽³⁾		0.044 IN
---------	---------	--------------------------	--	-------------

LAND CRUISER

2009-08	V8-5.7L	GCO-UXF79 ⁽³⁾		0.044 IN
2007	V8-4.7L	GCO-UXF79 ⁽³⁾		0.044 IN
2006-04	V8-4.7L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4		0.044 IN

MATRIX

2009-08	L4-1.8L	GCO-UXF79 ⁽³⁾		0.044 IN
2007-04	L4-1.8L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4		0.044 IN
2003	L4-1.8L	GCO-RC10YC4		0.044 IN

MR2 SPYDER

2006-05	L4-1.8L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4		0.044 IN
---------	---------	---	--	-------------

PRIUS C

2018	L4-1.5L Híbrido	GCO-RC12YC, GCO-UXF79 ⁽³⁾		0.043 IN
------	--------------------	---	--	-------------

RAV4

2008-04	L4-2.4L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4	GPL-3346 ⁽¹⁾	0.044 IN
---------	---------	---	-------------------------	-------------

SEQUOIA

2008	V8-4.7L	GCO-RC10YC4		0.044 IN
------	---------	-------------	--	-------------

SIENNA

2006-04	V6-3.3L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4, GCO-RC8YC4 ⁽¹⁾		0.044 IN
---------	---------	---	--	-------------

SOLARA

2006	V6-3.3L	GCO-RC10YC4		0.044 IN
------	---------	-------------	--	-------------

(1) Producto nuevo, (3) 4 Electrodo

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

TOYOTA (Continúa)**TACOMA**

2011 -10	V6-4.0L	GCO-UXF79 ⁽³⁾		0.044 IN
2009-07	V6-4.0L		GPL-3071	0.045 IN

TUNDRA

2009-08	V8-4.7L		GPL-3071	0.045 IN
2009-05	V6-4.0L		GPL-3071	0.045 IN
2007	V8-4.7L	GCO-RC10YC4	GPL-3071	0.044 IN, 0.045 IN
2006-00	V8-4.7L		GPL-3071	0.045 IN

YARIS

2011	L4-1.5L	GCO-RC12YC		0.044 IN
2010-06	L4-1.5L	GCO-UXF79 ⁽³⁾		0.044 IN
2005	L4-1.3L	GCO-UXF79 ⁽³⁾ , GCO-RC10YC4		0.044 IN
2004	L4-1.3L	GCO-RC10YC4		0.044 IN

VAM**GREMLIN**

1981 -76	L6-4.2L	GCO-N12YC		0.035 IN
1975 -74	L6-4.2L	GCO-UX79 ⁽³⁾		

JAVELIN

1973 -72	L6-4.6L	GCO-N12YC		0.035 IN
----------	---------	-----------	--	-------------

PACER

1979	L6-4.6L	GCO-N12YC		0.035 IN
1978 -76	L6-4.6L	GCO-UX79 ⁽³⁾		

VOLKSWAGEN**ATLANTIC**

1987 -85	L4-1.8L	GCO-UX79 ⁽³⁾		0.028 IN
1987	L4-1.7L	GCO-N12YC		0.028 IN
1986 -83	L4-1.7L	GCO-UX79 ⁽³⁾		0.028 IN
1984	L4-1.8L	GCO-N12YC		0.028 IN
1982	L4-1.7L	GCO-N12YC		0.027 IN
1981	L4-1.6L	GCO-UX79 ⁽³⁾		0.028 IN

GONHER		COBRE	PLATINO	CLBR
AÑO MOTOR				

VOLKSWAGEN (Continúa)

BEETLE

2011 -10	L4-2.0L	GCO-UXF79 ⁽³⁾		0.040 IN
2008	L4-2.0L	GCO-RC8VTC4 ⁽²⁾		0.040 IN
2007	L4-2.0L	GCO-UXF79 ⁽³⁾		0.040 IN
2005-98	L4-2.0L	GCO-UXF79 ⁽³⁾		0.040 IN

CABRIO

1999 -98	L4-2.0L	GCO-UXF79 ⁽³⁾		0.040 IN
----------	---------	--------------------------	--	----------

CARIBE

1987 -86	L4-1.8L	GCO-UX79 ⁽³⁾		0.028 IN
1987	L4-1.7L	GCO-N12YC		0.028 IN
1986 -81	L4-1.7L	GCO-UX79 ⁽³⁾		0.028 IN
1985 -84	L4-1.8L	GCO-N12YC		0.028 IN
1980 -77	L4-1.6L	GCO-UX79 ⁽³⁾		0.028 IN

CLASICO

2014 -11	L4-2.0L	GCO-RC8VTC4 ⁽²⁾		0.040 IN
----------	---------	----------------------------	--	----------

COMBI

2001 -88	L4-1.8L	GCO-UX79 ⁽³⁾		0.028 IN
----------	---------	-------------------------	--	----------

CORSAR

1988 -84	L4-1.8L	GCO-UX79 ⁽³⁾		0.028 IN
----------	---------	-------------------------	--	----------

CROSSFOX

2012 -11	L4-1.6L	GCO-UXF79 ⁽³⁾		0.040 IN
2009-07	L4-1.6L	GCO-RC8VTC4 ⁽²⁾		0.04 IN

DERBY

2009-08	L4-1.8L	GCO-N7BYC		0.032 IN
2007	L4-1.8L	GCO-UX79 ⁽³⁾		0.032 IN
2006-95	L4-1.8L	GCO-N7BYC		0.032 IN
2003-02	L4-2.0L	GCO-RC8VTC4 ⁽²⁾		0.032 IN

EUROVAN

2004-01	L5-2.5L	GCO-UXF79 ⁽³⁾		0.032 IN
2000	V6-2.8L	GCO-RC8VTC4 ⁽²⁾ , GCO-RC10YC4		0.044 IN

GONHER		COBRE	PLATINO	CLBR
AÑO MOTOR				

VOLKSWAGEN (Continúa)

GOL

2020-16	L4-1.6L	GCO-KC8ZMCC ⁽¹⁾		0.044 IN
2011 -09	L4-1.6L	GCO-RC8VTC4 ⁽²⁾		0.04 IN

GOL SEDAN

2011 -10	L4-1.6L	GCO-RC8VTC4 ⁽²⁾		0.044 IN
----------	---------	----------------------------	--	----------

GOLF

2007-06	L4-2.0L	GCO-RC8VTC4 ⁽²⁾		0.04 IN
2005-02	L4-1.8L Turbo		GPL-3071	0.032 IN
2005-95	L4-2.0L	GCO-UXF79 ⁽³⁾		0.032 IN
2001	L4-1.8L Turbo	GCO-RC10YC4	GPL-3071	0.044 IN, 0.032 IN
1999 -96	L4-1.8L	GCO-N7BYC, GCO-RC10YC4		0.032 IN, 0.044 IN
1999 -96	V6-2.8L	GCO-RC9BMC		0.04 IN
1995 -92	L4-1.8L	GCO-N7BYC		0.032 IN
1991 -88	L4-1.8L	GCO-UX79 ⁽³⁾		0.032 IN
1987	L4-1.8L	GCO-N12YC		0.028 IN

GTI

2009-07	L4-2.0L Turbo	GCO-RC12MC4		0.04 IN
---------	---------------	-------------	--	---------

JETTA

2018 -11	L4-2.0L	GCO-KC8ZMCC ⁽¹⁾		0.044 IN
2018 -08	L5-2.5L	GCO-KC8ZMCC ⁽¹⁾		0.044 IN
2012	L4-2.0L Turbo	GCO-RC8VTC4 ⁽²⁾		0.040 IN
2010	L4-2.0L	GCO-KC8ZMCC ⁽¹⁾ , GCO-RC8VTC4 ⁽²⁾		0.044 IN, 0.040 IN
2009-08	L4-2.0L	GCO-UXF79 ⁽³⁾ , GCO-RC9BMC		0.040 IN, 0.04 IN
2009-08	L4-2.0L Turbo	GCO-RC9BMC		0.04 IN
2008	L4-2.0L Turbo	GCO-UXF79 ⁽³⁾ , GCO-RC9BMC		0.040 IN, 0.04 IN
2007-00	L4-2.0L	GCO-UXF79 ⁽³⁾		0.040 IN
2007	L4-2.0L Turbo	GCO-UXF79 ⁽³⁾		0.040 IN
2005-04	L4-1.8L Turbo	GCO-RC8VTC4 ⁽²⁾		0.032 IN
2003	L4-1.8L Turbo	GCO-RC12YC		0.032 IN

BUJÍAS

VOLKSWAGEN

(1) Producto nuevo, (2) 3 Electrodo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER		COBRE	PLATINO	CLBR
AÑO	MOTOR			

VOLKSWAGEN (Continúa)**JETTA (Continúa)**

2002-01	V6-2.8L	GCO-RC12YC		0.04 IN
2002-00	L4-1.8L Turbo	GCO-RC8VTC4 ⁽²⁾		0.032 IN
2000-95	V6-2.8L	GCO-RC9BMC		0.04 IN
1999-98	L4-2.0L	GCO-RC8VTC4 ⁽²⁾		0.04 IN
1999-93	L4-1.8L	GCO-N7BYC		0.032 IN
1999	L4-1.8L Turbo	GCO-N7BYC		0.032 IN
1997-93	L4-2.0L	GCO-RC9BMC		0.04 IN
1992-87	L4-1.8L	GCO-UXF79 ⁽³⁾		0.032 IN

JETTA CITY

2009-08	L4-2.0L	GCO-UXF79 ⁽³⁾		0.040 IN
---------	---------	--------------------------	--	----------

LUPO

2009-07	L4-1.6L	GCO-RC8VTC4 ⁽²⁾		0.040 IN
2006-05	L4-1.6L	GCO-UXF79 ⁽³⁾		0.040 IN

PASSAT

2018-12	L5-2.5L	GCO-KC8ZMCC ⁽¹⁾		0.032 IN
2017-12	V6-3.6L		GPL-9407	0.044 IN
2005-99	V6-2.8L	GCO-RC8VTC4 ⁽²⁾		0.04 IN
2005	L4-1.8L Turbo	GCO-RC12MC4		0.04 IN
2004-00	L4-1.8L Turbo	GCO-RC8VTC4 ⁽²⁾ GCO-RC10YC4		0.028 IN, 0.044 IN
1999	L4-1.8L Turbo	GCO-RC12MC4		0.04 IN
1997-96	V6-2.8L	GCO-RC9BMC		0.04 IN
1993	L4-2.0L	GCO-RC8VTC4 ⁽²⁾		0.028 IN
1992-91	L4-2.0L	GCO-UXF79 ⁽³⁾		0.028 IN

POINTER

2009-08	L4-1.8L	GCO-RC8VTC4 ⁽²⁾		0.040 IN
2007-06	L4-1.8L	GCO-UXF79 ⁽³⁾		0.040 IN
2005-98	L4-1.8L	GCO-N7BYC		0.040 IN
2002-00	L4-2.0L	GCO-N7BYC		0.040 IN

POINTER TRUCK

2007-06	L4-1.8L	GCO-UXF79 ⁽³⁾		0.040 IN
2005-98	L4-1.8L	GCO-N7BYC		0.040 IN

GONHER		COBRE	PLATINO	CLBR
AÑO	MOTOR			

VOLKSWAGEN (Continúa)**POLO**

2007-03	L4-1.6L	GCO-RC8VTC4 ⁽²⁾		0.04 IN
2007	L4-2.0L	GCO-RC8VTC4 ⁽²⁾		0.04 IN
2006-03	L4-2.0L	GCO-UXF79 ⁽³⁾		0.033 IN

ROUTAN

2009	V6-3.8L	GCO-RE14MCC4		0.05 IN
------	---------	--------------	--	---------

SAVEIRO

2011	L4-1.6L	GCO-UXF79 ⁽³⁾		0.044 IN
------	---------	--------------------------	--	----------

SEDAN

2004-91	H4-1.6L	GCO-N12YC		0.025 IN
---------	---------	-----------	--	----------

SHARAN

2008-02	L4-1.8L Turbo	GCO-RC8VTC4 ⁽²⁾		0.032 IN
---------	---------------	----------------------------	--	----------

SPORTVAN

2010	L4-1.6L	GCO-UXF79 ⁽³⁾		0.040 IN
2009-07	L4-1.6L	GCO-RC8VTC4 ⁽²⁾		0.040 IN

TIGUAN

2009	L4-2.0L Turbo	GCO-RC12MC4		0.04 IN
------	---------------	-------------	--	---------

TOUAREG

2014-13	V6-3.0L Híbrido	GCO-UXF79 ⁽³⁾		0.028 IN
2009-08	V6-3.6L	GCO-RC12MC4		0.04 IN
2008-04	V8-4.2L		GPL-3071	0.045 IN

VAN

2008	L4-1.8L	GCO-UXF79 ⁽³⁾		0.032 IN
2007-03	L4-1.8L	GCO-RC8VTC4 ⁽²⁾		0.04 IN

VENTO

2020-14	L4-1.6L	GCO-KC8ZMCC ⁽¹⁾		0.044 IN
---------	---------	----------------------------	--	----------

VOLVO**C30**

2009-08	L5-2.5L Turbo		GPL-3071	
2009	L5-2.4L		GPL-3071	

C70

2005-02	L5-2.4L Turbo		GPL-3071	0.04 IN
---------	---------------	--	----------	---------

S40

2009-04	L5-2.5L Turbo		GPL-3071	
---------	---------------	--	----------	--

(1) Producto nuevo, (2) 3 Electrodo, (3) 4 Electrodo

Verifique la calibración de las bujías antes de instalarlas.

GONHER®		COBRE	PLATINO	CLBR
AÑO	MOTOR			

VOLVO (Continúa)

S60

2008-06	L5-2.4L Turbo		GPL-3071	0.04 IN
2005	L5-2.3L Turbo		GPL-3071	
2003-01	L5-2.4L Turbo		GPL-3071	0.04 IN

S80

2006-04	L6-2.9L Turbo		GPL-3071	
2003-00	L6-2.9L		GPL-3071	

V50

2007-06	L5-2.5L Turbo		GPL-3071	
---------	------------------	--	----------	--

XC70

2007-04	L5-2.5L Turbo		GPL-3071	0.04 IN
---------	------------------	--	----------	---------

XC90

2007-04	L5-2.5L Turbo		GPL-3071	0.04 IN
2006-03	L6-2.9L Turbo		GPL-3071	0.04 IN

GONHER				
Marca Modelo	Cilindrada (cc)	Año	GONHER	Calibración

AHM

AH110	110	2004 >	GCO-Z9Y	0.028 in
ATTILA	125	2004-2006	GCO-Z9Y	0.028 in
CITY	125	2006-2008	GCO-Z9Y	0.028 in
COMET 125	125	2005-2006	GCO-Z9Y	0.028 in
COMET 150	150	2006-2009	GCO-Z9Y	0.028 in
FORTUNE	110	2004-2009	GCO-Z9Y	0.028 in
MAGIC	50	2005 >	GCO-Z9Y	0.028 in
MAGIC	90	2010-2012	GCO-Z9Y	0.028 in
PLAY BIKE	110	2006 >	GCO-Z9Y	0.028 in
R110	110	2008-2011	GCO-Z9Y	0.028 in
RIDER 250	250	2004-2010	GCO-Z9Y	0.028 in
SHARK	125	2005 >	GCO-Z9Y	0.028 in
SPIDER	50	2006 >	GCO-Z9Y	0.028 in
SPIDER	90	2006 >	GCO-Z9Y	0.028 in
SPIDER	110	2006 >	GCO-Z9Y	0.028 in
SPIDER	200	2007-2011	GCO-Z9Y	0.028 in
SPIDER 200FA	200	2009-2012	GCO-Z9Y	0.028 in

HONDA

AERO, GYRO, SPREE	50		GCO-Z9Y	0.024 in
AT	70		GCO-Z9Y	0.024 in
C	80		GCO-Z9Y	0.024 in
C (12MM)	90		GCO-Z9Y	0.024 in
CA	70		GCO-Z9Y	0.024 in
CA	250		GCO-Z9Y	0.024 in
CA 105 T	55		GCO-Z9Y	0.024 in
CD (10MM)	90		GCO-Z9Y	0.024 in
CD M	65		GCO-Z9Y	0.024 in
CE	75		GCO-Z9Y	0.024 in
CF	70		GCO-Z9Y	0.024 in
CF CHALY	50		GCO-Z9Y	0.024 in
CF II	70		GCO-Z9Y	0.024 in
CF III	50		GCO-Z9Y	0.024 in
CH	80		GCO-Z9Y	0.024 in
CJ	125		GCO-Z9Y	0.024 in
CL	50		GCO-Z9Y	0.024 in
CL	70		GCO-Z9Y	0.024 in
CM	125		GCO-Z9Y	0.024 in
CMX250C	250	1996-2005	GCO-Z9Y	0.028 in
REBEL				
CR III	70		GCO-Z9Y	0.024 in
CR L, LA	50		GCO-Z9Y	0.024 in
CS	50		GCO-Z9Y	0.024 in
CS	70		GCO-Z9Y	0.024 in
CT	50		GCO-Z9Y	0.024 in
CY	50	1980-1985	GCO-Z9Y	0.024 in
LS	70		GCO-Z9Y	0.024 in
MD	70		GCO-Z9Y	0.024 in
MD	90		GCO-Z9Y	0.024 in
MINI	70		GCO-Z9Y	0.024 in
P L	50		GCO-Z9Y	0.024 in
PF	50		GCO-Z9Y	0.024 in
PS	50		GCO-Z9Y	0.024 in
QA	50		GCO-Z9Y	0.024 in
S ROLLER	50		GCO-Z9Y	0.024 in
SL	70		GCO-Z9Y	0.024 in
SS M	50		GCO-Z9Y	0.024 in
ROLLER				

GONHER				
Marca Modelo	Cilindrada (cc)	Año	GONHER	Calibración

HONDA (Continuación)

SS V, ZK2	50		GCO-Z9Y	0.024 in
ROLLER				
T	250		GCO-Z9Y	0.024 in
TL	50		GCO-Z9Y	0.024 in
TRAIL	70		GCO-Z9Y	0.024 in
TRAIL	70		GCO-Z9Y	0.024 in
XE	50		GCO-Z9Y	0.024 in
XE	75		GCO-Z9Y	0.024 in
XE II	50		GCO-Z9Y	0.024 in
XL	70		GCO-Z9Y	0.024 in
XL	75		GCO-Z9Y	0.024 in
XL (S M 10 MM)	100		GCO-Z9Y	0.024 in
XL K	75		GCO-Z9Y	0.024 in
XL S	80		GCO-Z9Y	0.024 in
XR K	75		GCO-Z9Y	0.024 in
YR	75		GCO-Z9Y	0.024 in

ISLO

ATC70	70	1973-1981	GCO-Z9Y	0.024 in
HERO 100	100	2002-2003	GCO-Z9Y	0.028 in
TRX90EX	90	2008 >	GCO-Z9Y	0.028 in

ITALIKA

ARGENTA (AT-110)	110	2005-2014	GCO-Z9Y	0.028 in
AT110	110	2011-2014	GCO-Z9Y	0.028 in
AT110	110	2011-2012	GCO-Z9Y	0.028 in
SPORT				
ATV150	150	2006-2011	GCO-Z9Y	0.028 in
ATV150	150	2013-2014	GCO-Z9Y	0.028 in
CON REVERSA				
ATV150	150	2011-2012	GCO-Z9Y	0.028 in
SPORT				
CITY	125	2007-2009	GCO-Z9Y	0.028 in
CS-125				
CS125	125	2010-2014	GCO-Z9Y	0.028 in
DIABOLO-125	125	2007-2009	GCO-Z9Y	0.028 in
DIABOLO-150	150	2007-2009	GCO-Z9Y	0.028 in
DS125	125	2005-2009	GCO-Z9Y	0.028 in
DS150	150	2013-2014	GCO-Z9Y	0.028 in
FT110	110	2010-2014	GCO-Z9Y	0.028 in
GS150	150	2013-2014	GCO-Z9Y	0.028 in
LEDS				
GTS175	175	2010-2014	GCO-Z9Y	0.028 in
JUMBO	110	2007 >	GCO-Z9Y	0.024 in
PS90	90	2010-2014	GCO-Z9Y	0.028 in
ST170	170	2005-2008	GCO-Z9Y	0.028 in
STRADA (ST-70)	70	2007-2009	GCO-Z9Y	0.028 in
STRADA (ST-90)	90	2009-2014	GCO-Z9Y	0.028 in
TS-170	170	2009 >	GCO-Z9Y	0.028 in
VENDETTA	90	2007-2009	GCO-Z9Y	0.028 in
VS-90				
VS90	90	2006-2008	GCO-Z9Y	0.028 in
WS-150	150	2008-2009	GCO-Z9Y	0.028 in
WS175	175	2012-2014	GCO-Z9Y	0.028 in
XS125	125	2010-2014	GCO-Z9Y	0.028 in
XS150	150	2010-2012	GCO-Z9Y	0.028 in

GONHER®				
Marca Modelo	Cilindrada (cc)	Año	GONHER	Calibración

KAWASAKI

4S-100	100	1993-1995	GCO-Z9Y	0.028 in
AN	80		GCO-Z9Y	0.028 in
AN090 (NEOMAX)	100	1995 >	GCO-Z9Y	0.028 in
AN110 (KAZE-R)	110	2000-2002	GCO-Z9Y	0.028 in
AN90 (NEOMAX, MAX II)	90	1998-1999	GCO-Z9Y	0.028 in
AX1	90		GCO-Z9Y	0.024 in
KAZE	110	1995 >	GCO-Z9Y	0.024 in
KLT	110		GCO-Z9Y	0.024 in
KLT	160		GCO-Z9Y	0.024 in
KLX110	110	2008-2009	GCO-Z9Y	0.028 in
KZE	110	1995 >	GCO-Z9Y	0.024 in
MOJAVE	110		GCO-Z9Y	0.024 in
NINJA 250R	250	2008-2010	GCO-Z9Y	0.020 in

KYMCO

CALYPSO 125	125	1997 >	GCO-Z9Y	0.020 in
PEOPLE	125	1999 >	GCO-Z9Y	0.024 in

MOTO GUZZI

V35 IMOLA II	350	1979-1986	GCO-Z9Y	0.020 in
V50 MONZA II	500	1984-1987	GCO-Z9Y	0.024 in
V65 LARIO	650		GCO-Z9Y	0.024 in
V75 DUNA	750		GCO-Z9Y	0.024 in

SUZUKI

FD110	110	2005 >	GCO-Z9Y	0.032 in
FD110CK4	110	2004 >	GCO-Z9Y	0.032 in
FK110SD (SMASH)	110	2008 >	GCO-Z9Y	0.032 in

SYM

F1-125	125	2010 >	GCO-Z9Y	0.028 in
JET 125	125	2010 >	GCO-Z9Y	0.028 in
MOVING 125	125	2010 >	GCO-Z9Y	0.028 in
RS-21 125	125	2005 >	GCO-Z9Y	0.028 in

VENTO

COLT 250	250	2009 >	GCO-Z9Y	0.028 in
FIRENZE	125	2005 >	GCO-Z9Y	0.028 in
PHANTON	150	2005-2006	GCO-Z9Y	0.028 in
REBELLIAN 250	250	2008 >	GCO-Z9Y	0.028 in
V-THUNDER 300	300	2009 >	GCO-Z9Y	0.028 in

GONHER®				
Marca Modelo	Cilindrada (cc)	Año	GONHER	Calibración

YAMAHA

BELUGA XC125	125	1997 >	GCO-Z9Y	0.020 in
JOG 100	100	2009 >	GCO-Z9Y	0.028 in
T 105 (CRYPTON)	105	1999-2008	GCO-Z9Y	0.028 in
T 50	50		GCO-Z9Y	0.028 in
XC 125D	125	1986-1993	GCO-Z9Y	0.028 in
XV 250	250	2009 >	GCO-Z9Y	0.028 in
V-STAR				
XV VIRAGO	125	1997 >	GCO-Z9Y	0.024 in
V TWIN				
YFM 100	100		GCO-Z9Y	0.024 in
YFM 80	80	1985-2004	GCO-Z9Y	0.028 in
YFM 80R	80	2002 >	GCO-Z9Y	0.028 in
YFM E, F	80	1993 >	GCO-Z9Y	0.024 in

AC DELCO	GONHER	BERU	GONHER	DENSO	GONHER	NGK	GONHER
44XLS	GCO-N12YC	Z6 14K-8DU	GCO-BN12Y	KJ20CR-L11	GCO-RC9MC4	BPR5EFS	GCO-BN12Y
FR1LS	GCO-RC9YC	Z74 14FR-8LDUOX4	GCO-RC9BMC	MA16P-U	GCO-F11Y	BPR5ES-A	GCO-RN12YC
FR2LS	GCO-RC12YC	Z8 14R-8DU	GCO-RN12YC	PT16VR-13	GCO-RES9YCC4	BPR6E-11	GCO-RC10YC4
R42LTS	GCO-BN12Y	Z80 14K-9DU	GCO-BN14Y	Q16PR-U11	GCO-RC12YC	BPR6EFS	GCO-RS9YCC
R43TS	GCO-BL15Y	BOSCH	GONHER	Q20PR-U	GCO-RC9YC	BPR6ES	GCO-RN9YC
R43XLS	GCO-RN12YC	F7LTCR	GCO-RC8VTYC4	Q20PR-U11	GCO-RC10YC4	BPR6EY	GCO-RN9YC
S102F	GCO-Z9Y	FR7DC	GCO-RC9YC	T16EPR-U	GCO-BN12Y	BPR6EY	GCO-UX79
AUTOLITE	GONHER	FR7LCX	GCO-RC9MC4	T16NR-U11	GCO-RS14LC	C7HSA	GCO-Z9Y
106	GCO-BN14Y	FR8DCX	GCO-RC10YC4	T16P-U	GCO-BL15Y	DCPR7E	GCO-RA7YC
2544	GCO-RS14LC	FR8DCX	GCO-RC12YC	T20EPR-U	GCO-RS9YCC	LF5A-11	GCO-REC10YC4
2545	GCO-RS14LC	FR8LDC	GCO-RC10YC4	U22FSU	GCO-Z9Y	LZKAR7A	GCO-REA8MCX
2546	GCO-RS14LC	FR8MC9	GCO-REC10YC4	W16EPR-U	GCO-RN12YC	LZTR4A-11	GCO-RE14MCC4
26	GCO-BL15Y	FR9HC	GCO-RC12MC4	W16EP-U	GCO-N12YC	TR4	GCO-BN12Y
275	GCO-L92Y	HR7DCX	GCO-RS9YCC	W16EP-U	GCO-N14Y	TR5-1	GCO-RS14LC
3923	GCO-RC10YC4	HR8MEV	GCO-RES9YCC4	W20EPR-U	GCO-RN9YC	TR55	GCO-RS14LC
3923	GCO-RC9YC	UR3AS	GCO-Z9Y	XE20HR-U9	GCO-REA8MCX	TR5B-13	GCO-RES9YCC4
3924	GCO-RC12YC	VR8SE	GCO-REA8MCX	XU22EPR-U	GCO-RA7YC	WR4-1	GCO-F11Y
3924	GCO-RC9YC	WR8DP	GCO-N12YC	MOTOCRAFT	GONHER	ZFR5F	GCO-RC10YC4
4194	GCO-Z9Y	WR9DC	GCO-RN12YC	AF52C	GCO-BL15Y	ZFR5F11	GCO-RC9MC4
4253	GCO-RN9YC	YR7DC	GCO-RA7YC	AGRF22PP1	GCO-RES9YCC4	ZFR5F-11	GCO-RC12MC4
4263	GCO-RN9YC	YR7DE	GCO-RA7YC	AGSP52C	GCO-RC12YC	ZFR6K-11	GCO-RC12MC4
5224	GCO-RC12MC4	CHAMPION	GONHER	ASF22C	GCO-BL15Y		
5224	GCO-RC9MC4	BL15Y	GCO-BL15Y	ASF32C	GCO-BL15Y	PLATINO	
5263	GCO-RE14MCC4	BN12Y	GCO-BN12Y	ASF52C	GCO-BL15Y	AUTOLITE	GONHER
55	GCO-N12YC	BN14Y	GCO-BN14Y	BSF82C	GCO-F11Y	AP3923	GPL-3071
64	GCO-N7BYC	F11Y	GCO-F11Y	MAE42C	GCO-L92Y	AP3924	GPL-3071
65	GCO-RN12YC	L92Y	GCO-L92Y	MAG42C	GCO-N14Y	AP605	GPL-3013
66	GCO-RN12YC	N12YC	GCO-N12YC	MAG52C	GCO-N14Y	APP5344	GPL-7437
747	GCO-F11Y	N12YC	GCO-UX79	MAGS32C	GCO-N12YC	BERU	GONHER
765	GCO-BN12Y	N12YC	GCO-UX79	MAGS52C	GCO-BN14Y	Z 400	GPL-3071
APP5344	GCO-RES9YCC4	N14Y	GCO-N14Y	MAGS52C	GCO-RN12YC	Z 402	GPL-3013
BERU	GONHER	N7BYC	GCO-N7BYC	MAGS54C	GCO-BN14Y	Z97 14KR-6MPX	GPL-7437
12VR-8 SE	GCO-REA8MCX	RA7YC	GCO-RA7YC	MAGSF52C	GCO-BN12Y	BOSCH	GONHER
14F-8LUR	GCO-RC10YC4	RC10YC4	GCO-RC10YC4	MAGSP32C	GCO-RC9YC	FR8DPX	GPL-3071
14FR-6 DPUX02	GCO-RC10YC4	RC12MC4	GCO-RC12MC4	MBF82C	GCO-F11Y	HR8DPX	GPL-3013
14FR-7LUX	GCO-RC9MC4	RC12YC	GCO-RC12YC	NGK	GONHER	CHAMPION	GONHER
UX 79	GCO-UX79	RC12YC	GCO-UXF79	AP4FS	GCO-F11Y	3013	GPL-3013
UXF 79	GCO-UXF79	RC87YCL	GCO-UXF79	APR4FS	GCO-F11Y	3071	GPL-3071
UXK-79	GCO-RS9YCC	RC8VTYC4	GCO-RC8VTYC4	BKR5E-11	GCO-RC12YC	7437	GPL-7437
Z 1	GCO-N12YC	RC8VTYC4	GCO-UXF79	BKR5E-11	GCO-UXF79	9407	GPL-9407
Z 117	GCO-RS14LC	RC9BMC	GCO-RC9BMC	BKR5EKU	GCO-RC9BMC	DENSO	GONHER
Z 118	GCO-L92Y	RC9MC4	GCO-RC9MC4	BKR5EKU	GCO-RC9BMC	IT16	GPL-3013
Z 118	GCO-L92Y	RC9YC	GCO-RC9YC	BKR6E	GCO-RC9YC	MOTOCRAFT	GONHER
Z 15	GCO-RC9YC	RE14MCC4	GCO-RE14MCC4	BKR6ES	GCO-RC9YC	AZFS32FE	GPL-7437
Z 174	GCO-BL15Y	REA8MCX	GCO-REA8MCX	BKUR6ET-10	GCO-RC8VTYC4	MAWSF32P	GPL-3013
Z 199	GCO-Z9Y	REC10YC4	GCO-REC10YC4	BKUR6ET-10	GCO-UXF79	MAZFS22FE	GPL-7437
Z 2	GCO-N7BYC	RES9YCC4	GCO-RES9YCC4	BKUR6ET-11	GCO-RC8VTYC4	NGK	GONHER
Z 20	GCO-RN9YC	RN12YC	GCO-RN12YC	BP4EFS	GCO-BN14Y	BKR6EVX-11	GPL-3071
Z 209	GCO-RS9YCC	RN9YC	GCO-RN9YC	BP4ES	GCO-N14Y	ILZKR7B11	GPL-9407
Z 216	GCO-RE14MCC4	RN9YC	GCO-UX79	BP4ES	GCO-N14Y	PTR5A-13	GPL-7437
Z 73	GCO-RC12YC	RS14LC	GCO-RS14LC	BP4ES	GCO-N14Y	PTR5A-15	GPL-7437
Z 76	GCO-N14Y	RS9YCC	GCO-RS9YCC	BP5EFS	GCO-BN12Y		
Z 90	GCO-RC8VTYC4	Z9Y	GCO-Z9Y	BP5ES	GCO-N12YC		
Z175 18K-9BU	GCO-F11Y	DENSO	GONHER	BP5ES-A	GCO-N12YC		
Z177 14KR-8MUV	GCO-RES9YCC4	K16PR- U11	GCO-RC10YC4	BP5ES-A	GCO-UX79		
Z183 14FR-8MU2	GCO-REC10YC4	K20PBR-S10	GCO-RC8VTYC4	BP5HS	GCO-L92Y		
Z299 14FR-7LUX0	GCO-RC12MC4	KJ16CR-L11	GCO-RC12MC4	BP6ET	GCO-N7BYC		
Z358	GCO-RA7YC			BPR4EFS	GCO-BN14Y		

ESPECIFICACIONES DE BUJÍAS

BUJÍAS

EQUIVALENCIAS

GONHER	ROSCA	ASIENTO	RESISTENCIA	ALCANCE DE ROSCA	HEXÁGONO	TIPO	CANTIDAD DE ELECTRODOS	GAP
GCO-BL15Y	M14X1.25	CONICO	SI	11.2 mm	16 mm	COBRE	1	1.1 mm
GCO-BN12Y	M14X1.25	CONICO	NO	17.25 mm	16 mm	COBRE	1	1.1 mm
GCO-BN14Y	M14X1.25	CONICO	NO	17.25 mm	16 mm	COBRE	1	1.1 mm
GCO-F11Y	M18X1.5	CONICO	NO	13.6 mm	20.8 mm	COBRE	1	1.1 mm
GCO-L92Y	M14X1.25	PLANO	NO	12.7 mm	20.8 mm	COBRE	1	0.7 mm
GCO-N12YC	M14X1.25	PLANO	NO	19 mm	20.8 mm	COBRE	1	0.7 mm
GCO-N14Y	M14X1.25	PLANO	NO	19 mm	20.8 mm	COBRE	1	0.8 mm
GCO-N7BYC	M14X1.25	PLANO	NO	19 mm	20.8 mm	COBRE	3	1.0 mm
GCO-RC12MC4	M14X1.25	PLANO	NO	19 mm	16 mm	COBRE	1	1.0 mm
GCO-RC12YC	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	1	1.1 mm
GCO-RC8VTYC4	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	3	1.0 mm
GCO-RC9BMC	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	2	1.0 mm
GCO-RC9YC	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	1	0.9 mm
GCO-RE14MCC4	M14X1.25	CONICO	SI	25 mm	16 mm	COBRE	1	1.0 mm
GCO-REC10YC4	M14X1.25	PLANO	SI	26.5 mm	16 mm	COBRE	1	1.1 mm
GCO-RES9YCC4	M14X1.25	CONICO	SI	25 mm	16 mm	COBRE	1	1.1 mm
GCO-RN12YC	M14X1.25	PLANO	SI	19 mm	20.8 mm	COBRE	1	0.7 mm
GCO-RN9YC	M14X1.25	PLANO	SI	19 mm	20.8 mm	COBRE	1	0.8 mm
GCO-RS14LC	M14X1.25	CONICO	SI	17 mm	16 mm	COBRE	1	1.1 mm
GCO-RS9YCC	M14X1.25	CONICO	SI	17.5 mm	16 mm	COBRE	1	1.1 mm
GCO-UX79	M14X1.25	PLANO	SI	19 mm	20.8 mm	COBRE	4	1.1 mm
GCO-UXF79	M14X1.25	PLANO	SI	19 mm	16 mm	COBRE	4	1.1 mm
GCO-Z9Y	M10X1.0	PLANO	NO	12.7 mm	16 mm	COBRE	1	0.7 mm
GPL-3013	M14X1.25	CONICO	SI	17.25 mm	16 mm	PLATINO	1	1.1 mm
GPL-3071	M14X1.25	PLANO	SI	19 mm	16 mm	PLATINO	1	0.7 mm
GPL-7437	M14X1.25	CONICO	SI	25 mm	16 mm	PLATINO	1	1.3 mm

GARANTÍA

Para nosotros la satisfacción del cliente es el objetivo principal. Por ello, en todos nuestros productos ofrecemos garantías de fabricación. Cuando se utilicen las **Bujías GONHER, Gonhermex, S.A. de C.V.**, garantiza sus productos contra cualquier defecto de fabricación durante un período de 1 año para bujías de cobre y 2 años para bujías de platino a partir de su compra.

En el caso de daño al motor atribuible en forma directa a falla de una bujía **GONHER** que ha sido instalada en forma correcta, **Gonhermex, S.A. de C.V.**, pagará la reparación a una condición equivalente a la que exista antes de la falla. El daño deberá ser comprobado por un técnico autorizado por **Gonhermex, S.A. de C.V.**, antes de cualquier reparación.

Gonhermex, S.A. de C.V., no es responsable por cualquier otro daño o perjuicio ni cuando las bujías hayan sido utilizadas en condiciones distintas a las normales y no cubre pérdidas causadas por una instalación incorrecta, errores en la aplicación o modificaciones del producto.

Esta garantía podrá hacerse válida en **Gonhermex, S.A. de C.V.**, o cualquiera de los distribuidores autorizados.

GONHERMEX, S.A. DE C.V.
Av. Manuel Ordoñez No. 600 C.P. 66350
Santa Catarina, N.L., México
Tel: (81) 8153-31-00



GONHER[®]

AUTOPARTES



Descarga nuestra APP
Catálogo Gonher

gonher.com.mx



gonher



gonher



gonher
autopartes



gonher
autopartes